

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66258

Completed : 18 JAN 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10943 Description : 2022 TT COACHMEN CATALINA 303RKDSLE
Tag : Date In : 08 JAN 22 Mileage : 0
Author : BH Promised :
Location : 0120 CHECK PREAUTH Date Sched :
Serial# : 5ZT2CAVB3NX024693 Chassis# : 5ZT2CAVB3NX024693
Warr. Date : Cust PO# :
Print Date : 18 JAN 22

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: PDI - NEW TRAVEL TRAILER I PDI PRE-D
CAUSE: pdi
CORRECTION: checked brakes, tire pressure, lug
nuts, all lights, filled lp tanks, ran lp
leak test, installed battery box and
strap, checked all appliances, water and
plumbing system, electrical system,
filled and drained holding tanks,
winterized, documented model and serial
numbers,
1 COMPLAINT: STAIN ON CHAIRS W 10024 FORES
CAUSE: SILICONE AND DIRT ON CHAIRS.
CORRECTION: REMOVED STAINS WITH GLASS CLEANER AND
MINERAL SPIRITS
2 COMPLAINT: WATER HEATER DOOR HARD TO SHUT W 10024 FORES
CAUSE: FLANGE ON WATER HEATER WAS HITTING THE
DOOR
CORRECTION: BENT THE FLANGE DOWN TO CLEAR THE DOOR.
3 COMPLAINT: SCRATCHES ON FREEZER DOOR AND FRIDGE W 10024 FORES
DOOR
CAUSE: SCRATCHES ON DOORS
CORRECTION: TRIED TO BUFF OUT SCRATCHES THE BEST I
COULD WITH STAINLESS STEEL CLEANER
4 COMPLAINT: STAIN ON ENTRY DOOR FRAME W 10024 FORES
CAUSE: STAINS ON DOOR FRAME.
CORRECTION: REMOVED STAINS WITH A RAG AND MINERAL
SPIRITS
5 COMPLAINT: BEDROOM DOOR WONT LATCH W 10024 FORES
CAUSE: DOOR IS NOT LATCHING. NEED TO SAND DOWN
WOOD WHERE THE LATCH IS LOCATED TO MOVE
OVER.
CORRECTION: TOOK A SANDING WHEEL AND SANDED HOLE
INSIDE DOOR FRAME AND MOVED LATCH OVER
SO THE DOOR WOULD LATCH

Continued on page 2

Work Order : 66258

```
*****
Job # Part No Description          PARTS          Bill to  Qty    Price    Total
*****
PDINT 13034   55362 STD BATTERY BOX          I-PDI      1     10.95    10.95
PDINT 24181   -50 RV ANTI-FREEZE GALLON          I-PDI      2      4.99     9.98
*****
```

```
*****
Job#  Lab Code Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      0.00    150.00     0.00
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      2.70    150.00    405.00
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      0.47    150.00     70.50
DINTT Z991    MISC LABOUR CODE (INTE ZMS  I-PDI      2.83    150.00    424.50
  1 Z990    MISC LABOUR CODE (EXTE ZMS  W-10024    0.20    150.00     30.00
  2 Z990    MISC LABOUR CODE (EXTE ZMS  W-10024    0.00    150.00      0.00
  2 Z990    MISC LABOUR CODE (EXTE ZMS  W-10024    0.20    150.00     30.00
  3 Z990    MISC LABOUR CODE (EXTE ZMS  W-10024    0.20    150.00     30.00
  4 Z990    MISC LABOUR CODE (EXTE ZMS  W-10024    0.20    150.00     30.00
  5 Z990    MISC LABOUR CODE (EXTE ZMS  W-10024    0.20    150.00     30.00
*****
```

```
*****
Job #  Excode  Description          EXTRAS          bill to  Qty    Price    Total
*****
DINTT  SS      SHOP SUPPLIES          I-PDI      1.00    35.00    35.00
DINTT  LPGI     LP - UNIT SALES          I-PDI      8.00     3.99    31.92
*****
```

CUSTOMER COMMENTS

BH SENT IN PREAUTH

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
I    PDI          20.93    900.00    0.00     66.92    0.00    987.85
W    10024         0.00    150.00    0.00      0.00    0.00    150.00

Totals          20.93    1050.00    0.00     66.92    0.00    1,137.85
*****
```