

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12699B

Date In: 15 SEP 25 Author: MGRAY
Promised Date: 31 MAY 26 Stock No: 11455
: Year: 2026
Customer Name: 1000 - GREENEWAY RV SA Manufacturer: GRAND DESIGN
Address: 8220 STATE HWY 13 SOUT Brand: IMAGINE
: WISCONSIN RAPIDS, WI Model: 2300MK
Postal/Zip: 54494 Miles/Hrs: 0
Phone#(res): 800-758-2272 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: NONE Tag#: DB: 9/19 PART INQUIRY:
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573TE2725T6656044 :

```
*****  
Job # Description JOB INFORMATION Type Bill To  
*****  
WARR COMPLAINT: WARRANTY REPAIR 1 - DS front tires W 1020 GRAND  
grease cap fell off and the cover for  
center cap is missing  
CAUSE: 1019 MISSING PART Center cap  
CORRECTION: Put new one on  
WARR COMPLAINT: WARRANTY REPAIR 2 - trim above the SSlide W 1020 GRAND  
is loose  
CAUSE: Mfg improper install  
CORRECTION: Pushed trim up and used pin nailer to  
secure in proper position then puttied  
the hole REQUEST .30 HOURS OF LABOR  
WARR AUTH: .10  
WARR COMPLAINT: WARRANTY REPAIR 3 -the water pump needs W 1020 GRAND  
to be adjusted  
CAUSE: Mfg did not have water pump adjust high  
enough for it to keep constant water  
flow and pulsating and lights flickered  
as well as it was pulsating  
CORRECTION: Found water pump in front compartment  
and adjusted for more pressure now it  
operates without pulsating and no  
flickering lights REQUEST .30 HOURS OF  
LABOR WARR AUTH: .30 HOURS OF LABOR  
WARR COMPLAINT: WARRANTY REPAIR 4 -the roof has a couple W 1020 GRAND  
of sealant gaps they need to be sealed  
CAUSE: Gaps in the roof sealant  
CORRECTION: Used left over dicor to seal the gaps  
REQUEST .50 HOURS OF LABOR WARRANTY
```

Continued on page 2

Work Order : 12699B

```

*****
Job #   Description           JOB INFORMATION                               Type Bill To
*****
                                AUTH: .40 HRS
WARR    COMPLAINT:  WARRANTY REPAIR 5 - toilet cap is           W    1020  GRAND
                                missing
                                CAUSE:  Missing caps on toilet
                                CORRECTION:  PUT NEW TOILET SEAT ON
WARR    COMPLAINT:  WARRANTY REPAIR 6 -interior speaker       W    1020  GRAND
                                seems like it's blown
                                CAUSE:  The mfg left sawdust in the speaker
                                CORRECTION:  Removed speaker checked wire all good
                                then shook speaker and sawdust fell out
                                retested sounds normal then teinstalled
                                I to ceiling and tested and it sounds as
                                it should REQUEST .40 HOURS OF LABOR
WARR    COMPLAINT:  WARRANTY REPAIR 8 - the exterior water     W    1020  GRAND
                                heater door looks bent
                                CAUSE:  1016 DAMAGED Door was bent
                                CORRECTION:  Replace door on hot water heater
WARR    COMPLAINT:  WARRANTY REPAIR 9 - scratch in the front   W    1020  GRAND
                                door above the dark grey decal door
                                closest to front of unit
                                CAUSE:  Scratched from mfg
                                CORRECTION:  I AM NOTING SO IF FUTURE CUSTOMER
                                NOTICES THIS IT HAS BEEN DOCUMENTED
1       COMPLAINT:  WHILE SETTING UP FOR THE SHOW DAMAGED     I    SEP    POLIC
                                THE TONGUE JACK
                                CAUSE:  DAMAGE FROM SETTING UP FOR THE SHOW
                                CORRECTION:  REPLACED THE TONGUE JACK
2       Transferred to GRV*12699C on 26 JAN 26 Estimate           W    1020  GRAND
                                amount was 0.00 ADDED 1/26- THE FENDERSKIRT IS
                                CRACKED AND NEEDS TO BE REPLACED
3       Transferred to GRV*12699C on 26 JAN 26 Estimate           W    1020  GRAND
                                amount was 0.00 ADDED 1/26- THE DOOR HOLD BACK FOR
                                THE ENTRY DOOR IS BROKEN AND NEEDS TO BE REPLACED-

```

```

*****
Job # Part No      Description          PARTS    Bill to    Qty    Price    Total
*****
WARR0 822040413      TIRE COVER BLACK W/GRAND W-1020      4      2.90     11.60
WARR0 822050460      TOILET SEAT / COVER KIT W-1020      1     109.72    109.72
WARR0 82200108      DOOR WATER HEATER BLACK W-1020      1      41.99     41.99
1      848150002044    3500 POWER TOUNGE JACK B I-SEP      1     247.53    247.53

```

```

*****
Job# Lab Code  Description          LABOUR    Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992    MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00    70.00
ARR01 WARR    MANUFACTURER WARRANTY JL W-1020    0.50   140.00    70.00
ARR02 Z992    MISC LABOUR CODE (WARR HOD W-1020    0.20   140.00    28.00
ARR03 Z992    MISC LABOUR CODE (WARR HOD W-1020    0.30   140.00    42.00

```

Continued on page 3

Work Order : 12699B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.40   140.00   56.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR05 WARR      MANUFACTURER WARRANTY JL W-1020    0.50   140.00   70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.50   140.00   70.00
ARR08 WARR      MANUFACTURER WARRANTY JL W-1020    0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1020    0.00   140.00    0.00
      1 RV2-15a  TONGUE JACK INSTALL PO JT I-SEP    1.00    70.00   70.00
      2 WARR      MANUFACTURER WARRANTY JL W-1020    0.00   140.00    0.00
      3 WARR      MANUFACTURER WARRANTY JL W-1020    0.00   140.00    0.00
*****
```

```
*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL W-1020  1.00  0.00  0.00
ARR08 FRT      FREIGHT      W-1020  1.00  20.76 20.76
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts  Labour  Sublet  Extras  Tax  Total
*****
I   SEP           247.53  70.00   0.00   0.00   0.00  317.53
W   1020          163.31  616.00  0.00  20.76   0.00  800.07

      Totals      410.84  686.00  0.00  20.76   0.00  1,117.60
*****
```

&k2S
&k0S