



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$1,014.85

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
LACROSSE  
5ZT2LC9B8TG012140  
1 Mi In / 1 Mi Out  
Sold Date: 04/30/2026  
Stock #: FR26-24

**Service Advisor**  
KEVIN GOODIEL  
goodielk

A.	MISCELLANEOUS	DEALER STATES BACK SPLASH TO LEFT OF STIVE IS COMING OFF WALL	Warranty Pay	\$82.50
----	---------------	---	--------------	---------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Cut too long along top. .50hr requested.

Op:1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50

Labor Cost: \$15.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.37	0.5	0.5	\$82.50	\$15.50
boiem	-	0	0	0	\$0.00	\$0.00

1. Removed round trim from the top of the back splash and the bottom trim from the overhead cabinet to gain access to the entire top of the back splash section. Once trim and brad nails were removed, trimmed down the back splash and tested fit. Once fit was correct, applied new strip of adhesive tape to back. Refastened the trim pieces and resealed corner of back splash and counter top.

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$82.50	\$15.50	\$0.00	\$0.00

B.	MISCELLANEOUS	DEALER STATES FASCIA TRIM ON FRONT SIDE OF BED IS LOOSE	Warranty Pay	\$66.00
----	---------------	---	--------------	---------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Trim was cut too long. .40hr requested.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$1,014.85**

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
 Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
 Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
 linkautomotive - 2174  
 PD7155200709I  
 Customer  
 1235491  
 +1 - (715) 466 - 2222

**Billing-Customer**  
 Same as Customer

**Vehicle**  
 2026 FOREST RIVER  
 LACROSSE  
 5ZT2LC9B8TG012140

**Service Advisor**  
 KEVIN GOODIEL  
 goodielk

**Op.1 MISCELLANEOUS -MISCELLANEOUS**

**Labor Sale: \$66.00**  
**Labor Cost: \$15.20**

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.19	0.4	0.4	\$66.00	\$15.20
boiem	-	0	0	0	\$0.00	\$0.00

1. Removed trim piece and the upper corner plate, as the trim piece was fastened behind it with staples. Measured and cut down the trim piece to fir correctly. Fastened back in place and puttied holes. Reinstalled corner plate.

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$66.00	\$15.20	\$0.00	\$0.00

<b>C. MISCELLANEOUS</b>	<b>DEALER STATES GLUE STREAK NEXT TO SEAM TAPE ABOVE BEDROOM WINDOW</b>	<b>Warranty Pay</b>	<b>\$33.00</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Excess adhesive, possibly from lamination. .20hr requested.

**Op.1 MISCELLANEOUS -MISCELLANEOUS**

**Labor Sale: \$33.00**  
**Labor Cost: \$6.20**

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.11	0.2	0.2	\$33.00	\$6.20
boiem	-	0	0	0	\$0.00	\$0.00

1. Cleaned with adhesive remover.

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$33.00	\$6.20	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$1,014.85

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
Promise Time: Mon Mar 16, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER LACROSSE 5ZT2LC9B8TG012140	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

D. MISCELLANEOUS	DEALER STATES LEFT OF BEDROOM CLOSET, TRIM PIECE HAS A KNICK IN IT. HAS RED TAPE NEXT TO IT FROM MANUFACTURER	Warranty Pay	\$323.90
------------------	---	--------------	----------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Damage during install. .40hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50  
Labor Cost: \$19.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.58	0.5	0.5	\$82.50	\$19.00
boiem	-	0	0	0	\$0.00	\$0.00

- needs new
- Removed damaged piece and test fit the new piece. Stapled and then touched up staple holes with putty.

Parts

Parts Total Sale Amount \$22.28  
Parts Total Cost Amount \$17.14

Name	Quantity	Unit Price	Sale Price	Cost Price
F100578285 - MOLDING, CROWN 3/4"X1 3/4"X108" ANDOVER SABLE (UPPER)	1	\$22.28	\$22.28	\$17.14

Fees \$219.12

Code	Description	Sale Amount	Cost Amount
FF	Freight Fee	\$219.12	\$0.00

<b>Total Labor Sale</b> \$82.50	<b>Total Labor Cost</b> \$19.00	<b>Total Parts Sale</b> \$22.28	<b>Total Parts Cost</b> \$17.14
------------------------------------	------------------------------------	------------------------------------	------------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvidirect.com

Invoice  
\$1,014.85

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
Promise Time: Mon Mar 16, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER LACROSSE 5ZT2LC9B8TG012140	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

<b>E. MISCELLANEOUS</b>	<b>DEALER STATES FABRIC ON SECOND AWNING HAS SMALL TEAR ABOVE ENTRY DOOR</b>	<b>Warranty Pay</b>	<b>\$165.00</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Damage from install by manufacturer. 2.50hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$85.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	2.09	1.5	1.5	\$82.50	\$57.00
boiem	-	0.67	1.5	1.5	\$82.50	\$28.50

1. Awning assembly does not have manufacturer tags on it. Took additional pics of awning assembly for reference. Needs new awning fabric. Awning is 14ft long center of arm to center of arm.

2. Removed and replaced awning fabric with new. Adjusted as necessary and tested.

**Parts**

Parts Total Sale Amount \$0.00

Parts Total Cost Amount \$0.00

Name	Quantity	Unit Price	Sale Price	Cost Price
AWNING FAB - VELARIUM 14 FT FABRIC	1	\$0.00	\$0.00	\$0.00

Total Labor Sale  
\$165.00

Total Labor Cost  
\$85.50

Total Parts Sale  
\$0.00

Total Parts Cost  
\$0.00

<b>F. MISCELLANEOUS</b>	<b>DEALER STATES THERMOSTATES FOR MAIN BEDROOM A/C NOT TURNING ON</b>	<b>Warranty Pay</b>	<b>\$49.50</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Red wire going into thermostat was broken at the thermostat. .20hr requested.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$1,014.85**

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
 Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
 Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
 linkautomotive - 2174  
 PD7155200709I  
 Customer  
 1235491  
 +1 - (715) 466 - 2222

**Billing-Customer**  
 Same as Customer

**Vehicle**  
 2026 FOREST RIVER  
 LACROSSE  
 5ZT2LC9B8TG012140

**Service Advisor**  
 KEVIN GOODIEL  
 goodielk

**Op.1 MISCELLANEOUS -MISCELLANEOUS**

**Labor Sale: \$49.50**  
**Labor Cost: \$11.40**

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.13	0.3	0.3	\$49.50	\$11.40
boiem	-	0	0	0	\$0.00	\$0.00

1. After trying to turn on, removed from wall and saw the red wire was loose. Upon closer inspection, the terminal where it needed to go had a broken section of wire. Removed, stripped the wire, and installed into thermostat. Thermostat turned on and worked without issue.

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$49.50	\$11.40	\$0.00	\$0.00

<b>G. MISCELLANEOUS</b>	<b>DEALER STATES BUNK BATHROOM SHOWER DRIZZLES WATER OUT OF SHOWER HEAD. PRESSURE STILL POOR EVEN WITH HEAD REMOVED.</b>	<b>Warranty Pay</b>	<b>\$132.00</b>
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Debris in water system plugged faucet. .80hr requested.

**Op.1 MISCELLANEOUS -MISCELLANEOUS**

**Labor Sale: \$132.00**  
**Labor Cost: \$24.80**

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.54	0.8	0.8	\$132.00	\$24.80
boiem	-	0	0	0	\$0.00	\$0.00

1. Removed shower head to check for obstructions. Tested shower without head on. Water was coming out, but could tell the pump was rapidly pulsing. Pulled screws holding faucet plate on shower wall and removed shower faucet from water lines. Inspected the ports on the faucet for obstructions. Couldn't see anything, but blew air from lungs through faucet backwards to push any unseen debris out. Reconnected faucet to water lines and tested. Water was flowing





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$1,014.85

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
Promise Time: Mon Mar 16, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER LACROSSE 5ZT2LC9B8TG012140	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$132.00  
Labor Cost: \$24.80

properly. Put shower head on and water was still flowing properly. Removed faucet and put plate back on, reconnected faucet to lines again, and mounted to shower wall. Did another test, then sealed the plate with caulk.

<b>Total Labor Sale</b> \$132.00	<b>Total Labor Cost</b> \$24.80	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

H.	MISCELLANEOUS	DEALER STATES WATER PUMP PULSES EVERY 15 SECONDS.	Warranty Pay	\$0.00
----	---------------	---	--------------	--------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Debris in master bath faucet. Completed on Line J.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.29	0	0	\$0.00	\$0.00
boiem	-	0	0	0	\$0.00	\$0.00

1. Completed on Line J.

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

I.	MISCELLANEOUS	DEALER STATES ROOF NEEDS SEALANT IN SEVERAL SPOTS.	Warranty Pay	\$60.55
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Improper sealing from manufacturer. .30hr requested.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$1,014.85**

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
 Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
 Promise Time: Mon Mar 16, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER LACROSSE 5ZT2LC9B8TG012140	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50  
 Labor Cost: \$9.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.21	0.3	0.3	\$49.50	\$9.30
boiem	-	0	0	0	\$0.00	\$0.00

1. Resealed and reinspected. All ok.

Parts

Parts Total Sale Amount \$11.05  
 Parts Total Cost Amount \$8.50

Name	Quantity	Unit Price	Sale Price	Cost Price
08091088 - LAP SEALANT WHT	1	\$11.05	\$11.05	\$8.50

<b>Total Labor Sale</b> \$49.50	<b>Total Labor Cost</b> \$9.30	<b>Total Parts Sale</b> \$11.05	<b>Total Parts Cost</b> \$8.50
------------------------------------	-----------------------------------	------------------------------------	-----------------------------------

<b>J. MISCELLANEOUS</b>	<b>DEALER STATES MASTER BATHROOM FAUCET DRIPPING EVEN WITH BOTH HANDLES CLOSED COMPLETELY.</b>	<b>Warranty Pay</b>	<b>\$82.50</b>
-------------------------	--	---------------------	----------------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Debris trapped in faucet cold water valve. .50hr requested.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$1,014.85**

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
 Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
 Promise Time: Mon Mar 16, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD71552007091 Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER LACROSSE 5ZT2LC9B8TG012140	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$82.50  
 Labor Cost: \$15.50

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0	0.5	0.5	\$82.50	\$15.50
boiem	-	0	0	0	\$0.00	\$0.00

1. Removed faucet from unit and inspected the ports for hot and cold. In the cold side at the valve there was a piece of debris. Managed to work out of faucet with a pick. Reconnected to water lines and tested.

<b>Total Labor Sale</b> \$82.50	<b>Total Labor Cost</b> \$15.50	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>K. MISCELLANEOUS</b>	<b>DEALER STATES SEAM TAPE IS BUNCHED UP ABOVE FRIDGE ON MAIN WALL, BELOW WINDOW.</b>	<b>Warranty Pay</b>	<b>\$19.90</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Wed Mar 11, 2026 | 11:31 AM

1. Seam tape was pushed by the window ring. .30hr requested.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50  
 Labor Cost: \$3.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.24	0.1	0.1	\$16.50	\$3.80
boiem	-	0	0	0	\$0.00	\$0.00

1. needs new  
 2. Cleaned wall and applied new seam tape.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$1,014.85**

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
 Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
 Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
 linkautomotive - 2174  
 PD7155200709I  
 Customer  
 1235491  
 +1 - (715) 466 - 2222

**Billing-Customer**  
 Same as Customer

**Vehicle**  
 2026 FOREST RIVER  
 LACROSSE  
 5ZT2LC9B8TG012140

**Service Advisor**  
 KEVIN GOODIEL  
 goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$16.50  
 Labor Cost: \$3.80

Parts

Parts Total Sale Amount \$3.40  
 Parts Total Cost Amount \$2.60

Name	Quantity	Unit Price	Sale Price	Cost Price
F100578291 - SEAM TAPE 1" DOVE LILO	20	\$0.17	\$3.40	\$2.60

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$16.50	\$3.80	\$3.40	\$2.60

Category	Sale	Cost
Labor	\$759.00	\$206.20
Parts	\$36.73	\$28.24
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$219.12	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$1,014.85</b>	<b>\$234.44</b>





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$1,014.85

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
LACROSSE  
5ZT2LC9B8TG012140

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Mar 11, 2026	12:18 PM	12:37 PM	0.32 hrs	W	lafavet	0.5 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Wed Mar 11, 2026	12:37 PM	12:40 PM	0.05 hrs	W	lafavet	-
Tag: Regular Hour			Reason: -					
B	MISC	Wed Mar 11, 2026	12:40 PM	12:51 PM	0.19 hrs	W	lafavet	0.4 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Wed Mar 11, 2026	12:52 PM	12:58 PM	0.11 hrs	W	lafavet	0.2 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Wed Mar 11, 2026	1:00 PM	1:08 PM	0.13 hrs	W	lafavet	0.3 hrs
Tag: Regular Hour			Reason: -					
K	MISC	Wed Mar 11, 2026	1:09 PM	1:16 PM	0.13 hrs	W	lafavet	0.1 hrs
Tag: Regular Hour			Reason: -					
G	MISC	Wed Mar 11, 2026	2:07 PM	2:33 PM	0.43 hrs	W	lafavet	0.8 hrs
Tag: Regular Hour			Reason: -					
G	MISC	Wed Mar 11, 2026	2:33 PM	2:40 PM	0.11 hrs	W	lafavet	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$1,014.85

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
LACROSSE  
5ZT2LC9B8TG012140

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
H	MISC	Wed Mar 11, 2026	2:40 PM	2:50 PM	0.16 hrs	W	lafavet	0 hrs
Tag: Regular Hour			Reason: -					
H	MISC	Wed Mar 11, 2026	2:50 PM	2:58 PM	0.13 hrs	W	lafavet	-
Tag: Regular Hour			Reason: -					
I	MISC	Wed Mar 11, 2026	3:08 PM	3:20 PM	0.21 hrs	W	lafavet	0.3 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Tue Apr 7, 2026	12:56 PM	2:24 PM	1.46 hrs	W	lafavet	1.5 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Fri May 8, 2026	1:16 PM	1:56 PM	0.67 hrs	W	boiem	1.5 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Fri May 8, 2026	1:17 PM	1:55 PM	0.63 hrs	W	lafavet	-
Tag: Regular Hour			Reason: -					
D	MISC	Fri May 8, 2026	2:04 PM	2:39 PM	0.58 hrs	W	lafavet	0.5 hrs
Tag: Regular Hour			Reason: -					
K	MISC	Fri May 8, 2026	2:49 PM	2:56 PM	0.11 hrs	W	lafavet	-
Tag: Regular Hour			Reason: -					
J	MISC	-	-	-	0 hrs	W	lafavet	0.5 hrs
A	MISC	-	-	-	0 hrs	W	boiem	0 hrs
B	MISC	-	-	-	0 hrs	W	boiem	0 hrs





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
**\$1,014.85**

RO# : 40256 Tag# : TG012140

Check-in: Wed Mar 11, 2026 | 11:31 AM  
 Ready for Pickup: Wed May 13, 2026 | 6:59 AM  
 Promise Time: Mon Mar 16, 2026 | 6:00 PM

**Customer**  
 linkautomotive - 2174  
 PD7155200709I  
 Customer  
 1235491  
 +1 - (715) 466 - 2222

**Billing-Customer**  
 Same as Customer

**Vehicle**  
 2026 FOREST RIVER  
 LACROSSE  
 5ZT2LC9B8TG012140

**Service Advisor**  
 KEVIN GOODIEL  
 goodielk

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
C	MISC	-	-	-	0 hrs	W	boiem	0 hrs
D	MISC	-	-	-	0 hrs	W	boiem	0 hrs
F	MISC	-	-	-	0 hrs	W	boiem	0 hrs
G	MISC	-	-	-	0 hrs	W	boiem	0 hrs
H	MISC	-	-	-	0 hrs	W	boiem	0 hrs
I	MISC	-	-	-	0 hrs	W	boiem	0 hrs
J	MISC	-	-	-	0 hrs	W	boiem	0 hrs
K	MISC	-	-	-	0 hrs	W	boiem	0 hrs

