

WORK ORDER # 66264

```
Completed : 22 FEB 22      Customer : 49672 - RIVERSIDE RV - 260-499-4578
Licence # :                Invoice # :
Stock No : 11072          Description : 2022 TT RIVERSIDE RV RETRO 190BH
Tag :                    Date In : 08 JAN 22      Mileage : 0
Author : BH              Promised :
Location : 0225 CHECK PREAUTH Date Sched :
Serial# : 59CCC4611NL004686 Chassis# : 59CCC4611NL004686
Warr. Date :              Cust PO# :
Print Date : 22 FEB 22
```

Job #	Description	JOB INFORMATION	Type	Bill To	
BUNK	PRE DELIVERY INSPECTION NEW BUNKHOUSE		I	PDI	PRE-D
1	COMPLAINT: FRESH TANK FILL LINE IS BUNCHED UP AND IS COMING BACK UP BEFORE THE TANK CAN FILL		W	49672	RIVER
	CAUSE: fill line ran up over overflow line causing water to come out when filling				
	CORRECTION: removed fill line and ran under overflow line to help water flow downwards. secured fill line. tested for leaks.				
2	COMPLAINT: SCREEN DOOR LATCH NEEDS ADJ		W	49672	RIVER
	CAUSE: screen door was not latching to main door				
	CORRECTION: removed door latch. sanded down holes where latch was installed.moved latch over to the left so it would hold the screen door handle				
3	COMPLAINT: EXCESS SILICONE ON WINDOW & AROUND COMPARTMENT DOORS		W	49672	RIVER
	CAUSE: silicone on windows, walls and compartment door				
	CORRECTION: removed silicone with mineral spirits				
4	COMPLAINT: WIRES NEED SECURED IN OUTSIDE COMPARTMENT		W	49672	RIVER
	CAUSE: wires hanging down in storage compartment				
	CORRECTION: secured wires to stud with romex staples				
5	COMPLAINT: WATER HEATER IS NOT HEATING		W	49672	RIVER
	CAUSE: RAN WATER THROUGH LINES TO CLEAR OUT ANTIFREEZE.REMOVED PANEL TO ACCESS WATER HEATER. TURNED VALVES TO FLOW THROUGH WATER HEATER. PULLED POP OFF VALVE OPEN AND HAD WATER COMING OUT. TURNED WATER HEATER ON AND LET SIT FOR 1 HR. TURNED ON WATER PUMP AND NOTICED IT WAS TAKING				

Continued on page 2

Work Order : 66264

 Job # Description JOB INFORMATION Type Bill To

A LONG TO TO BUILD UP PRESSURE. NOT
 GETTING HOT WATER THROUGH ANY OF THE
 LINES IN THE UNIT. TRIED RUNNING ON CITY
 WATER AND STILL COULDN'T GET HOT WATER TO
 FLOW. AFTER COMING BACK TO LATER I
 NOTICED I STILL DIDN'T HAVE HOT WATER AND
 THE LIGHT WAS OUT AND THE UNIT WAS NOT
 WARM AT ALL. MANUAL FOR THE WATER HEATER
 STATES TO REMOVE COVER FOR ACCESS TO
 HIGH LIMIT SWITCH. SUPPORT BEAM FOR THE
 BED RUNS OVERTOP OF THE SCREW THAT HOLDS
 THIS COVER ON. TOOK A LARGE DRILL BIT
 AND DRILLED A ACCESS HOLE FOR THE
 SCREW. REMOVED SCREW AND COVER FOR WATER
 HEATER. DISCONNECTED POWER AND RESET
 HIGH LIMIT SWITCH. TURNED WATER HEATER
 ON AND THE LIGHT CAME ON. AFTER RUNING
 FOR A LITTLE THERE WAS A VERY STRONG
 BURNT SMELL AND STILL DIDN'T HAVE HOT
 WATER. SHUT OFF WATER HEATER AND
 WAITING TO TALK TO DENNY.1-12-22

 Job # Part No Description PARTS Bill to Qty Price Total

 BUNKH 13034 55362 STD BATTERY BOX I-PDI 0 13.99 0.00

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

 HOUSE Z990 MISC LABOUR CODE (EXTE I-PDI 0.00 130.00 0.00
 HOUSE Z990 MISC LABOUR CODE (EXTE ZMS I-PDI 0.77 130.00 100.10
 HOUSE Z990 MISC LABOUR CODE (EXTE ZMS I-PDI 2.77 130.00 360.10
 HOUSE Z990 MISC LABOUR CODE (EXTE ZMS I-PDI 0.46 130.00 59.80
 HOUSE Z990 MISC LABOUR CODE (EXTE ZMS I-PDI 0.00 130.00 0.00
 1 Z990 MISC LABOUR CODE (EXTE ZMS W-49672 0.20 150.00 30.00
 2 Z990 MISC LABOUR CODE (EXTE ZMS W-49672 0.20 150.00 30.00
 3 Z990 MISC LABOUR CODE (EXTE ZMS W-49672 0.30 150.00 45.00
 4 Z990 MISC LABOUR CODE (EXTE ZMS W-49672 0.20 150.00 30.00
 5 Z990 MISC LABOUR CODE (EXTE W-49672 0.00 150.00 0.00
 5 Z990 MISC LABOUR CODE (EXTE ZMS W-49672 0.00 150.00 0.00
 5 Z990 MISC LABOUR CODE (EXTE ZMS W-49672 0.00 150.00 0.00

 Job # Excode Description EXTRAS bill to Qty Price Total

 HOUSE LPG LP GAS I-PDI 8.00 3.99 31.92
 HOUSE SS SHOP SUPPLIES I-PDI 0.00 0.00 0.00

Continued on page 3

Work Order : 66264

CUSTOMER COMMENTS

BH SENT IN PREAUTH 2-21

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	520.00	0.00	31.92	0.00	551.92
W	49672	0.00	135.00	0.00	0.00	0.00	135.00
	Totals	0.00	655.00	0.00	31.92	0.00	686.92