



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73412  
 Promised Date:  
 \*73412\*

WO #: 73412  
 Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date:  
 Invoice#:  
 Author: BRIAN  
 Stock Desc: 9709 2027 CRUSADER  
 FAM37  
 Serial#: 128657  
 Chassis#: 5ZT3CS2B6VG128657  
 Miles/Hrs:  
 Tag#:  
 Purchased Date:  
 Warranty Date:

Date In: 03 JUN 26  
 Time In:

**Job #5W-PRE PDI - Internal**

COMPLAINT: Transferred to RV\*73412-1 on 15 JUN 26  
 Estimate amount was 0.00  
 5TH WHEEL PRE PDI 4.0 HRS

CAUSE: Free PDI fifth wheel new unit

CORRECTION: Pre-PDI complete  
 18 jobs added  
 Notes for the jobs  
 Master bedroom, barn door, master bathroom, barn door boat 24 x 74  
 Wraparound style door jam overall with 2 3/8 x 79  
 Cabinet door 17 x 26 right hand handle left hand hinge  
 Cabinet base next to the refrigerator 14 1/2 x 78 1/2 two openings for two cabinet doors  
 Slight fascia 5 1/2 x 79 1/2.  
 Linoleum size 47 x 105  
 Bottom board 63 wide by 40 feet

**Labor**

Job #	Description	Total
5W-PRE PDI	Pre pdi 5th wheel	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #5W-PRE PDI: 0.00**

**Job #1 - Warranty**

COMPLAINT: UNDERBELLY COMPLETELY MISSING

CAUSE: Torn off during transport

CORRECTION: Will need the full length of the trailer for a new bottom board will have to go along and remove all self tapping screws from front to back. We have to remove what bottom board is still attached to any of the sewer drops for great tanks and black tanks. Well have to pull all the foam away from all the sewer drops and freshwater drop drains. Will have to go along all electric lines resecure electric lines up some waterlines that are sagging will have to be resecured. This will be done using zip ties to secure the lines back up in place not interfering with the installation of the new bottom board.  
 New bottom board will have to be installed reattached with self tapping screws with washers, cut outs for all

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,

\*1000\*

the drains freshwater drain and low point drains once a bottom board has been completely reinstalled. Any cut out in the bottom board for dreams. Any electric will have to be sealed with foam.

Requesting 16 hours to complete this job

<b>Labor</b>		
Job #	Description	Total
1	Bottom board torn away during delivery	N/C
<b>Subtotal for Job #1:</b>		<b>0.00</b>

**Job #2 - Warranty**

COMPLAINT: GRAY TANK HANDLES MISSING

CAUSE: Completely missing

CORRECTION: Need to replace both front and rear gray tank handles. Found them to be completely missing. One will need an extension rod with the handle the other, just the bull handle.  
 Request .15 hours labor

<b>Labor</b>		
Job #	Description	Total
2	Two grey tank handles missing	N/C
<b>Subtotal for Job #2:</b>		<b>0.00</b>

**Job #3 - Warranty**

COMPLAINT: BELT RAIL COMING IT OFF.

CAUSE: Staples came loose not enough screws

CORRECTION: We have to scrape clean and remove all silicone on the belt rail for the main slide on the passenger side. The slide will be the one that contains a refrigerator and dinette.  
 Well have to measure and put the screws through the belt rail to reattach to the side of the unit and equal increments from the slide room to the rear of the unit.  
 Will request one hour labor time

<b>Labor</b>		
Job #	Description	Total
3	Belt rail coming off passenger side large slide room	N/C
<b>Subtotal for Job #3:</b>		<b>0.00</b>

**Job #4 - Warranty**

COMPLAINT: INNER SEAL FALLING OFF

CAUSE: Inner seal falling out not long enough or secured properly

CORRECTION: Will need to remove the inner seal for the compartment door and replace inner seal with a seal that is longer in order for it to stay up in the corners. Second recommendation would be to completely replace the compartment door.  
 Will request 30 minutes labor time

<b>Labor</b>		
Job #	Description	Total
4	Compartment door coming apart	N/C
<b>Subtotal for Job #4:</b>		<b>0.00</b>

**Job #5 - Warranty**

COMPLAINT: spring hanger bent

CAUSE: Unknown cause some object struck the axle and bent the spring hanger during transport

CORRECTION: Recommendation remove front axle completely and replace with a new axle. Full inspection of the spring hanger check it for square straightness any stress fractures cracks in the steel.

Potentially have to replace the spring hanger completely if it has any sort of damage besides being bent. Its a spring hanger can be straightened without causing further damage recommend straightening. Removal of the axle will require disconnecting it from the spring hanger and the rocker to the second axle, disconnecting the powerlines for the electric brakes pulling the axle out from underneath the unit, and of course, removing the tires hanging a new axle reconnecting the wires for the electric brakes voting it back into place and reinstalling the tires.

Will request three hours to remove and replace and inspect the spring hanger

**Labor**

Job #	Description	Total
5	Damaged axle and bent spring hanger	N/C

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: WALL SEPARATION IN MASTER BEDROOM

CAUSE: Interior wall separation from exterior wall

CORRECTION: Recommendation full inspection to be conducted to ensure that there are no structural issues with the wall separation. This will require the removal of the panel. This will be at the entry door to the master bedroom on the passenger side will involve removing of all trim door jam for the barn door. The built-in cabinet at that wall, the top will have to be removed the cabinet disconnected from the exterior wall in order to get the panel completely off to remove the full sheet of paneling, it will be a light switch that will have to be removed for inspection of the joist between the exterior wall and the interior wall, possibly reattaching using screws. Reassembly of the built-in cabinet after installing the panel back in place putting the door jam back in place reinstalling the barn door reinstalling the light switch and putting back all trim putting any new and old staple holes.

Will request six hours labor

**Labor**

Job #	Description	Total
6	Wall separating	N/C

**Subtotal for Job #6: 0.00**

**Job #7 - Warranty**

COMPLAINT: WALL SEPERATION ON OTHER SIDE OF THE BEDROOM.

CAUSE: Wall separation unknown structural damage

CORRECTION: This will require the removal of all trim, electrical outlets, door, jam, removal of the panel, full inspection of the wall for the cause of the separation repairing replace any broken studs, possibly screwing the studs back to the wall if there is no broken material. Reinstalling the sheet of paneling, all trim door, jam, and electrical outlets.

Will request three hours labor time

**Labor**

Job #	Description	Total
7	Wall separating master bedroom to the rear of the slide room	N/C

**Subtotal for Job #7: 0.00**

**Job #8 - Warranty**

COMPLAINT: BEDROOM DOOR RIPPED OFF.

CAUSE: Roller on one side of the door ripped off completely tore off bottom door guide from the wall

CORRECTION: Recommendation fully replace the door door size 24 x 74 barn door style. Recommendation replace the paneling behind the door, bottom door guide damage the paneling tearing large holes where it was attached. Those were require removal of all trim, barn door top guide removing the panel installing a new panel reinstalling all trim door, jam, and barn door. Also require new door in attaching all hardware to the new door, including travel latches rollers, reattaching the bottom door guide to the wall. Putting any new and old, staple holes or nail holes.

Will request three hours labor for the whole job

<b>Labor</b>		
Job #	Description	Total
8	Damaged barn door to master bathroom	N/C
<b>Subtotal for Job #8:</b>		<b>0.00</b>

**Job #9 - Warranty**

COMPLAINT: FURNITURE LOOSE.

CAUSE: Loose furniture, rubbing against the wall on the rear and exterior wall due to not having straps installed.

CORRECTION: Recommendation completely replacing both panels on the end and on the long ways exterior wall require removal of two window, windows, window, blinds, window, trim, bat strips, any and all trim, cutting away silicone that seals edges against the ceiling, cleaning and removing all excessive silicone cutting new paneling to fit disconnecting and removing all electrical components from the walls light switches this board and 120 outlet installing new paneling, resealing edges with white silicone, cutting and covering all new staple holes or nail holes and any trim and on the paneling, reinstalling, both windows, both window blinds and window trim.  
 We request eight hours labor

<b>Labor</b>		
Job #	Description	Total
9	Damage, paneling, passenger side, dinette slide exterior wall and rear wall	N/C
<b>Subtotal for Job #9:</b>		<b>0.00</b>

**Job #10 - Warranty**

COMPLAINT: REFRIGERATOR NOT IN PROPERLY

CAUSE: Refrigerator misaligned in the cabinet.

CORRECTION: Recommend removing all brackets screws, holding the refrigerator in place realigning the refrigerator to match the cabinet verifying the doors operate correctly re-securing the refrigerator with secure brackets.  
 Request one hour labor

<b>Labor</b>		
Job #	Description	Total
10	Refrigerator misaligned within the cabinet, sticking out on the right side, considerably compared to the right side.	N/C
<b>Subtotal for Job #10:</b>		<b>0.00</b>

**Job #11 - Warranty**

COMPLAINT: DOOR DAMAGED.

CAUSE: Large gouge on the inside of the door and chipped door jam

CORRECTION: Recommend replacement of the door completely door size 24 x 74 barn door style. Will require removal of the damaged door all hardware removed from the door hardware reinstalled on the new door new door re-hung and adjusted.  
 While the doors off removal and replacement of the door gym is wrapped around style door jam, 2 3/8 overall with by 79 inches and will require removal of the door jam cleaning up any nails or staples at pull through cutting the new door jam to fit with 45 angle at the top reattaching cutting new nails.  
 Will request one .5 hours labor

<b>Labor</b>		
Job #	Description	Total
11	Damaged bedroom door	N/C

**Subtotal for Job #11: 0.00**

**Job #12 - Warranty**

COMPLAINT: CABINET DOOR DAMAGED.

CAUSE: Gouge in the middle of the door, unknown object structure door

CORRECTION: Recommend complete replacement of the door. Cabinet door size 17 x 26 handle on the right hinges on the left. Require removing the screws from the hinges taking the door off, attaching all the hardware to the new door reinstalling the door properly aligning it.

Request 30 minutes of labor

**Labor**

Job #	Description	Total
12	Damaged cabinet door	N/C

**Subtotal for Job #12: 0.00**

**Job #13 - Warranty**

COMPLAINT: CHAIR HAS WHOLE TORN IN THE BACK.

CAUSE: Tear wrapped against another chair during delivery, rubbing a hole all the way through the back material

CORRECTION: Recommend recommendation replacement of the chair completely

Labor time, 15 minutes

**Labor**

Job #	Description	Total
13	Hole dinette chair	N/C

**Subtotal for Job #13: 0.00**

**Job #14 - Warranty**

COMPLAINT: COUCH IS NOT SECURED PROPERLY.

CAUSE: Unsecured couch piece rotating on the linoleum damage linoleum leaving a large mark in the linoleum.

CORRECTION: Recommendation remove damage Leno replaced with new. This will require removing all couch components all base trim, cutting the Leno away from the wall edges. Cutting the new Leno to fit and installing it this will have to be glued down. Installing a bat strip along the entire perimeter at the floor to ensure no scenes can be seen visibly.

Will request six hours labor time

**Labor**

Job #	Description	Total
14	Damaged Lino living room slide	N/C

**Subtotal for Job #14: 0.00**

**Job #15 - Warranty**

COMPLAINT: CABINET CORNER DAMAGED.

CAUSE: Unsecured furniture struck the corner of the cabinet. Patient next to the refrigerator.

CORRECTION: Recommendation replacing the entire cabinet face. Cabinet face was found to be assembled with wavy nails, preventing it to be taken apart and replacing the single piece of facia, the entire cabinet face will have to be removed and replaced. Just require removing both cabinet doors un screwing the cabinet face from the cabinet itself. Assembling the new cabinet face screwing it back into place to the cabinet reinstalling the cabinet doors.

Requesting six hours labor

<b>Labor</b>		
Job #	Description	Total
15	Damaged cabinet facia	N/C
<b>Subtotal for Job #15:</b>		<b>0.00</b>

**Job #16 - Warranty**

COMPLAINT: DAMAGE TO SLIDE FACIA

CAUSE: Unknown object struck passenger side, kitchen, dinette slide, facia, closest to the front door chipping the corner.

CORRECTION: Recommendation removal and replacement of the slide facia slide facia size 5 1/2 x 79 1/2. This require praying the slight face off cleaning up any nails or staples and pulled through cutting the new facia to fit reattaching with Brad nails cutting any in all new staple or nail holes.  
 Requesting 30 minutes labor

<b>Labor</b>		
Job #	Description	Total
16	Damaged slide facia	N/C
<b>Subtotal for Job #16:</b>		<b>0.00</b>

**Job #17 - Warranty**

COMPLAINT: washer and dryer closet wall separating

CAUSE: Unknown cause wall separating on both sides of the closet for the washer and dryer

CORRECTION: Recommendation removal of the paneling on both sides inside the closet was required on one side, removing two electrical outlets, plumbing compartment for the for the washer, hook ups, removing all that strip, cutting away silicone and removing excess silicone after its been cut. Removing the paneling conducting a full inspection of the structure to ensure nothing is broken inside. Potentially replacing studs inside the wall or screw the studs back to the exterior wall. Reinstalling the paneling, replacing all bat strips removed resealing joints with white silicone, putting any new nails or staple holes, reinstalling, electrical outlets, and plumbing compartment for the washing machine.  
 Request six hours labor

<b>Labor</b>		
Job #	Description	Total
17	Wall separating in washer dryer closet	N/C
<b>Subtotal for Job #17:</b>		<b>0.00</b>

**Job #18 - Warranty**

COMPLAINT: VENT LID IN BATHROOM BROKEN

CAUSE: AIR vent in the master bathroom, the lid will not open, cause unknown.

CORRECTION: Conduct a full inspection of the power vent to find out why the vent will not open. This will require an inspection on the roof to see if theres an obstruction. Taking a ladder inside and conducting a full inspection inside, removing the screen verifying attachment points..  
 Well, request 30 minutes diagnostic time

<b>Labor</b>		
Job #	Description	Total
18	Power vent master bath	N/C
<b>Subtotal for Job #18:</b>		<b>0.00</b>

**Job #19 - Warranty**

COMPLAINT: COMPARTMENT DOOR WILL NOT LATCH.

CAUSE: Compartment, door driver side for the basement and water utility hook ups will not latch properly

CORRECTION: Will require adjustment of the latch on the right side so that the door will properly latch and lock.

Request 15 minutes labor

<b>Labor</b>		
Job #	Description	Total
19	Compartment door latch	N/C
<b>Subtotal for Job #19:</b>		<b>0.00</b>

**Job #20 - Warranty**

COMPLAINT: SAFTEY STRAPS TO HOLD FURNITURE MISSING

CAUSE: Furniture straps missing completely FACTORY NEVER INSTALLED.

CORRECTION: Recommend ordering straps to properly secure, dinette table, and chairs, couch pieces in the dinette area and the couch in the living area parts will need to be ordered

Request 15 minutes installation time

<b>Labor</b>		
Job #	Description	Total
20	Furniture straps	N/C
<b>Subtotal for Job #20:</b>		<b>0.00</b>

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>0.00</b>

NOTICE:  
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Jun 2026

Customer Signature : \_\_\_\_\_