

aim Response

2/28/2022
11:34:17 am

aim: C3013400

Non-Warranty Goodwill Adjustment

Last Modified by: tltk

Item Reference no.

Repair start date Repair date VIN

Pre-auth

Dealer Repairing dealer name

Labor rate

Changed Type warranty rate

Date Of Purchase

013400 66284

2/12/2022 2/15/2022

4YDT26024L3101098

1194

Basden's American RV
600 E Baseline Rd
Evansville, IN 47725

150.00

0.00 SA21-411 2/22/20

Item Name

Quantity

Qty Returned

Dealer price Markup

Part total

Appr Freight

Sub Freight

Sublet

Status

662585 Regulator - Kit - Auto Change

1.00

0.00

48.79 15.00

56.11

0.00

0.00

0.00

Approved

21839

Component Model: 6020

Component Serial Number: N 19 10

446897 Hose - LP - 12" Pigtail

2.00

0.00

6.65 15.00

15.30

0.00

0.00

0.00

Approved

Operation Description

Srvc advisory

Sub hours Apvd Hours

Labor amt

Sublet

Qty Base Hours

Status

7141442B

Safety Advisory 21-414 Winn-Tec

0.50

0.50

75.00

0.00

1

0.50

Approved

Complaint: CHECK FOR REGULATOR RECALL.
Cause: regulator falls under recall. need to order regulator
Correction: removed regulator and installed new one with new lines. installed mounting bracket (AP KBS)

Submitted parts & sublet
Submitted labor & sublet

71.41
75.00

Submitted freight

0.00

Tax:

0.00

Total Submitted:

146.41

Approved parts & sublet
Approved labor & sublet

71.41
75.00

Approved freight

0.00

Tax:

0.00

Total approved:

146.41