



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

Estimate: 27266 FUENTES,
 GUILLERMO



Estimate: 27266 (Appointment Date: 11 JUN 2026 - Time: 09:00am)

Customer: 86186 - FUENTES, GUILLERMO
 Address: 4240 N. MOHAWK RD

37810
 Home Phone: 860-794-7018

Work Phone:
 Author: T.HAYES
 Location: IH
 Invoice #: 423894

Stock #:
 Stock Desc: 2018 TT MPG ULTRA LITE 2120RB
 Model: 2120RB
 Serial #: 5RXHB2621J2382611
 Chassis #:
 Mileage:
 Key #:
 Req'n #: 62782
 License #:
 Trim:

Purchase Date:
 Date In: 05 JUN 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 15 JUN 26
 Warr. Date:

Job #1 - External

COMPLAINT: CUSTOMER STATES WOULD LIKE BEARINGS CHECKED, DO NOT REPACK UNLESS YOU CALL HIM FIRST

CORRECTION: CUSTOMER WILL HAVE BEARINGS PACK NEXT TIME, AND IS AWARE TIRES ARE OUT OF DATE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00
Subtotal for Job #1:				0.00

Job #2 - External

COMPLAINT: CUSTOMER STATES SLIDE DOES NOT GO IN CROOKED - PLEASE CHECK AND ADVISE

CAUSE: SLIDE ROOM NOT CONNECTED TO GEAR TRACK ON FRONT SIDE

CORRECTION: TRACK ON FRONT SIDE REATTACHED , INSTALLED NEW BOLTS AND ADJUSTED

Labor

Code	Description	Hours	Rate	Total
Z990	REATTACHED SLIDE TRACK	0	175.00	0.00
Subtotal for Job #2:				0.00

Job #3 - External

COMPLAINT: CUSTOMER STATES SOMETHING UNDER CAMPER IS LEAKING - HE THINKS SUPPLY MAYBE - THERE ARE A COUPLE OF THINGS HANGING FROM UNDERNEATH THE CAMPER ON THE DRIVERS SIDE. WANTS TO MAKE SURE HOLDING TANK MAY BE LEAKING, PLEASE CHECK

CAUSE: LEAK AT FRESH WATER TANK DRAIN

CORRECTION: REPLACED DRAIN

Labor

Code	Description	Hours	Rate	Total
Z990	INSTALL FRESH WATER VALVE	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
72-0841	51201 FRESH WATER SHUT OFF	0	15.99	0.00



Subtotal for Job #3: 0.00

Job #4 - External

CUSTOMER WOULD LIKE BATTERY CONNECTIONS CHECKED TO SEE IF OK

Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: CUSTOMER STATES FAUCET IN SHOWER TO BE REPLACED - PLEASE CHECK AND ADVISE - EXTRA PARTS IN THE SINK

CORRECTION: REPLACED SHOWER VALVE

Labor

Code	Description	Hours	Rate	Total
Z990	REPLACED SHOWER VALVE	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
10-0826	SHOWER CONTROL VAVE DF-SA100C-BC PARCHMNT	0	24.99	0.00

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 15 Jun 2026

