

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66311

Completed : 10 FEB 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
 Licence # : Invoice # :
 Stock No : 10944 Description : 2022 TT COACHMEN CATALINA 333RETSLE
 Tag : Date In : 14 JAN 22 Mileage : 0
 Author : BH Promised :
 Location : 0220CHECK WORK Date Sched :
 Serial# : 5ZT2CAYB5NX024402 Chassis# : 5ZT2CAYB5NX024402
 Warr. Date : 10 DEC 21 Cust PO# :
 Print Date : 10 FEB 22

```

*****
Job #   Description                               JOB INFORMATION           Type Bill To
*****
1       COMPLAINT:  HOLD BACK MISSING ON COMPARTMENT DOOR           W       10024  FORES
        CAUSE:      HOLD BACK MISSING ON COMPARTMENT DOOR.
        CORRECTION: Installed compartment door hold back to
                    replace missing part.
2       COMPLAINT:  AWNING LIGHTS DON'T WORK                         W       10024  FORES
        CAUSE:      AWNING LIGHTS DO NOT WORK.
        CORRECTION: Removed monitor panel. Checked for
                    power to and from awning light switch.
                    Both ok. Checked connections at awning
                    light strip. Checked power connection.
                    Power OK. Checked 4 pin connector to
                    awning light strip. Can wiggle it and
                    get lights to come "on". Infared "Y"
                    adapted for awning lights needs
                    replaced. 12/7/2021: Turned in parts
                    request for a new part.
3       COMPLAINT:  OPEN HOLE UNDER BATHROOM SINK                   W       10024  FORES
        CAUSE:      OPEN HOLE IN FLOOR UNDER BATHROOM SINK.
        CORRECTION: Closed up hole from bottom with
                    underbelly tape. Used spray foam to
                    fill hose from top around fresh water
                    tank fill hose.
4       KITCHEN SINK BASKET MISSING                                   W       10024  FORES
2-1    COMPLAINT:  OFF DOOR SIDE ON THE BOTTOM BETWEEN THE           W       10024  FORES
        TWO SLIDES LOOKS LIKE THERE IS PAINT
        MARKS
        CORRECTION: REMOVED OLD METAL AND INSTALLED NEW
                    METAL.
3-1    THE WELD NEAR THE SPARE TIRE IT IS STARING TO RUST           W       10024  FORES
        AD CRACK
7       COMPLAINT:  AFTER REPLACEING THE Y CONNECTOR FOR THE W       10024  FORES
        AWNING LIGHTS THEY ARE STILL NOT WORKING
        CAUSE:      NEED TO REPLACE THE AWNING LIGHTS
  
```

Continued on page 2

Work Order : 66311

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
1 E210 E210 2-pk BLK ROUN W-10024 1 6.54 6.54
2 F100207754 KIT, LED CONTROLLE W-10024 1 8.12 8.12
2 6576 LED LIGHTS FOR CAR W-10024 1 135.08 135.08
4 C01231589 KITCHEN STRAINER W W-10024 1 3.68 3.68
2-1 C01307180 METAL, .040 14 X 1 W-10024 1 146.92 146.92
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
1 Z990 MISC LABOUR CODE (EXTE DKM W-10024 0.10 140.00 14.00
2 Z990 MISC LABOUR CODE (EXTE BRM W-10024 0.00 130.00 0.00
2 Z990 MISC LABOUR CODE (EXTE DKM W-10024 0.50 140.00 70.00
2 Z990 MISC LABOUR CODE (EXTE BRM W-10024 0.00 130.00 0.00
3 Z990 MISC LABOUR CODE (EXTE DKM W-10024 0.50 130.00 65.00
2-1 Z990 MISC LABOUR CODE (EXTE BRM W-10024 1.00 140.00 140.00
2-1 Z990 MISC LABOUR CODE (EXTE BRM W-10024 0.50 140.00 70.00
3-1 Z990 MISC LABOUR CODE (EXTE BRM W-10024 0.00 150.00 0.00
3-1 Z990 MISC LABOUR CODE (EXTE BRM W-10024 0.50 150.00 75.00
7 Z990 MISC LABOUR CODE (EXTE BRM W-10024 0.50 150.00 75.00
*****
```

```
*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
2 FRT UPS-AWNING REMOTE W-10024 1.00 15.61 15.61
2 FRT UPS-AWNING LIGHTS W-10024 1.00 15.67 15.67
4 FRT UPS-SINK STRAINER W-10024 1.00 15.61 15.61
2-1 FRT FREIGHT/CRATE - METAL W-10024 1.00 359.65 359.65
*****
```

CUSTOMER COMMENTS

```
*****
BH TALKED TO CUSTOMER ABOUT THE RACK AND HE OKED TO CLEAN THE SPOT AND
PAINT IT BLACK 2-9
METALIN RED TRAILER. 2-2-22 MAB
AWNING LIGHTS IN BACKROOM 1-27-22..CAM
BH ADD TWO ROS TOGETHER FOR WARRANTY SINCE NONE OF THE WARRANTY
WAS PUT INFOR ANYOF IT
CUSTOMER TO BRING CAMPER 01-11 AND DROP OFF
UNIT HAS ANOTHER RO 66088
SINK STRAINER AND AWNING REMOTE IN BACKROOM 12-13-21...CAM
AWNING REMOTE AND CONTROLLER AND SINK BASKET ORDERED
12-8-21...CAM
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 10024 300.34 509.00 0.00 406.54 0.00 1,215.88
*****
```

Continued on page 3

Work Order : 66311

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	300.34	509.00	0.00	406.54	0.00	1,215.88
