



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27038



WO #: 27038

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11240

Stock Desc: 2026 FW FOREST RIVER CEDAR

CREEK 385RK

Model: 385RK

Serial #: 4X4FCRR26TS235371

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 21 APR 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983

THIS IS THE DS FRONT WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY THE FOAM TAPE
AND INSTALL NEW WINDOW

LABOR 2.0

Labor

Job #	Description	Hours	Total
1	REPLACED WINDOW	1.00	175.00

Other Services

Code	Description	Qty	Price	Total
NII	BLACK BUTYL	2.00	12.99	25.98
NII	F100815073 WINDOW, MARK UP ON PART AT NO CHARGE	1.00	104.98	104.98

Subtotal for Job #1: 305.96

Job #2 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983

THIS IS THE DS WINDOW BEHIND ENTRY DOOR

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW, CLEAN WINDOW OPENING, APPLY THE FOAM TAPE
AND INSTALL NEW WINDOW

LABOR 2.0

Labor

Job #	Description	Hours	Total
2	REPLACED WINOW	1.00	175.00

Other Services

Code	Description	Qty	Price	Total
NII	F100815073 WINDOW, MARK UP ON PART	1.00	324.26	324.26

Subtotal for Job #2: 499.26

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Job #3 - Warranty

COMPLAINT: TECH SERV BULLETIN 20-1983
THIS WINDOW IS NDS REAR

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW,CLEAN WINDOW OPENING,APPLY THE FOAM TAPE
AND INSTALL NEW WINDOW
LABOR 2.0

Labor

Job #	Description	Hours	Total
3	REPLACED WINDOW	1.00	175.00

Other Services

Code	Description	Qty	Price	Total
NII	F100815151 WINDOW, MARK UP ON PART	1.00	140.63	140.63

Subtotal for Job #3: 315.63

Job #4 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983
THIS WINDOW IS NDS REAR 2ND FROM BACK

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW,CLEAN WINDOW OPENING,APPLY THE FOAM TAPE
AND INSTALL NEW WINDOW
LABOR 2.0

Labor

Job #	Description	Hours	Total
4	REPLACED WINDOW	1.00	175.00

Other Services

Code	Description	Qty	Price	Total
NII	F100815151 WINDOW, MARK UP ON PART	1.00	140.63	140.63

Subtotal for Job #4: 315.63

Job #5 - Warranty

COMPLAINT: TECH SERVICE BULLETIN 20-1983
THIS IS NDS MIDDLE WINDOW

CAUSE: FOREST RIVER SENT NOTICE TO TRIAM ABOUT TSB 20-1983

CORRECTION: REMOVE CURRENT WINDOW,CLEAN WINDOW OPENING,APPLY THE FOAM TAPE
AND INSTALL NEW WINDOW
LABOR 2.0

Labor

Job #	Description	Hours	Total
5	REPLACED WINDOW	1.00	175.00

Other Services

Code	Description	Qty	Price	Total
NII	F100815072 WINDOW, MARK UP ON PART	1.00	340.02	340.02

Subtotal for Job #5: 515.02



Customer #: 47602
TRIAM RV CENTER-EAST
TN,



W/O: 27038

Parts Total:	0.00
Labour Total:	875.00
Sublet Total:	0.00
Extras Total:	1,076.50
WORK ORDER TOTAL:	1,951.50

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 16 Jun 2026

Customer Signature : _____



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

