



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 27317



WO #: 27317 (Appointment Date: 24 JUN 2026 - Time: 09:00am)

Customer: 60689 - BUCKNER, MALCOLM  
 Address: 252 EASTER GAP RD  
 MARSHALL, NC  
 28753

Home Phone: 828-206-0952

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 10908

Stock Desc: (10908) 2024 KZ-RV CONNECT SE

312BHKSE

Model: 312BHKSE

Serial #: 4EZTL3325R4120335

Chassis #:

Mileage:

Key #: 2500

Req'n #:

License #:

Trim:

Purchase Date: 06 FEB 25

Date In: 15 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 06 FEB 25

**Job #1 - External**

COMPLAINT: SC RF LOT 11 TO KINSER PARK AWNING STUCK OUT CHECK AND ADVISE

CAUSE: FOUND CUSTOMER AWNING STUCK OPEN TESTED 12V AND IT IS RECEIVING 13.2V AT MOTOR BUT DOES NOT OPERATE. DUE TO AN INTERNAL DEFECT MOTOR HAS FAILED

CORRECTION: REPLACE AWNING MOTOR AND RETEST  
 1.0L

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
<b>Subtotal for Job #1:</b>				<b>0.00</b>

**Job #2 - External**

SC 100\$

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: AWNING FABRIC IS NOT ALLOWING ARMS TO RETRACT ALL OF THE WAY

CAUSE: DUE TO DEFECT IN THE FABRIC IT HAS SHRUNK ON ONE SIDE CAUSING A TWIST WHILE RUNNING THE AWNING IN

CORRECTION: REPLACE AWNING FABRIC AND RETEST  
 L 1.5

**Subtotal for Job #3: 0.00**

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

Customer #: 60689  
 BUCKNER, MALCOLM



-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_  
-----

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 15 Jun 2026

Customer Signature : \_\_\_\_\_

W/O: 27317

Customer Work  
Order



Customer #: 60689  
BUCKNER, MALCOLM

