

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Authorized  
 CLAIM 2711708  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2AVEC1VG816041  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 452 / 452  
 ITEM # AVT16BHX-452  
 DEALER RO # 73446-1  
 CLAIM START DATE 06/16/2026  
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code**      **Operational Description**  
 20-66-02-17-000672      Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-06-16 12:47:32 :: Complaint: Entry striker plate is sticking  
 Cause: Door is hanging up/sticking on the striker plate Correction: Remove the striker plate, flattened striker plate  
 out. Used two phillips screws and reattached the striker plate to the door jamb. Tested door and it operates  
 normally.

|                |                    |      |                               |
|----------------|--------------------|------|-------------------------------|
| <b>Model#</b>  | <b>Dlr Sub Hrs</b> | 0.20 | <b>Sub Labor Amt</b> \$38.00  |
| <b>Serial#</b> | <b>Appr Hrs</b>    | 0.20 | <b>Appr Labor Amt</b> \$38.00 |

**Notes**

### Labor

**Line# 2**      **Operation Code**      **Operational Description**  
 70-164-19-00-001970      Exterior Exhaust Vent - Appliances/Range Hood/Reseal/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-06-16 12:49:05 :: Complaint: Gap in sealant at exhaust vent  
 Cause: Found a small gap in the sealant on the bathroom exhaust vent on the roof. Correction: Used self leveling  
 dicor to seal the gap in the sealant.

|                |                    |      |                               |
|----------------|--------------------|------|-------------------------------|
| <b>Model#</b>  | <b>Dlr Sub Hrs</b> | 0.20 | <b>Sub Labor Amt</b> \$38.00  |
| <b>Serial#</b> | <b>Appr Hrs</b>    | 0.20 | <b>Appr Labor Amt</b> \$38.00 |

**Notes**

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 10-3-01-00-000078      Bumper Mount Spare Tire Carrier - Frame & Chassis/Wheels, Tires, Hubcaps/  
 Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-06-16 12:50:31 :: Complaint: U bolt is broken Cause: Spare  
 tire carrier u bolt is broken, unknown cause Correction: Remove broken u bolt, installed and secure new u bolt  
 Additional Note : stephanie@dealer-advisors.com, 2026-06-16 12:53:31 :: \*\*this is only for the broken U bolt, not  
 the entire carrier. Did not see a flat rate code for only the bolt.\*\*

|                |                    |      |                               |
|----------------|--------------------|------|-------------------------------|
| <b>Model#</b>  | <b>Dlr Sub Hrs</b> | 0.30 | <b>Sub Labor Amt</b> \$57.00  |
| <b>Serial#</b> | <b>Appr Hrs</b>    | 0.30 | <b>Appr Labor Amt</b> \$57.00 |

**Notes**

|                  |                 |          |                 |                 |          |
|------------------|-----------------|----------|-----------------|-----------------|----------|
| <b>Submitted</b> | Labor Amt       | \$133.00 | <b>Approved</b> | Labor Amt       | \$133.00 |
|                  | Parts & Freight | \$0.00   |                 | Parts & Freight | \$0.00   |
|                  | Total           | \$133.00 |                 | Total           | \$133.00 |

---

**DEALER** **DATE**  
**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** **DATE**  
**SIGNATURE**

All repairs described have been inspected and are satisfactory.