

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 13496

Date In: 12 MAY 26 Author: MGRAY
Promised Date: 30 JUN 26 Stock No:
: Year:
Customer Name: 1020 - GRAND DESIGN Manufacturer: GRAND DESIGN
Address: 11333 COUNTY RD 2 Brand: MOMENTUM
: MIDDLEBURY, IN Model: 395MS-R
Postal/Zip: 46540 Miles/Hrs:
Phone#(res): 888-825-2820 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: NONE Tag#: DB - 5/23
Purchased Date: :
Delivery Date: :
InService Date: :
Serial#: 573FM4436M1117889 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: CS CAMPAIGN FOR WALL SECURMENT AND DOOR W 1020 GRAND
INSPECTIONS. (920017, 920018, 92000190)
CAUSE: Check front bedroom for movement on side
walls. Does show signs of movement.
Consult gd for futher instruction on how
to proceed. Took pic of before lifting
the front and after. Removed front fylon
to check for cracks. None found. But my
have remove front cap as well for any
other repairs.
CORRECTION: REQUEST: 5.9 - FOR LAG BOLTS REMOVE
FRONT CAP:2HOUR WARR APPROVED: 0.1 hour
for the inspection, 5.9 hours for the
lag bolts, 2 hours to R&I the front cap
and 0.1 hour to inspect doors
afterwards.
1 COMPLAINT: CUSTOMER REQUESTS AN ESTIMATE TO HAVE E 15511 GRASS
THE WIRE FOR THE HAPPIJACK SYSTEMS THE
CORRECT WAY-
CAUSE: Estimate for wiring the happy jack
properly. Could possibly run the wire
through the ac ducting. Also would need
to remove some wall paneling to the wire
down to the switch onthe wall. Could
take several hours to retrace the wire.
CORRECTION: CMR DECLINED
WARR COMPLAINT: WARRANTY REPAIR 2 - THERE IS A SCREW AT W 1020 GRAND
THE END OF THE BED THAT IS PUSHING

Continued on page 2

Work Order : 13496

```
*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                THROUGH THE LINO.
CAUSE:   Screw head popping up in bedroom at the
                foot of the bed under lino. Pics
                uploaded.
CORRECTION: CUT OVER SCREW TAKE SCREW OUT AND SMALL
                REPAIR TO LINO.  REQUEST: 1HR
*****
```

```
*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
WARR0 8220961661 BOLT 1/2 - 6 X 3 - 1/2" HE W-1020      0     1.05     0.00
WARR0 822061052 SEALANT SIKAFLEX 252 WHITE W-1020      0    30.03     0.00
*****
```

```
*****
Job# Lab Code Description           LABOUR           Mech Bill to   Hrs   Rate   Total
*****
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.50  140.00    70.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
  1 DIAG  DIAGNOSTICS                E-15511  0.00  140.00     0.00
  1 DIAG  DIAGNOSTICS                TD E-15511  0.37  140.00    51.80
  1 DIAG  DIAGNOSTICS                TD E-15511  0.24  140.00    33.60
  1 DIAG  DIAGNOSTICS                TD E-15511  0.39  140.00    54.60
  1 Z990 MISC LABOUR CODE (EXTE E-15511  0.00  140.00     0.00
  1 DIAG  DIAGNOSTICS                TD E-15511  0.00  140.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR01 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR02 Z992 MISC LABOUR CODE (WARR TD W-1020      0.00  140.00     0.00
ARR02 Z992 MISC LABOUR CODE (WARR TD W-1020      0.09  140.00    12.60
*****
```

```
*****
Job # Excode Description           EXTRAS           bill to   Qty   Price   Total
*****
  1 SSE SHOP SUPPLIES - EXTERNAL E-15511  1.00  10.50    10.50
*****
```

```
*****
                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
E 15511           0.00    140.00    0.00    10.50    8.30    158.80
W 1020           0.00     82.60    0.00     0.00    0.00     82.60

Totals           0.00    222.60    0.00    10.50    8.30    241.40
*****
```

Continued on page 3

Work Order : 13496

&k2S
&k0S