



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27238



WO #: 27238 (Appointment Date: 01 JUN 2026 - Time: 02:00pm)

Customer: 93152 - CULBERTSON, ROBERT
Address: PO BOX 262
NORTON VA
24273

Home Phone: (276) 219-9555

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11126

Stock Desc: (11126) 2025 KZ-RV CONNECT SE
211MKSE

Model: 211MKSE

Serial #: 4EZTL2320S4046550

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 28 APR 26

Date In: 01 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 28 APR 26

Job #1 - Warranty

COMPLAINT: TABLE LEG ON THE DINING TABLE DOES NOT LINE UP CORRECTLY AND MISSING A SCREW

CAUSE: TABLE LEG IS MOUNTED ABOUT 1/2 INCH OUT MORE THAN NEEDED TO LINE UP CORRECTLY AT WALL

CORRECTION: RELOCATE THE TABLE LEG 1/2 INCH OVER AND SECURE IN PLACE
LABOR .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: KITCHEN FAUCET HAS A SMALL DRIP
CUST NOTICED IT WHEN THEY WAS USING THE SINK COVER AND NOTICED WATER WAS PUDDLING ON TOP OF THE COVER

CAUSE: TECH VERIFIED THE FAUCET HAS A SMALL DRIP WHEN TURNED OFF. THERE IS A INTERNAL DEFECT IN THE FAUCET.

CORRECTION: REPLACE THE KITCHEN FAUCET AND TEST
LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE FRIDGE IS MAKING A NOISE WHEN RUNNING. THIS IS A LOUD NOISE CUSTOMER STATED.

CORRECTION: NO ISSUES FOUND AT THIS TIME

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SEAL ON SLIDE OUT IS DAMAGED AT THE BOTTOM

CAUSE: TECH VERIFIED CONCERN AND FOUND SEAL WAS FOLDING IN THE CENTER DUE TO BEING MOUNTED TO HIGH.

CORRECTION: NEED TO REMOVE THE SEAL AND REINSTALL TO TAKE CARE OF THIS ISSUE
LABOR .50

Customer #: 93152
CULBERTSON, ROBERT



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: SLIDE IS MAKING A NOISE. CUST STATED THAT IT SOUNDS LIKE IT IS RUBBING HARD ON SOMETHING.

CORRECTION: NO ISSUES FOUND AT THIS TIME

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CITY WATER HOOKUP IS LEAKING CUST STATED ITS NOT BAD BUT LOOKS LIKE THE SCREEN WAS INSTALLED WRONG PLEASE CHECK AND ADVISE

CORRECTION: NO ISSUE AT THIS TIME

Subtotal for Job #6: 0.00

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES VENT RIGHT IN FRONT OF THE TABLE IS CRACKED

CAUSE: VENT WAS OVER TIGHTENED AT INSTALL AND HAS DEVELOPED A CRACK

CORRECTION: REPLACE VENT
LABOR .10

Subtotal for Job #8: 0.00

Customer Work Order

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 16 Jun 2026

Customer Signature : _____

Customer #: 93152
CULBERTSON, ROBERT

