



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27326



WO #: 27326

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11314
Stock Desc: 2026 FW FOREST RIVER
SANDPIPER 3800RK
Model: 3800RK
Serial #: 4X4FSAP22TJ049243
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 16 JUN 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #2 - Warranty

COMPLAINT: METAL IN FRONT COMPARTMENT DOOR IS SCRATCHED

CAUSE: SCRATCHED AT FACTORY BUILD, NOTED ON DAF

CORRECTION: REPLACE DAMAGED METAL IN FORNT COMPARTMENT AREA
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: REAR WINDOW IS DAMAGED
GUIDE STRIP HAS CAME LOOSE AND NOT ATTACHED TO THE WINDOW AS IT SHOULD BE

CAUSE: NOTED ON DAF
DAMAGED AT BUILD

CORRECTION: REMOVE DAMAGED WINDOW AND REPLACE WITH NEW WINDOW
LABOR 1.0

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: REAR WINDOW SCREEN IS DAMAGED AND HAS A HOLE IN IT

CAUSE: NOTED ON DAF

CORRECTION: REPLACE REAR WINDOW SCREEN
LABOR .40

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: DAMAGE TO CABINET DOOR IN KITCHEN, STRAIGHT CHUNK IS MISSING

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: UPPER PANEL IN KITCHEN CABINET IS LOOSE FROM WALL AND THIS IS ALLOWING THE CABINET SHELF TO NOT BE STABLE

CAUSE: NOTED ON DAF
GREEN TAPE FROM FACTORY MARKING ISSUE AS WELL

CORRECTION: NEED TO SECURE THE CABINET SHELF INTO CORRECT PLACE AND ALLOW IT TO REST AGAINST THE WALL AS THE OTHER ONES DO
LABOR .20

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: STILE BESIDE THE KITCHEN CABINETS ARE STAINED IN DIFFERENT SPOTS

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND THE AREA
LABOR .20

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: KITCHEN CABINET DOORS WILL NOT SHUT LIKE DESIGNED TO DO

CAUSE: NOTED ON DAF
HINGE IS NOT IN THE CORRECT LOCATION TO ALLOW CABINET TO SHUT CORRECTLY

CORRECTION: ADJUST HINGES SO CABINET DOOR WILL SHUT ALL THE WAY
LABOR .30

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: SHADE OVER THE KITCHEN SINK IS NOT LONG ENOUGH AND DOES NOT COME ALL THE WAY DOWN COVERING THE WINDOW. TECH DID ATTEMPT TO ADJUST HOWEVER THIS DID NOT FIX THE ISSUE

CAUSE: NOTED ON DAF
WRONG SIZE SHADE WAS INSTALLED

CORRECTION: REMOVE AND REINSTALL VALANCE
REPLACE TH SHADE WITH CORRECT SIZE
LABOR .50

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: STAIN/GUMMY SPOT ON KITCHEN COUNTER AND THIS WILL NOT JUST WIPE OFF.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND BUFF COUNTER
LABOR .50



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: KITCHEN CABINET HANDLE IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE HANDLE ON CABINET
LABOR .20

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: STILE ON KITCHEN SLIDE IS CHIPPED AND PAINT FADED IN DIFFERENT AREAS

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .30

Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: KITCHEN BAR IS CHIPPED AT THE BOTTOM FRONT. THIS AREA FACES THE LIVING PART OF THE UNIT.

CAUSE: NOTED ON DAF

CORRECTION: BUFF AND SMOOTH AREA
LABOR .40

Subtotal for Job #13: 0.00

Job #14 - Warranty

COMPLAINT: LEFT VALANCE DOWN AT DELIVERY OVER DOUBLE SEATING

CAUSE: NOTED ON DAF
DOWN AT CHECK IN

CORRECTION: RESECURE VALANCE IN CORRECT PLACE
LABOR .20

Subtotal for Job #14: 0.00

Job #15 - Warranty

COMPLAINT: VALANCE DOWN OVER DESK IN THE LIVING AREA

CAUSE: NOTED ON DAF
DOWN AT DELIVERY

CORRECTION: RESECURE VALANCE IN CORRECT PLACE
LABOR .20

Subtotal for Job #15: 0.00

Job #16 - Warranty

COMPLAINT: VALANCE ON LIVING AREA SLIDE OUT IS DOWN

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BACK INTO CORRECT PLACE



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR .20

Subtotal for Job #16: 0.00

Job #17 - Warranty

COMPLAINT: STAINS OF SOMETHING THAT WAS SPILLED DOWN THE FRONT OF THE STILE ONTO THE FLOOR

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND COLOR BLEND THE STILE WHERE IT IS STAINED
LABOR .50

Subtotal for Job #17: 0.00

Job #18 - Warranty

COMPLAINT: DRAWER UNDER TV INSTALLED SIDEWAYS, HARD TO OPEN AND CLOSE

CAUSE: NOTED ON DAF
HAREWARE WAS FOUND ON SHELF IN FRONT OF DRAWER

CORRECTION: ADJUST DRAWER GUIDE SO DRAWER IS IN CORRECTLY, OPENS AND CLOSING CORRECTLY
LABOR .40

Subtotal for Job #18: 0.00

Job #19 - Warranty

COMPLAINT: RIGHT OF THE ENTRY DOOR HAS EXT PAINT DULLING AND STREAKS THAT WILL NOT WIPE OFF

CAUSE: NOTED ON DAF

CORRECTION: BUFF AREAS TO BLEND ON EXT
LABOR 2.0

Subtotal for Job #19: 0.00

Job #20 - Warranty

COMPLAINT: ENTRY DOOR HARD TO SHUT AND DOOR IS HITTING ON BOTTOM LEFT

CAUSE: NOTED ON DAF

CORRECTION: ADJUST ENTRY DOOR TO OPERATE CORRECTLY
LABOR .50

Subtotal for Job #20: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

W/O: 27326



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Signature : _____

Date: 16 Jun 2026

W/O: 27326

Customer Work Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

