

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA Labor rate: \$150.00 OWNER INFORMATION	CLAIM STATUS Authorized CLAIM 920607 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CANB1NU039954 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 103 / 103 ITEM # CAT243RBSLE DEALER RO # 66342 CLAIM START DATE 02/05/2022 CLAIM END DATE 01/01/1900
--	--

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code								
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-02-05 15:30:22 :: TRIM AROUND INSIDE OF THE ENTRANCE DOOR IS LOOSE TRIM AROUND INSIDE OF ENTRANCE DOOR IS LOOSE. Trim around entrance door not attached to wall. Added staples in trim to secure to wall. Filled staple holes with matching putty.										
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.10</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$15.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.10</td> <td>Appr Labor Amt</td> <td>\$15.00</td> </tr> </table>	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00	Appr Hrs	0.10	Appr Labor Amt	\$15.00
Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00							
Appr Hrs	0.10	Appr Labor Amt	\$15.00							
Notes										

Labor

Line# 2	Operation Code 50-134-01-00-001453	Operational Description LP Regulator Hose, Pigtail - Includes Leak Test - LP Gas/LP Gas System/ Replace/No Tread Code								
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-02-05 15:31:49 :: WATER HEATER WILL NOT LITE. Water heater will try to lite. Flame is lazy and burns at orifice. Blew out burner tube but still will not burn correctly. LP pressure is 11 in.wc. when trying to lite. Removed burner orifice and checked to see if blocked. Orifice ok. Reinstalled orifice. Burner would still not lite and burn. Checked gas line from water heater back to junction with main LP line. Found clamp holding line up next to frame was twisted and pinching LP line flat. Removed clamp. Straightened LP line. Reclamped line in a different location to prevent pinching line flat.										
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.40</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$60.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.40</td> <td>Appr Labor Amt</td> <td>\$60.00</td> </tr> </table>	Dlr Sub Hrs	0.40	Sub Labor Amt	\$60.00	Appr Hrs	0.40	Appr Labor Amt	\$60.00
Dlr Sub Hrs	0.40	Sub Labor Amt	\$60.00							
Appr Hrs	0.40	Appr Labor Amt	\$60.00							
Notes										

Submitted <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Labor Amt</td> <td style="width: 20%;">\$75.00</td> </tr> <tr> <td>Parts & Freight</td> <td>\$0.00</td> </tr> <tr> <td>Total</td> <td>\$75.00</td> </tr> </table>	Labor Amt	\$75.00	Parts & Freight	\$0.00	Total	\$75.00	Approved <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Labor Amt</td> <td style="width: 20%;">\$75.00</td> </tr> <tr> <td>Parts & Freight</td> <td>\$0.00</td> </tr> <tr> <td>Total</td> <td>\$75.00</td> </tr> </table>	Labor Amt	\$75.00	Parts & Freight	\$0.00	Total	\$75.00
Labor Amt	\$75.00												
Parts & Freight	\$0.00												
Total	\$75.00												
Labor Amt	\$75.00												
Parts & Freight	\$0.00												
Total	\$75.00												

DEALER _____ **DATE** _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.