

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66342

Completed : 31 JAN 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10693 Description : 2022 TT COACHMEN CATALINA 243RBSLE
Tag : Date In : 20 JAN 22 Mileage : 0
Author : C.ALLEN Promised : 31 JAN 22
Location : 03 Date Sched :
Serial# : 5ZT2CANB1NU039954 Chassis# : 5ZT2CANB1NU039954
Warr. Date : Cust PO# :
Print Date : 05 FEB 22

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: PDI - NEW TRAVEL TRAILER I PDI PRE-D
 CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.
 CORRECTION: Moved unit into shop from sales lot.
 Purged and filled LP tanks. Installed
 new battery box. Relocated clamp
 holding 7-way cord to clear hitch
 bracket. Shortened battery cables to
 fit. Checked all exterior lights and
 brakes. Checked lug nuts and set tire
 pressure at 65 psi. Checked power cord.
 Checked roof and awning. Checked
 entrance door and all compartment doors.
 Checked all interior lights. Checked
 all windows and blinds. Checked all
 cabinets and drawers. Checked all
 electrical outlets and GFCI outlets.
 Checked all USB outlets. Checked
 converter output. Recorded all serial
 numbers and took pictures. Applied all
 company decals. Filled fresh water
 tank. Flushed antifreeze from water
 lines and faucets. Checked all water
 lines and faucets for leaks. Opened
 by-pass on water heater and filled.
 Purged all air from water lines.
 Performed LP drop test and set LP
 pressure at 11 in.wc. Filled all
 holding tanks and checked monitor panel.
 Checked TV Antenna, TV, Radio and
 Fireplace. Operated all appliances. By
 -passed water heater and blew out all
 water lines and faucets, including
 outside shower. Added antifreeze to
 water lines and faucets, including

Continued on page 2

Work Order : 66342

 Job # Description JOB INFORMATION Type Bill To

outside shower. Poured antifreeze in
 all drain traps. Drained all holding
 tanks, including water heater. Moved
 unit back to sales lot.

1 COMPLAINT: TRIM AROUND INSIDE OF THE ENTRANCE DOOR W 10024 FORES
 IS LOOSE
 CAUSE: TRIM AROUND INSIDE OF ENTRANCE DOOR IS
 LOOSE.
 CORRECTION: Trim around entrance door not attached
 to wall. Added staples in trim to
 secure to wall. Filled staple holes
 with matching putty.

2 COMPLAINT: WATER HEATER WILL NOT LITE. W 10024 FORES
 CAUSE: WATER HEATER WILL NOT LITE.
 CORRECTION: Water heater will try to lite. Flame is
 lazy and burns at orifice. Blew out
 burner tube but still will not burn
 correctly. LP pressure is 11 in.wc.
 when trying to lite. Removed burner
 orifice and checked to see if blocked.
 Orifice ok. Reinstalled orifice. Burner
 would still not lite and burn. Checked
 gas line from water heater back to
 junction with main LP line. Found clamp
 holding line up next to frame was
 twisted and pinching LP line flat.
 Removed clamp. Straightened LP line.
 Reclamped line in a different location
 to prevent pinching line flat.

 Job # Part No Description PARTS Bill to Qty Price Total

PDINT	13034	55362 STD BATTERY	I-PDI	1	10.95	10.95
PDINT	24181	-50 RV ANTI-FREEZE	I-PDI	2	4.99	9.98

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

DINTT	Z991	MISC LABOUR CODE (INTE DKM	I-PDI	0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE DKM	I-PDI	0.92	150.00	138.00
DINTT	Z991	MISC LABOUR CODE (INTE DKM	I-PDI	4.05	150.00	607.50
DINTT	Z991	MISC LABOUR CODE (INTE DKM	I-PDI	0.18	150.00	27.00
DINTT	Z991	MISC LABOUR CODE (INTE DKM	I-PDI	0.80	150.00	120.00
DINTT	Z991	MISC LABOUR CODE (INTE DKM	I-PDI	0.05	150.00	7.50
1	Z990	MISC LABOUR CODE (EXTE DKM	W-10024	0.10	150.00	15.00
2	Z990	MISC LABOUR CODE (EXTE DKM	W-10024	0.40	150.00	60.00

Continued on page 3

Work Order : 66342

```

*****
Job #  Excode   Description   EXTRAS      bill to    Qty    Price    Total
*****
DINTT  SS       SHOP SUPPLIES          I-PDI      1.00    35.00    35.00
DINTT  LP20      20 LB. LP CYLINDER      I-PDI      2.00    14.00    28.00
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras      Tax      Total
*****
I      PDI         20.93    900.00    0.00      63.00      0.00      983.93
W      10024        0.00     75.00    0.00       0.00      0.00       75.00

      Totals      20.93    975.00    0.00      63.00      0.00      1,058.93

```