

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2685011
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT3SN3B3TG706407
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 049 / 049A
 ITEM # SNF38LAUNDRY
 DEALER RO # 73100-1
 CLAIM START DATE 05/22/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 60-138-01-00-001525 Termination Valve Handle - Plumbing/Drainage System/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:21:07 :: Complaint: Dump valve handles are missing in several locations Cause: Handles are missing Correction: Replace missing dump valve handles

| | | | |
|----------------|--------------------|------|------------------------------|
| Model# | Dlr Sub Hrs | 0.00 | Sub Labor Amt \$0.00 |
| Serial# | Appr Hrs | 0.00 | Appr Labor Amt \$0.00 |

Notes

Please provided requested Labor Amount.
 Forest River requested the following information: Please provided requested Labor Amount. The Dealer has failed to provide it within 14 days. The repair line has now been denied as recommended by The Forest River Way guidelines.

Labor

Line# 2 **Operation Code** **Operational Description**
 10-9-15-00-000168 Polymax Underbelly - Frame & Chassis/Levelers, Underbelly/Repair or Replace/
 No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:22:09 :: Complaint: HOle in the underbelly Cause: Hole from factory Correction: Performed a patch repair. Cut new underbelly material to size. Used sealant and fasteners with backers to complete repair.

| | | | |
|----------------|--------------------|------|--------------------------------|
| Model# | Dlr Sub Hrs | 1.00 | Sub Labor Amt \$190.00 |
| Serial# | Appr Hrs | 1.00 | Appr Labor Amt \$190.00 |

Notes

Authorized 1 hour as Requested to Repair Underbelly. This authorization is pending ALL requirements of repair code have been met.

Labor

Line# 3 **Operation Code** **Operational Description**
 60-136-24-00-002002 Water Line Shut-Off Valve - Plumbing/Fresh Water Supply/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:26:56 :: Complaint: E10 code on washer Cause: Water valves off and inaccessible Correction: Had to cut off and remove silicone from secured trim. Remove fasteners from trim. Remove trim to allow access to water valves. Turned on water valves and tested washing machine. Verified proper operation and reinstalled trim.

| | | | |
|----------------|--------------------|------|-------------------------------|
| Model# | Dlr Sub Hrs | 0.50 | Sub Labor Amt \$95.00 |
| Serial# | Appr Hrs | 0.40 | Appr Labor Amt \$76.00 |

Notes

The pictures provided on this repair line do not show the problem described in the Complaint, Cause, & Correction. Please provide pictures of the following: of the E01 Error Code described. The E10 code is what is stated in the notes, and there is a picture of that.

Excessive labor requested to remove stile on the left side of the washer and dryer to gain access to hot and cold waterlines. Turn water supply lines on and resecure trim to the left of washer and dryer

Labor

Line# 4

Operation Code 30-95-24-00-000948 **Operational Description** Dinette Table Top - Booth - Interior/Dinette/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:28:47 :: Noting only. ktichen table is scratched.

Model# **Dlr Sub Hrs** 0.00 **Sub Labor Amt** \$0.00

Serial# **Appr Hrs** 0.00 **Appr Labor Amt** \$0.00

Notes

Please provided requested Labor Amount.

No labor needed, just noting.

Noted to vin. Table is scratched

Labor

Line# 5

Operation Code 30-92-01-00-001112 **Operational Description** Information Sticker or Decal - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:29:38 :: Missing all owner manuals. Only the keys and envelope are present. Additional Note : stephanie@dealer-advisors.com, 2026-05-22 11:32:31 :: I could not find a code for the owners manual Additional Note : stephanie@dealer-advisors.com, 2026-05-22 11:41:11 :: NO time needed, but wanted this line to be seen so part order was accurate for the manual.

Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$19.00

Serial# **Appr Hrs** 0.00 **Appr Labor Amt** \$0.00

Notes

The problem described on this repair line is normal and would not be considered a warranty issue. The repair has been denied. Please note: Owner's Manual are Avialble online

Labor

Line# 6

Operation Code 30-307-01-00-000920 **Operational Description** Fireplace Remote Control - Interior/Fireplace/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:33:13 :: Mlissing air conditioner remotes Need to order and replace remote Additional Note : stephanie@dealer-advisors.com, 2026-05-22 11:37:18 :: There is not flat rate code for an AC remote

Model# **Dlr Sub Hrs** 0.00 **Sub Labor Amt** \$0.00

Serial# **Appr Hrs** 0.00 **Appr Labor Amt** \$0.00

Notes

Please provide photo of the Model # on the AC

Forest River requested the following information: Please provide photo of the Model # on the AC

The Dealer has failed to provide it within 14 days. The repair line has now been denied as

recommended by The Forest River Way guidelines.

Labor

Line# 7

Operation Code 70-147-01-00-001779 **Operational Description** TV Remote - Appliances/Television/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:37:36 :: TV remotes are missing. Need to order and replace.

Model# **Dlr Sub Hrs** 0.00 **Sub Labor Amt** \$0.00

Serial# **Appr Hrs** 0.00 **Appr Labor Amt** \$0.00

Notes

Labor

Line# 8

Operation Code 30-307-01-00-000920 **Operational Description** Fireplace Remote Control - Interior/Fireplace/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-22 11:37:56 :: Fireplace remote is missing. Order and replace remote.

Model# **Dlr Sub Hrs** 0.00 **Sub Labor Amt** \$0.00

