



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73090-1  
 Promised Date:  
 05 MAY 26

\*73090-1\*

WO #: 73090-1

Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date:  
 Invoice#:  
 Author: ADVISOR  
 Stock Desc: 9689 2026 TRACER 275BH  
 Serial#: 527080  
 Chassis#: 5ZT2TRTB4TB527080  
 Miles/Hrs:  
 Tag#:  
 Purchased Date:  
 Warranty Date:

Date In: 05 MAY 26  
 Time In:

**Job #A - Warranty**

COMPLAINT: Awning electrical short

CAUSE: ELECTIRCAL SHORT

CORRECTION: Upon PDI and delivery awning was not working. The awning and internal lights were not working, the fuse was blown. The awning and internal lights are connected to the same fuse. Tech open the awning manually and disconnected the power plug and tested the power wire at that time the awning did retract and open. The tech then followed the awning wires to the wall outside wall of the entrance of the inside of the unit the wires of the awning did work there is no pinched wires. The tech found that there is a short inside of the RV unit and still needs to find the short. This short not only affects the awning but the interior lights as well.

The tech needs more time to find the short to ground wires inside of the RV unit. Tech has spent 4 hour on unit now.

Request 8 hours

Photos attached

**Labor**

Job #	Description	Total
A	MISC LABOUR CODE (WARRANTY)	N/C
<b>Subtotal for Job #A:</b>		<b>0.00</b>

**Job #01 - Warranty**

COMPLAINT: Wire short for awning

CAUSE: Wire short from factory

CORRECTION: The shorted wire have to found behind the wall of the unit. It can cause a fire inside. Tech has to unscrew the compartments in the kitchen and besides the door opening. The fuse box has to be unscrewed and removed so the wires can be found. Once found the new wires need to be run back through the walls and connected to correctly to the fuse box and to the switch of the awning. All screws and compartments need to be replaced back to the factory location and installed. The awning wires also are attached to the lights of the unit.

Request 8 hours

Photos attached

**Labor**

Job #	Description	Total
01	Wire short for awning(WARRANTY)	N/C

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,

\*1000\*

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
<b>Subtotal for Job #01:</b>				<b>0.00</b>

**Job #03 - Warranty**

COMPLAINT: DAMAGE TO SIDE FACIA CABINET OVER SINK

CAUSE: Factory bad install

CORRECTION: Tech has to unscrew damaged fascia remove. Also unscrew cabinet, remove cabinet for repair over the kitchen sink. Once parts are in the fascia has to be replaced and screwed back in. The kitchen cabinet has to be screwed and replaced back into factory location.

Request 4 hours

**Labor**

Job #	Description	Total
03	Damaged fascia (WARRANTY)	N/C
<b>Subtotal for Job #03:</b>		<b>0.00</b>

**Job #04 - Warranty**

COMPLAINT: TV HAS SCRATCHES

CAUSE: Bad install

CORRECTION: Tv need to be unscrewed and then replaced with a new TV. New tv needs to be screwed back in to tv and placed back into fatory position. The new tv has to tested and made sure it's working.

Request 1.5 hours

**Labor**

Job #	Description	Total
04	Scratched TV (WARRANTY)	N/C
<b>Subtotal for Job #04:</b>		<b>0.00</b>

**Job #05 - Warranty**

COMPLAINT: SCRATCHES ON STOVE TOP COVER

CAUSE: Unknown

CORRECTION: Stove top needs to be unscrewed and taken off. A new replacement needs new screws and stove top needs to be screwed back into fatory location. Then the stove needs to be tested for leaks.

Request 1.5

**Labor**

Job #	Description	Total
05	Stove top Scratches(WARRANTY)	N/C
<b>Subtotal for Job #05:</b>		<b>0.00</b>

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>0.00</b>

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 11 May 2026

Customer Signature : \_\_\_\_\_

Customer Work Order

W/O: 73090-1  
Promised Date: 12 MAY 26

\*73090-1\*

Customer #: 1000  
MYERS "RV" CENTER,  
INC.,

\*1000\*