

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD  EVANSVILLE, IN 47725 USA  <b>Labor rate:</b> \$150.00 <b>OWNER INFORMATION</b>	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 906201 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2CAGC4NK003399 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 203 / 203 <b>ITEM #</b> BCAT184BHS <b>DEALER RO #</b> 66362 <b>CLAIM START DATE</b> 01/24/2022 <b>CLAIM END DATE</b> 01/01/1900
--	---

<b>Retail Date of Purchase</b>	<b>WARRANTY EXPIRATION DATE</b>
--------------------------------	---------------------------------

## Claim Line Details

<b>Labor</b>				
<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-95-01-00-000960	Free Standing Dinette Table - Top Only - Interior/Dinette/Replace/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2022-01-24 12:06:54 :: CHECK THE KITCHEN TABLE TOP THERE MIGHT BE A BIG SCRATCH ON IT AND THE TABLE HAS A BOW IN IT FOUND TABLE WITH SCRATCH AND BOW REPLACE THE TABLE			
	<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>	<b>\$45.00</b>
	<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>	<b>\$15.00</b>
	<b>Notes</b>			
	excessive time requested per job description.			
<b>Labor</b>				
<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	40-196-01-11-001306	LED Light - Electrical/12 Volt Interior/Replace/Electrical		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2022-01-24 12:09:01 :: LIGHT LENS MISSING ON LIGHT IN OUTSIDE KITCHEN NEED TO REPLACE THE LIGHT INSTALLED NEW LIGHT			
	<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>	<b>\$45.00</b>
	<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>	<b>\$30.00</b>
	<b>Notes</b>			
	excessive time requested per job description.			
<b>Labor</b>				
<b>Line# 3</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	RC-029-03-00-004110	21V828, 2021-646 - COOKTOP INVERTED FLAME - Recall/Stove/Install/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2022-01-24 12:10:13 :: RECALL 21V828 THE STOVE IS NOT ISOLATED FROM THE FURANCE RETURN AIR TOOK MICROWAVE OUT AND UNPLUGGED CUT PANEL TO FIT AND SCREWED IN AND SEALED,MOVED 110 OUTLET UP.REINSTALLED MICROWAVE.			
	<b>Model #</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>	<b>\$150.00</b>
	<b>Serial #</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>	<b>\$150.00</b>
	<b>Notes</b>			

<b>Submitted</b>	<b>Labor Amt</b>	\$240.00	<b>Approved</b>	<b>Labor Amt</b>	\$195.00
	<b>Parts &amp; Freight</b>	\$0.00		<b>Parts &amp; Freight</b>	\$0.00
	<b>Total</b>	<b>\$240.00</b>		<b>Total</b>	<b>\$195.00</b>

DEALER \_\_\_\_\_ DATE \_\_\_\_\_

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

**SIGNATURE**

All repairs described have been inspected and are satisfactory.