



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73039-1
Promised Date:
06 MAY 26

73039-1

WO #: 73039-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9679 2026 AVENGER
26DBS
Serial#: 942101
Chassis#: 5ZT2AVRB4TB942101
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 04 MAY 26
Time In:

Job #1 - Warranty

COMPLAINT: SLIDE INOP

CAUSE: Wire had short

CORRECTION: Unit came in and the slide out-not working I had to take the fuse panel off and run electrical tests. Then I pulled off the bottom panel from the under carriage and saw that the yellow wire had been rubbing the metal frame. I then cut the wires and ran some more test, It was the wire that I found. I then fixed wires with new butt connection , heat shrink tube and covered with black electrical tape. The slide out now works

Photos attached
Requesting 3hrs
RP 5/4/26

Labor

Job #	Description	Total
1	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #1:		0.00

Job #01 - Warranty

COMPLAINT: Floor tear
RP 5/5/26

Floor has a tear and nail sticking out of floor

CAUSE: possibly from slide out

CORRECTION: Requesting 8 hours for repair

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #01:				0.00

Job #02 - Warranty

COMPLAINT: CATCHERS INSTALLED IMPROPERLY

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

CAUSE: Catchers installed improperly at the factory and was bent out of place.

CORRECTION: Need to order a new couch remove relocate and reinstall new couch and make any adjustments needed to cabinet door for proper function. After installation test all functions. Request .5

Labor		
Job #	Description	Total
02	Kitchen door catch	N/C
Subtotal for Job #02:		0.00

Job #02-1 - Warranty

COMPLAINT: Kitchen latch

RP 5/5/26

Kitchen door under sink has a broken catch on it
 Needs to be replaced

CAUSE: Catch is installed improperly and was bent out of shape

CORRECTION: Catch needs to be removed relocated and reinstalled in a proper position. After installation will need to Make any necessary adjustments to the cabinet door and test function. Order and replace door catch see attached photos. Request .5

Labor		
Job #	Description	Total
02-1	Under kitchen cabinet catch	N/C
Subtotal for Job #02-1:		0.00

Job #03-1 - Warranty

COMPLAINT: Scuffs of floor

RP 5/5/26

Floor has giant scuffs on it
 Photos attached

CAUSE: Unknown

CORRECTION: Linoleum needs to be taken off with the adhesive
 . The lower cabinets on the floor taken off and out of the unit with their screws . The diner section with the table mount and chairs with all of the screws need to be removed and taken out of the unit.
 Glue needs to be added to the floor and new linoleum needs to be rolled and flattened so not bubbles are trapped under the new linoleum. All of the cabinets, chairs, screws and table need to be replaced and placed back to the factory location.
 Photos attached
 Request 10 hours

Labor		
Job #	Description	Total
03-1	Linoleum deep scratches	N/C
Subtotal for Job #03-1:		0.00

Job #04-1 - Warranty

COMPLAINT: Scratches outside

RP 5/5/26

Scratches on back passenger side under compartment

CAUSE: Unknown

CORRECTION: Scratch underneath rear passenger compartment approximately 3 inches long. Correction can be either repainted or touched up.
 Photos attached
 Required for touch up 1 hour
 Required for repaint corner 3 hours

W/O: 73039-1
Promised Date: 05 MAY 26

73039-1

Customer #: 1000
MYERS "RV" CENTER,
INC.,

1000

Labor		
Job #	Description	Total
04-1	Scratches under rear outside compartment	N/C
Subtotal for Job #04-1:		0.00

Job #05 - Warranty

COMPLAINT: Outside refer

Rp5/5/26

Outside refer in compartment isnt attached needs to be rescued and repaired if anymoe damaged. Floor holding refer needs new screws to be attached

Requesting 1 hour

CAUSE: UNKNOWN

CORRECTION:

Outside refer in compartment isnt attached needs to be rescued and repaired if anymoe damaged. Floor holding refer needs new screws to be attached

Requesting 1 hour

Labor		
Job #	Description	Total
05	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #05:		0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 11 May 2026