

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66382

Completed : 28 FEB 22 Customer : 49672 - RIVERSIDE RV - 260-499-4578
Licence # : Invoice # :
Stock No : 11176 Description : 2022 TT RIVERSIDE RV RETRO 171DRD
Tag : Date In : 25 JAN 22 Mileage : 0
Author : BH Promised :
Location : 0309 CHECK PREAUTH Date Sched :
Serial# : 59CCC451XNL005014 Chassis# : 59CCC451XNL005014
Warr. Date : Cust PO# :
Print Date : 08 MAR 22

Job # Description JOB INFORMATION Type Bill To

BUNK Transferred to BAS*66453 on 04 FEB 22 Estimate I PDI PRE-D
 amount was 0.00 PRE DELIVERY INSPECTION NEW
 BUNKHOUSE
1 COMPLAINT: BEDROOM WALL IA PUSHING OUT AND SEAM W 49672 RIVER
 TAPE IS BUNCHED UP
 CAUSE: wall in bedroom is pushing out and seam
 tape is bunched up in the middle
 CORRECTION: secured wall with brad nails. took a
 piece of a trim to match and added to
 cover seam tape.
2 COMPLAINT: ENTRY DOOR HANDLE ONE OF THE HOLES FOR W 49672 RIVER
 THE MOUNTING SCREW BROKE NEEDS REPLACED
 CAUSE: door handle is broken and needs
 replaced. mounting bracket is broken
 CORRECTION: removed old handle. installed new
 handle
3 COMPLAINT: SEALER AROUND WINDOW ON DRIVERS SIDE W 49672 RIVER
 CAUSE: sealer around window on drivers side
 CORRECTION: removed with mineral spirits
4 COMPLAINT: SCREEN DOOR LATCH NEEDS ADJUSTED W 49672 RIVER
 CAUSE: screen door latch isnt catching door
 CORRECTION: moved latch to catch main door
5 COMPLAINT: ENTRY DOOR IS HITTING THE FRAME W 49672 RIVER
 CAUSE: entry door is hitting the frame at the
 top left corner and is hitting latch
 plate.
 CORRECTION: took a hammer and moved latch plate over
 from door. took a block of wood and a
 hammer and pushed door frame "in" away
 from door.
6 COMPLAINT: CORNER TRIM UNDER RADIO IS DAMAGED AND W 49672 RIVER
 NEEDS PUTTY
 CAUSE: corner is damaged.
 CORRECTION: took putty and stain and applied to

Continued on page 2

Work Order : 66382

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
7       damaged area as needed.
    COMPLAINT:  THE BATHROOM DOOR HITS THE DOOR FRAME      W      49672  RIVER
    CAUSE:      door is hitting plastic frame.
    CORRECTION: took a screw and painted it black to
                match the trim. installed screw to hold
                frame in place
8       THE SHELF HOLDERS THAT ARE IN THE FREEZEER ARE      W      49672  RIVER
    BROKEN

```

```

*****
Job # Part No Description                PARTS                Bill to    Qty    Price    Total
*****
BUNKH 13034    55362 STD BATTERY BOX                I-PDI        0     13.99     0.00
2      08200    LOCK ASSEMBLY-BLAC                W-49672       1     22.51    22.51

```

```

*****
Job# Lab Code Description                LABOUR    Mech Bill to    Hrs    Rate    Total
*****
HOUSE Z990    MISC LABOUR CODE (EXTE ZMS I-PDI        0.00    130.00     0.00
HOUSE Z990    MISC LABOUR CODE (EXTE ZMS I-PDI        0.00    130.00     0.00
HOUSE Z990    MISC LABOUR CODE (EXTE ZMS I-PDI        0.00    130.00     0.00
HOUSE Z990    MISC LABOUR CODE (EXTE ZMS I-PDI        0.00    130.00     0.00
HOUSE Z990    MISC LABOUR CODE (EXTE ZMS I-PDI        0.00    130.00     0.00
1 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.00    150.00     0.00
1 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
2 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
3 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
4 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
5 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
6 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
7 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.20    150.00    30.00
8 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.00    150.00     0.00
8 Z990    MISC LABOUR CODE (EXTE ZMS W-49672       0.00    150.00     0.00

```

```

*****
Job # Excode    Description                EXTRAS                bill to    Qty    Price    Total
*****
HOUSE LPG      LP GAS                        I-PDI        0.00     3.99     0.00
HOUSE SS       SHOP SUPPLIES                I-PDI        0.00     0.00     0.00

```

```

*****
                        CUSTOMER COMMENTS
*****
BH IS TRYING TO GET RIVERSIDE TO FIX THE ISSUE  CHECK EMAILES
PER RIVERSIDE (I did email Furrion on the issue of the hardware
being broken for the shelves in the freezer. They denied this
claim. We are working with Furrion to get additional hardware for
that issue. We will get these out to you when they come in. )
BH SENT EMAIL TO GET A UPDATE ON THE FRIDGE

```

Continued on page 3

Work Order : 66382

BH SENT IN PREAUTH WAITING TO HEAR BACK

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	49672	22.51	210.00	0.00	0.00	0.00	232.51
	Totals	22.51	210.00	0.00	0.00	0.00	232.51