



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73507
 Promised Date:
 06 JUN 26



WO #: 73507 (Appointment Date: 06 JUN 2026 - Time: 09:15am)
 Customer Name: 61640 - GONZALEZ, AUBRY BREANN
 Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9646 2026 OPEN RANGE COLT 17BH
 Serial#: 58TBM0AJ3T7V53124 Date In: 06 JUN 26
 Chassis#: 58TBM0AJ3T7V53124 Time In:
 Miles/Hrs:
 Tag#: 7184
 Purchased Date: 18 MAY 26
 Warranty Date: 18 MAY 26

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES CEILING PANEL SOFT AT UPPER BUNK AREA

CAUSE: delamination

CORRECTION: Section of ceiling needs to be replaced with a 4 x 8 sheet of roof and make sure it is the same color and design. the lights need to come down the kitchen cabinets need to be unscrewed and removed in order to fit. The skylight has to be unscrewed and come off. The cabinet where the reefer and microwave has to be unscrewed and removed. The microwave and refrigerator has to be unscrewed and removed. The new sheet has to be cut to size and all holes for the lights and skylight have to be fitted a cut. The cabinet above the dinner table also needs to be unscrewed unscrewed and removed . Once the everything is cut to size everything needs to be screwed back into its factory location fitted and tested.

Photos attached
 4x8 sheet needs to be ordered
 Request 5 hours

Labor

Job #	Description	Total
1	REPAIR CEILING PANEL	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: CUSTOMER STATES WHILE COOKING AND PAN GETS HOT THE FLAME SHUTS DOWN

CAUSE: Unknown

CORRECTION: Tested leak test lp held at 8 lbs for 3 minutes. Cant repeat the problem. Stove is working fine.

Photos attached

Labor

Job #	Description	Total
2	STOVE	N/C

Customer #: 61640
 GONZALEZ, AUBRY
 BREANN



W/O: 73507
Promised Date: 06 JUN 26

Other Services

Code	Description	Qty	Price	Total
SS-1	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C
Subtotal for Job #2:				0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES DRIVER SIDE DUST CAP FELL OFF IN TRANSIT (GREASE ON WHEEL)

CAUSE: CS dust cover fell off

CORRECTION: Replaced new dust cover

Photos attached

.10HRS

Labor

Job #	Description	Total
3	BEARING DUST CAP INSTALL	N/C

Parts

Part #	Description	Qty	Price	Total
02823	BEARING DUST CAP W/ PLUG 2K & 3.5K AXLES	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

Customer #: 61640
GONZALEZ, AUBRY
BREANN

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 12 Jun 2026



Customer Work Order