



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$99.00

RO# : 40966 Tag# : SE569133

Check-in: Mon Jun 15, 2026 | 10:25 AM  
Ready for Pickup: Wed Jun 17, 2026 | 10:05 AM  
Promise Time: Sat Jun 20, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2025 Ram ProMaster  
Window Van  
3C6MRVUG5SE569133  
626 Mi In  
Stock #: 26-23

**Service Advisor**  
BONNIE SEEMANN  
bonnie

A.	MISCELLANEOUS	DEALER STATES INSIDE ON THE ROOF ON DRIVERS SIDE, THERE IS A LEAK AND STAINED THE CEILING.	Warranty Pay	\$99.00
----	---------------	--	--------------	---------

Job added by BONNIE SEEMANN on Mon Jun 15, 2026 | 10:25 AM

1. Improper windshield seal. Request .60hr for diag time. Windshield will have to be handled by specialist.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$99.00

Labor Cost: \$22.80

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
lafavet	-	0.44	0.6	0.6	\$99.00	\$22.80

1. Brought unit in and inspected windshield area for leaks. Found the headliner stuck to windshield sealant in the top corner near where staining is located. Carefully peeled back liner from sealant and inspected further. Could see what looked like debris or dirt in sealant. Sprayed windshield with water and went back in. Water was coming in at that exact spot. Took video of dripping. Will need windshield removed, resealed and reinstalled. Headliner will need replace or clean, if at all possible.

<b>Total Labor Sale</b>	<b>Total Labor Cost</b>	<b>Total Parts Sale</b>	<b>Total Parts Cost</b>
\$99.00	\$22.80	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$99.00

RO# : 40966 Tag# : SE569133

Check-in: Mon Jun 15, 2026 | 10:25 AM  
Ready for Pickup: Wed Jun 17, 2026 | 10:05 AM  
Promise Time: Sat Jun 20, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2025 Ram ProMaster  
Window Van  
3C6MRVUG5SE569133

**Service Advisor**  
BONNIE SEEMANN  
bonnie

Category	Sale	Cost
Labor	\$99.00	\$22.80
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$99.00</b>	<b>\$22.80</b>

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Jun 16, 2026	11:48 AM	12:14 PM	0.44 hrs	W	lafavet	0.6 hrs

Tag: Regular Hour Reason: -

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40966	LINK RV	\$99.00
57200	40966	LINK RV	-\$99.00
67200	40966	LINK RV	\$22.80
14400	lafavet	LINK RV	-\$22.80

