

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2664866
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC1TG815405
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16RBX-452
LINDA WHITE		DEALER RO #	73311
2028 DUKE CITY STREET SE		CLAIM START DATE	05/05/2026
Albuquerque, NM 87123		CLAIM END DATE	06/05/2026
USA			
Retail Date of Purchase	03/27/2026	WARRANTY EXPIRATION DATE	03/27/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-474-01-00-003344	Bracket - Interior/Appliance Securement/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-05 12:56:06 :: Complaint: Customer states refer is loose in cabinet Cause: Refer had no screws in factory locations Correction: Tech removed refer in order to see what was missing. Refer did not have top screws holding the refer in. Installed new screws in factory locations and secure refer down. Refer is installed correctly in its factory location.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00	
Serial#	Appr Hrs	0.50	Appr Labor Amt \$95.00	
	Notes			
	Authed. Closest code found to resecure refer			

Part

Line# 1	Item #	Description			
	USERPART	Screws			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$4.75	Sub Freight \$0.00		
	Appr Qty 1.00	Appr Dlr Price \$4.75	Appr Freight \$0.00		
	Notes				

Labor

Line# 2	Operation Code	Operational Description		
	30-100-24-00-001051	Cabinet - complete - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-05-05 13:03:31 :: Complaint: Panel and framing above refer is loose Cause: Refer was not secured and was hitting panel and frame Correction: Remove refer from factory location. Inspect panel and frame damage. New mails and screws were installed to area where panel and frame were loose and damaged. Panels and frame are installed and properly secured to proper location.			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$190.00	
Serial#	Appr Hrs	1.00	Appr Labor Amt \$190.00	
	Notes			
	Authed			

Part

Line# 1	Item #	Description			
	USERPART	Screws & nails			
	Model #	Serial #	Part tag		
	Sub Qty 1.00	Sub Dlr Price \$9.50	Sub Freight \$0.00		
	Appr Qty 1.00	Appr Dlr Price \$9.50	Appr Freight \$0.00		

Notes

Labor
Line# 3

Operation Code

70-170-01-00-002055

Operational Description

Furnace Return Air Grille - Appliances/Furnace (Suburban)/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-05-05 13:05:13 :: Complaint: Furnace grill is loose/screw is on dinette Cause: Screws are missing and the furnace grill is loose Correction: Adjusted furnace and installed new screws on both sides of furnace cover. Additional Note : stephanie@dealer-advisors.com, 2026-05-05 13:07:12 :: **this is not a replacement, just a resecuring**

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

Part

Line# 1

Item #

USERPART

Description

Screws

Model #

Serial #

Part tag

Sub Qty 1.00

Sub Dlr Price \$1.90

Sub Freight \$0.00

Appr Qty 1.00

Appr Dlr Price \$1.90

Appr Freight \$0.00

Notes

Submitted

Labor Amt	\$323.00
Parts & Freight	\$16.15
Total	\$339.15

Approved

Labor Amt	\$323.00
Parts & Freight	\$16.15
Total	\$339.15

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.