

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66398

Completed : 30 MAR 22 Customer : 49672 - RIVERSIDE RV - 260-499-4578
Licence # : Invoice # :
Stock No : 11196 Description : 2022 TT RIVERSIDE RV RETRO 171DRD
Tag : Date In : 27 JAN 22 Mileage : 0
Author : BH Promised : 31 MAR 22
Location : 0405 CHECK WORK Date Sched :
Serial# : 59CCC4519NL005120 Chassis# : 59CCC4519NL005120
Warr. Date : Cust PO# :
Print Date : 30 MAR 22

Job # Description JOB INFORMATION Type Bill To

BUNK Transferred to BAS*66516 on 16 FEB 22 Estimate I PDI PRE-D
 amount was 0.00 PRE DELIVERY INSPECTION NEW
 BUNKHOUSE
1 COMPLAINT: SEALER ON BACKSPLASH W 49672 RIVER
 CORRECTION: NEED TO REPLACE THE BACKSPLASH
2 COMPLAINT: SEALER ON WINDOW W 49672 RIVER
 CAUSE: SEALER ON WINDOW
 CORRECTION: TOOK A RAG AND MINERAL SPIRITS AND
 REMOVED SEALER FROM WINDOW
3 COMPLAINT: SCREEN DOOR HITTING FRAME W 49672 RIVER
 CAUSE: door is hitting the frame
 CORRECTION: took a block of wood and moved the top
 left corner of the frame in so the door
 would stop hitting.
4 COMPLAINT: 7 WAY DAMAGED W 49672 RIVER
 CAUSE: 7 way was dragged on the ground and is
 damaged.
 CORRECTION: removed plate from junction box. removed
 nuts from wire terminals. removed 7 way
 wires. 7 way wires were installed first
 in this box so i had to remove all other
 wires and then remove 7 way wires.
 removed damaged plug. installed wire
 terminals on new 7 way plug. secured 7
 way to frame, secured 7 way to junction
 box. installed 7 way wires and all other
 wires. tightened down nuts. tested 7 way
 and lights. secured panel to junction
 box
5 COMPLAINT: FRESH FILL LINE RUNS UPWARD W 49672 RIVER
 CAUSE: FILL LINE FOR FRESH TANK IS RUNNING UP
 AND IS CAUSING WATER TO BACKFEED AND NOT
 FILL THE TANK.
 CORRECTION: REMOVED FILL LINE. REROUTED UNDER OTHER

Continued on page 2

Work Order : 66398

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                WATER LINES THAT RAN THROUGH THE
                                COMPARTMENT AND FLOOR. CUT EXCESS LINE.
                                SECURED LINE TO INLET.
6      COMPLAINT:  FRIDGE DOOR HITTING ON THE BOTTOM          W      49672  RIVER
      CAUSE:       SCREWS ON BOTTOM OF FRAME WERE INSTALLED
                                AT AN AGLE AND WERE HITTING THE BOTTOM
                                OF THE DOOR WHEN SHUTTING
      CORRECTION:  REMOVED ORIGINAL SCREWS. INSTALLED NEW
                                SCREWS FLUSH WITH BOTTOM
7      COMPLAINT:  THE WINDOW OVER THE DINETTE WILL NOT      W      49672  RIVER
      CAUSE:       WINDOW BLIND WONT STAY UP.
      CORRECTION:  ADJUSTED TENSION ON BLIND CHORD SO IT
                                WILL STAY UP.
8      THE INSIDE SHROUD FOR THE ROOF VENT IS CRACKED.      W      49672  RIVER

```

```

*****
Job # Part No Description          PARTS          Bill to      Qty      Price      Total
*****
BUNKH 13034   55362 STD BATTERY          I-PDI          0       13.99       0.00
BUNKH 24181   -50 RV ANTI-FREEZE          I-PDI          0        4.99       0.00
4      19430   10' MOLDED 7-WAY CORD          W-49672        1       49.67      49.67

```

```

*****
Job# Lab Code Description          LABOUR      Mech Bill to      Hrs      Rate      Total
*****
HOUSE Z990      MISC LABOUR CODE (EXTE          I-PDI          0.00     130.00       0.00
HOUSE Z990      MISC LABOUR CODE (EXTE ZMS      I-PDI          0.00     130.00       0.00
HOUSE Z990      MISC LABOUR CODE (EXTE ZMS      I-PDI          0.00     130.00       0.00
HOUSE Z990      MISC LABOUR CODE (EXTE ZMS      I-PDI          0.00     130.00       0.00
HOUSE Z990      MISC LABOUR CODE (EXTE ZMS      I-PDI          0.00     130.00       0.00
1 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        1.00     150.00      150.00
1 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.00     150.00       0.00
1 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.00     150.00       0.00
2 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.10     150.00       15.00
3 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.20     150.00       30.00
4 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.50     150.00       75.00
5 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.40     150.00       60.00
6 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.10     150.00       15.00
7 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.20     150.00       30.00
8 Z990          MISC LABOUR CODE (EXTE ZMS      W-49672        0.30     150.00       45.00
1 Z990          MISC LABOUR CODE (EXTE          W-49672        0.00     150.00       0.00

```

```

*****
Job # Excode   Description          EXTRAS          bill to      Qty      Price      Total
*****
HOUSE SS       SHOP SUPPLIES          I-PDI          0.00       0.00       0.00
HOUSE LP20     20 LB. LP CYLINDER      I-PDI          0.00      14.00       0.00

```

Continued on page 3

Work Order : 66398

CUSTOMER COMMENTS*****
CEILING GARNISH IN BACKROOM AND WALL PANEL IN RED TRAILER...NO
CHARGE.... 3-21-22...CAM
ORDERED PARTS PER BEN.
BH GOT OK TO ORDER
BH SENT IN PREAUTH WAITING TO HEAR BACK

BILLINGS SUMMARY*****
Type Bill Id Parts Labour Sublet Extras Tax Total

W 49672 49.67 420.00 0.00 0.00 0.00 469.67

 Totals 49.67 420.00 0.00 0.00 0.00 469.67
