



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 27215



WO #: 27215 (Appointment Date: 03 JUN 2026 - Time: 09:00am)

Customer: 91575 - MASON, DENNIS
 Address: 1774 LITTLE DRY RUN RD
 BUTLER, TN
 37640

Home Phone: 423-291-0137

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10836

Stock Desc: (10836) 2024 FOREST RIVER
 ROCKWOOD ULTRA 2608BS

Model: 2608BS

Serial #: 4X4TRLB27RZ189705

Chassis #:

Mileage:

Key #: 5000

Req'n #: 62736

License #:

Trim:

Purchase Date: 01 JUL 24

Date In: 27 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 17 JUN 26

Warr. Date: 01 JUL 24

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES BATHROOM FAUCET WAS CRACKED IN BATHROOM, AND WAS REPLACED HERE LAST YEAR. THE NEW ONE HAS SPLIT - MAY HAVE EXT SERV PLAN - PLEASE CHECK AND ADVISE

CAUSE: BATHROOM FAUCET HAS CRACKED AND LEAKING
 MANUF DEFECT ON FAUCET

CORRECTION: REPLACE FAUCET
 LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED FAUCET	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100481342	FAUCET	1.00	28.41	28.41

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
FRT	FREIGHT ON PARTS	1.00	26.68	26.68

Subtotal for Job #1: 142.59

Job #2 - External

COMPLAINT: CUSTOMER STATES PLUMBING UNDER SINK IS NOW LEAKING - MAY HAVE EXT SERV PLAN - PLEASE CHECK AND ADVISE

CORRECTION: NO ISSUES FOUND

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: CUSTOMER STATES BACK SLIDE HAS A PLACE ON IT - STATE THIS HAPPENED LAST TIME UNIT WAS HERE AND DOOR WAS LEFT WHEN THEY PUT THE SLIDE IN - MAY HAVE EXT SERV PLAN - PLEASE CHECK AND ADVISE

CORRECTION: COMPLETED

Customer #: 91575
 MASON, DENNIS



Parts

Part #	Description	Qty	Price	Total
F100332931	INTERCHANGEABLE LEG	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	N/C	N/C
SHP	SHIPPING/FREIGHT FEE	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: CUSTOMER STATES ON THE PANEL INSIDE THE WATER HEATER IS SHOWING DSI FAULT - MAY HAVE EXT SERV PLAN - PLEASE CHECK AND ADVISE

CORRECTION: WORKS AS DESIGNED

Subtotal for Job #4: 0.00

Job #5 - External

COMPLAINT: TOILET LEAKING

CORRECTION: NO ISSUES FOUND

Subtotal for Job #5: 0.00

Customer Work Order

Parts Total:	28.41
Labour Total:	87.50
Sublet Total:	0.00
Extras Total:	26.68
WORK ORDER TOTAL:	142.59

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 17 Jun 2026

Customer Signature : _____



Customer #: 91575
MASON, DENNIS

