

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Expired
MYERS RV CENTER INC		CLAIM	2359114
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVRB3TB940730
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT26DBS
RAMON RAMOS		DEALER RO #	71948
12308 CLOUDVIEW AVE NE		CLAIM START DATE	07/08/2025
Albuquerque, NM 87123		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	07/03/2025	WARRANTY EXPIRATION DATE	07/03/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-103-01-00-001119	Carpet - Interior/Flooring/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : lars9707caf@gmail.com, 2025-07-08 11:58:04 :: Hole in the carpet in front of the couch / Carpet torn appears to have had something sharp drug across / Replace carpet , 4 foot by 13 feet, Everything in the slide out will have to be removed, the couch, the built in dinette, the table . The walls will have to be taken apart removing all trim , paneling and 3 windows in order to remove and replace the carpet. Then all items listed will have to be reinstalled. 16 hours for this job			
Model#	Dlr Sub Hrs	16.00	Sub Labor Amt	\$2,960.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00
	Notes			
	We will need a picture of the complete slide out. CB I will get those over to you. Thanks! In feedback to add pictures. CB PICTURES PHOTOS ARE NOW ATTACHED Time requested is very excessive. Please have your tech provide a timed breakdown. CB this "carpet" is tucked underneath the walls of the slide room, in order to replace the carpet per manufacturing standards that the trailer was built to, the windows have to come out in order to pull the wall panels out, to tuck the "carpet" under the panels. if you have a way you would like to have this replaced, please recommend. Sent video you can pull the room and tilt slide out on the back and remove the floor and replace with new carpet. Hey Richard can you send the video to: b.parrott@myersrv.com Sent b.parrott@myersrv.com link to video. I also have attached the link below as well. https://www.youtube.com/watch?v=QgHqioGQ0p4&list=PLt-6vUiQanUVEq5sVKGoMxAKN76QHrONx&index=20			

Labor

Line# 2	Operation Code	Operational Description		
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : lars9707caf@gmail.com, 2025-07-08 12:10:21 :: Large chip out of the trim on the slide above the couch / Gouged trim / Trim board will have to be replaced 5 1/2 inches by 13 feet. Remove old trim and end caps. Nail new trim board and putty nail holes replace end caps. 2 hours for this job			
Model#	Dlr Sub Hrs	2.00	Sub Labor Amt	\$370.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$92.50
	Notes			
	Excessive amount requested. Authorized for .5 hour to R/R fascia board. Corner blocks do not			

need replaced. NVCB CB

**Labor
Line# 3**

Operation Code

20-46-01-00-000721

Operational Description

Window - Exterior/Windows/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : lars9707caf@gmail.com, 2025-07-08 12:17:27 :: Screw hole and hammer mark on kitchen window outside / Struck with a hammer and screw ran all the way thru window frame / Remove old window and replace with new window 2 hours for this job

Model#

Dlr Sub Hrs

2.00

Sub Labor Amt \$370.00

Serial#

Appr Hrs

1.00

Appr Labor Amt \$185.00

Notes

Excessive amount requested. Authorized for 1 hour to R/R window. NVCB CB

Submitted

Labor Amt \$3,700.00
Parts & Freight \$0.00
Total \$3,700.00

Approved

Labor Amt \$277.50
Parts & Freight \$0.00
Total \$277.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.