

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2664866
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC1TG815405
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16RBX-452
LINDA WHITE		DEALER RO #	73311
2028 DUKE CITY STREET SE		CLAIM START DATE	05/05/2026
Albuquerque, NM 87123		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	03/27/2026	WARRANTY EXPIRATION DATE	03/27/2027

Claim Line Details

Labor

Line# 1

Operation Code	30-474-01-00-003344	Operational Description
		Bracket - Interior/Appliance Securement/Replace/No Tread Code
Complaint, Cause, Correction	Original Note : stephanie@dealer-advisors.com, 2026-05-05 12:56:06 :: Complaint: Customer states refer is loose in cabinet Cause: Refer had no screws in factory locations Correction: Tech removed refer in order to see what was missing. Refer did not have top screws holding the refer in. Installed new screws in factory locations and secure refer down. Refer is installed correctly in its factory location.	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.50	\$95.00
Serial#	Appr Hrs	Appr Labor Amt
	0.50	\$95.00
Notes	Authed. Closest code found to resecure refer	

Labor

Line# 2

Operation Code	30-100-24-00-001051	Operational Description
		Cabinet - complete - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction	Original Note : stephanie@dealer-advisors.com, 2026-05-05 13:03:31 :: Complaint: Panel and framing above refer is loose Cause: Refer was not secured and was hitting panel and frame Correction: Remove refer from factory location. Inspect panel and frame damage. New mails and screws were installed to area where panel and frame were loose and damaged. Panels and frame are installed and properly secured to proper location.	
Model#	Dlr Sub Hrs	Sub Labor Amt
	1.00	\$190.00
Serial#	Appr Hrs	Appr Labor Amt
	1.00	\$190.00
Notes	Authed	

Labor

Line# 3

Operation Code	70-170-01-00-002055	Operational Description
		Furnace Return Air Grille - Appliances/Furnace (Suburban)/Replace/No Tread Code
Complaint, Cause, Correction	Original Note : stephanie@dealer-advisors.com, 2026-05-05 13:05:13 :: Complaint: Furnace grill is loose/screw is on dinette Cause: Screws are missing and the furnace grill is loose Correction: Adjusted furnace and installed new screws on both sides of furnace cover. Additional Note : stephanie@dealer-advisors.com, 2026-05-05 13:07:12 :: **this is not a replacement, just a resecurng**	
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$38.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$38.00
Notes		

Submitted	Labor Amt	\$323.00
	Parts & Freight	\$0.00
	Total	\$323.00

Approved	Labor Amt	\$323.00
	Parts & Freight	\$0.00
	Total	\$323.00

DEALER _____ **DATE** _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE

All repairs described have been inspected and are satisfactory.