



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73311
 Promised Date:
 no MAY 26



WO #: 73311

Customer Name: 60740 - WHITE, LINDA Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9632 2026 AVENGER
 16RBX
 Serial#: 5ZT2AVEC1TG815405 Date In: 04 MAY 26
 Chassis#: 5ZT2AVEC1TG815405 Time In:
 Miles/Hrs:
 Tag#: STORAGE 3
 Purchased Date: 27 MAR 26
 Warranty Date: 27 MAR 26

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES REFER LOOSE IN CABINET / CUSTOMER PUSHED BACK IN

CAUSE: refer had no screws in factory locations

CORRECTION: Tech removed refer in order see what was missing Refer didnt have top screws holding the refer in.

Tech installed new screws in factory locations and secured refer down.

Refer is installed correctly in its factory location

Photos attached before and after

.50HRS

Labor

Job #	Description	Total
1	SECURE REFER	N/C
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES PANEL AND FRAMING ABOVE REFER LOOSE

CAUSE: Lose Refer banging panel and frame

CORRECTION: RP 5/4/26

Tech removed refer from factory location

Tech looked at panel and frame damage

New nails and screws were installed to area where panel and frame was loose and damaged.

Panels and frame are installed and properly secured to factory location.

Photos attached

1.00HRS

Labor

Job #	Description	Total
2	SECURE PANEL AND FRAMING	N/C
Subtotal for Job #2:		0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES FURNACE GRILLE LOOSE /SCREW ON DINETTE SEAT.

Customer #: 60740
 WHITE, LINDA



CAUSE: Screws missing and loose furnace grill

CORRECTION: RP 5/4/26

Upon inspection the furnace cover was loose and missing screws.

Tech adjusted the furnace

Tech installed new screws on both sides of furnace cover.

Furnace cover is tightly secured

Photos attached

.10HRS

Labor

Job #	Description	Total
3	FURNACE GRILLE	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Internal

COMPLAINT: COURTESY INPSECTION FOR WARRANTY ISSUES AND SYSTEMS CHECK

CORRECTION: RP 5/5/26

Upon Courtesy inspection I fill the freshwater tank. Tech didnt find any other problems with the unit other than that was stated before in line 1 line 2 and line 3.

Tech ran the AC and the furnace to make sure everything is correctly running.

Chris the shop manager inspected for quality control and everythings good to go insecure.

Labor

Job #	Description	Total
4	INSPECTION	N/C

Subtotal for Job #4: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 05 May 2026

W/O: 73311
Promised Date: 08 MAY 26



Customer #: 60740
WHITE, LINDA

