



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 66399
Promised Date: 31 MAR 22

CUSTOMER WORK ORDER

WO #: 66399

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0414 FIND OUT IF THIS CAN
BE CLOSED

Stock #: 11197

Stock Desc: 2022 TT RIVERSIDE RV
RETRO 171DRD

Chassis #: 59CCC4515NL005115

Serial #: 59CCC4515NL005115

Mileage: 0

Licence:

Invoice #:

Date In: 27 JAN 22

Promised: 31 MAR 22

Date Sched:

Completed: 14 APR 22

Warr. Date:

Job #BUNKHOUSE - Internal

COMPLAINT: Transferred to BAS*66891 on 25 MAR 22

Estimate amount was 0.00

PRE DELIVERY INSPECTION NEW BUNKHOUSE

CORRECTION: installed gas line and regulator ,checked brakes, water system, plumbing, electrical, appliances, brakes lights, lug nuts, filled lp, ran lp leak test, installed battery box, installed lp tank holder, winterized, drained tanks, documented serial numbers,

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #1 - Warranty

COMPLAINT: FRESH TANK FILL LINE RUNS UPWARD NEED TO REROUTE LINE

CAUSE: FILL HOSE NEEDS MOVED SO IT HAS A "SLOPE DOWN INTI THE TANK

CORRECTION: VERY DIFFICULT TO ACCESS HOSE CLAMP. REMOVED HOSE CLAMP. RE ROUTED HOSE. CUT TO LENGTH. SECURED HOSE WITH CLAMP. FILLED TANK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	75.00

Subtotal for Job #1: 75.00

Job #2 - Internal

COMPLAINT: GAP BETWEEN WALL AND FRIDGE

CAUSE: need to install trim to hide gap



Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: cut trim to length, installed trim to wall.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #2:			0.00

Job #3 - Warranty

COMPLAINT: CORNER OF SHOWER NEEDS SEALED

CAUSE: corner of shower needs sealed with silicone

CORRECTION: sealed with silicone

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00
Subtotal for Job #3:			30.00

Job #4 - Warranty

COMPLAINT: SEAM TAPE IN BATHROOM IS COMING OFF

CAUSE: seam tape was coming off.

CORRECTION: applied adhesive to seam tape.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Subtotal for Job #4:			30.00

Job #5 - Warranty

COMPLAINT: WALL IN BEDROOM IS PUSHING OUT ON THE DRIVERS SIDE

CAUSE: WALL IS PUSHING OUT

CORRECTION: SECURED WITH STAPLES AND FILLED HOLES WITH PUTTY

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00
Subtotal for Job #5:			30.00

Job #6 - Warranty

COMPLAINT: WALL IN BEDROOM ON PASSENGER SIDE IS PUSHING OUT

CAUSE: WALL PUSHING OUT

CORRECTION: SECURED WITH BRAD NAILS AND FILLED WITH PUTTY

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	30.00
Subtotal for Job #6:			30.00

Job #7 - Warranty

COMPLAINT: CABINET ABOVE SINK. TRIM NEEDS SECURED



CAUSE: trim was loose inside the cabinet

CORRECTION: secured trim with brad nails.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00
Subtotal for Job #7:			15.00

Job #8 - Warranty

DENT IN A HUBCAP ON THE OFF DOOR SIDE

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00
Subtotal for Job #8:			15.00

Job #9 - Warranty

COMPLAINT: PASSANGER SIDE BRAKE LIGHT NOT WORKING

CAUSE: brake light isnt working. removed cover for 7 way junction box. tested each lead for lights. all leads have power. traced wires to the back. tested each wire and all have power. removed light from the camper to test light. noticed the wire was not secure to the light.

CORRECTION: cut wire and re crimped to light. light is now working. installed cover plate for the 7way. installed light. sealed light with silicone.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	105.00
Subtotal for Job #9:			105.00

Parts Total:	0.00
Labour Total:	330.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	330.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Apr 2022

W/O: 66399
Promised Date: 31 MAR 22



Customer #: 1000
BASDEN'S AMERICAN RV,

