

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	921530
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
		VIN	5ZT2CKEC3NY022192
EVANSVILLE, IN 47725		CHASSIS VIN	
USA		MILEAGE	0
		SITE/WAREHOUSE	017 / 017D
Labor rate:	\$150.00	ITEM #	CKTR16PF-D
OWNER INFORMATION		DEALER RO #	66430
		CLAIM START DATE	02/07/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	70-469-01-00-001800	Operational Description	Refrigerator Door - Appliances/Refrigerator (Furrion)/Replace/No Tread Code	
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2022-02-07 12:53:43 :: OUTSIDE FRIDGE HAS A DENT IN THE DOOR NEED TO REPLACE THE FRIDGE DOOR				
Model #	HME02GGMBBB	Dlr Sub Hrs	0.30	Sub Labor Amt \$45.00
Serial #	RS022662	Appr Hrs	0.30	Appr Labor Amt \$45.00

Notes

Labor

Line# 2

Operation Code	20-66-19-00-000664	Operational Description	Entry Door - RV - Exterior/Entry Doors/Reseal/No Tread Code	
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2022-02-07 12:56:17 :: ENTRY DOOR HAS GAPS IN THE SEALANT SEALED ALL GAPS AROUND DOOR.				
Model #		Dlr Sub Hrs	0.20	Sub Labor Amt \$30.00
Serial #		Appr Hrs	0.20	Appr Labor Amt \$30.00

Notes

Labor

Line# 3

Operation Code	10-7-02-00-000141	Operational Description	Entry Step - Frame & Chassis/Manual Entry Step/Adjust/No Tread Code	
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2022-02-07 12:57:36 :: STEP HITS THE DOOR WHEN IT IS PULLED OUT ADJUSTED LATCH.				
Model #		Dlr Sub Hrs	0.10	Sub Labor Amt \$15.00
Serial #		Appr Hrs	0.10	Appr Labor Amt \$15.00

Notes

Labor

Line# 4

Operation Code	40-197-01-11-001419	Operational Description	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/Electrical	
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2022-02-07 12:58:30 :: OUTSIDE REC COVER IS NOT LINED UP WITH OUTLET CUT SILICONE AROUND COVER AND PULLED OFF AND RESET PLUG AND PUT				

COVER BACK ON AND SEALED WITH SILICONE.

Model #	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00
Serial #	Appr Hrs	0.30	Appr Labor Amt	\$45.00

Notes

Submitted	Labor Amt	\$135.00	Approved	Labor Amt	\$135.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$135.00		Total	\$135.00

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	