

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66457

Completed : 17 FEB 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10646 Description : 2022 TT COACHMEN CATALINA 263BHCKL
Tag : Date In : 07 FEB 22 Mileage :
Author : BH Promised : 12 FEB 22
Location : 0212 SENT IN PREAUTDate Sched :
Serial# : 5ZT2CARB3NU039464 Chassis# : 5ZT2CARB3NU039464
Warr. Date : 12 FEB 22 Cust PO# :
Print Date : 17 FEB 22

Job # Description JOB INFORMATION Type Bill To

FPDI COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS I PDI PRE-D
 CORRECTION: FINAL DONE.
EQUA COMPLAINT: INSTALL 1000# EQUALIZER HITCH I DO DEALE
 CAUSE: install hitch
 CORRECTION: installed hitch and adjusted as needed.
1 RV CARE / WASH KIT I PDI PRE-D
DELU DELUXE STARTER KIT I DO DEALE
WALK COMPLAINT: WALK THRU I PDI PRE-D
 CAUSE: WALK THROUGH
 CORRECTION: WALK THROUGH WENT GOOD
2 COMPLAINT: THE FURNACE WONT LIGHT W 10024 FORES
 CORRECTION: removed acess panel to furnance and
 removed panel from back of furnance and
 found parts of blower wheel in
 furnance,cut wires and removed screws
 and lp line and pulled out furnance,took
 furnance out of cage and removed casing
 for blower motor and fan and found blade
 got into sail switch and fan blade blew
 apart,replaced sail switch and legenthed
 wires to hook back up,to short to
 reach,waiting on blower wheel to put
 back together.INSTALLED BLOWER WHEEL AND
 HOOKED ALL WIRES BACK TOGETHER,AND
 INSTALLED HOUSING BACK TOGETHER,HOOKED
 ALL WIRES IN CAMPER TO FURNANCE AND
 CSREWED DOWN FURNANCEAND HOOKED UP LP
 LINE,TESTED AND IT WORKS
 FINE.INSTALLED OUT SIDE VENT AND
 SEALED.
3 COMPLAINT: THE ENTERTAINMENT DOOR BELOW THE TV IS I PDI PRE-D
 RIPPED OFF
 CORRECTION: replaced 4 screws in hinges

Continued on page 2

Work Order : 66457

```

*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
FPDIN DC-24 ADVANCE GROUP 24 D I-PDI 1 131.99 131.99
EQUAL 710831 EQUALIZER 1000#/10 I-DO 1 677.95 677.95
1 6505 RV CLEANING KIT - I-PDI 1 149.99 149.99
DELUX 44722 DELUXE STARTER KIT I-DO 1 137.99 137.99
2 BRV232261 SAIL SWITCH/SUBURBAN FURNAC W-10024 1 7.34 7.34
2 69-7047 350206 SUBURBAN BLOWER WHEEL W-10024 1 13.94 13.94

```

```

*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
DINTT PDINTT PDI - NEW TRAVEL TRAIL DGH I-PDI 1.76 150.00 264.00
DINTT PDINTT PDI - NEW TRAVEL TRAIL DGH I-PDI 0.24 150.00 36.00
R1000 Z990 MISC LABOUR CODE (EXTE I-DO 0.00 105.00 0.00
R1000 Z990 MISC LABOUR CODE (EXTE DGH I-DO 0.42 105.00 44.10
R1000 Z990 MISC LABOUR CODE (EXTE ZMS I-DO 1.08 150.00 162.00
WALK Z990 MISC LABOUR CODE (EXTE BAP I-PDI 1.50 150.00 225.00
2 Z990 MISC LABOUR CODE (EXTE DGH W-10024 1.00 150.00 150.00
2 Z990 MISC LABOUR CODE (EXTE DGH W-10024 1.00 150.00 150.00
3 Z990 MISC LABOUR CODE (EXTE DGH I-PDI 0.20 150.00 30.00

```

```

*****
Job # Excode Description EXTRAS bill to Qty Price Total
*****
R1000 SS SHOP SUPPLIES I-DO 0.00 11.25 0.00
2 FRT UPS-BLOWER WHEEL W-10024 1.00 7.98 7.98

```

CUSTOMER COMMENTS

```

*****
BH SENT IN PREAUTH 2-10
BLOWER WHEEL GIVEN TO DONNIE 2-10-22...CAM
BLOWER WHEEL ORDERED 2-8-22 2ND DAY AIR...CAM
RV WASH KIT IN JOSH'S OFFICE (SO IT DOESN'T FREEZE)..CAM 2-8-22
DELUXE KIT IN SHOP ON "B" SIDE 2-7-22...CAM

```

BILLINGS SUMMARY

```

*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
I DO 815.94 206.10 0.00 0.00 0.00 1,022.04
I PDI 281.98 555.00 0.00 0.00 0.00 836.98
W 10024 21.28 300.00 0.00 7.98 0.00 329.26

Totals 1119.20 1061.10 0.00 7.98 0.00 2,188.28

```