



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73140
 Promised Date:
 06 MAY 26



WO #: 73140 (Appointment Date: 02 APR 2026 - Time: 08:45am)
 Customer Name: 59966 - HUMPHREYS, CHRISTOPHER SEAN
 Completed Date: 30 MAY 26
 Invoice#: _____
 Author: ADVISOR
 Stock Desc: 9374 2024 R-POD RP-196
 Serial#: 5ZT2RPJC1RV025973
 Chassis#: 5ZT2RPJC1RV025973
 Miles/Hrs: _____
 Tag#: 7142
 Purchased Date: 29 MAY 25
 Warranty Date: 29 MAY 25
 Date In: 02 APR 26
 Time In: _____

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES WHEN USING BLACK WATER FLUSH WATER COMES OUT FROM UNDER UNIT **UNDER WHERE THE BLACK TANK FLUSH IS & OTHER SIDE UNDER WHERE THE WASTE WATER HOLDING TANK IS**

CAUSE: 1001 CUSTOMER REQUESTED That we check out the black tank flush and black tank because it sometimes is leaking on the grey tank side

CORRECTION: Filled up black tank all the way until standing water in toilet. filling up gray tank currently to check for leaks. Determined that shower is leaking at the drain underneath the shower. Upon taking it to be dumped a bunch of water built up on the under belly padding from the leaking shower. Directly in the spot that the customer stated. Need one hour to repair.

4/14/26 - Went to go and replace the plumbers putty around the shower drain when I removed it I noticed that somebody have used decor to seal it up. After I cleaned it up around the drain, noticed a notch around the drain circle ..see picture. Going to rebuild to the best of my ability, so customer can use unit. Recommend the shower pan be replaced it will eventually leak, if not replaced. Got the shower drain to stop leaking but noticed when the shower is shooting to the back wall it drips from the back of the panel in between the wall and the pan underneath. Further recommending for pan replacement. The drain will need to be removed. The shower curtain strips will need to be removed the enclosure will need to be removed. The plumbing for the shower handles that leads to the showerhead will need to be removed. In the pictures there are some measurements and potentially the tag model number. Requesting 4 hours for install.

- 5/1/26
- Remove showerhead and hose and shower valve assembly 1.0
- Removed shower curtain slide holder .10
- Need to pop all the rivets out of the shower walls .50
- Need to remove drain assembly underneath shower pan .20
- Need to remove the shower enclosure completely out of the bathroom with very limited space.50
- Need to remove attachment points around shower pan .50
- Need to install new pan and secure two new attachment points .50
- Need to Install P-trap and correctly attach all plumbing points .50
- Need to bring back in the shower enclosure and position and attach correctly .50
- Need to re-install shower curtain rod .15
- Need to reconnect shower valve and handle system and verify plumbing integrity 1.0
- Will need to caulk and seal the enclosure to manufacturer specifications .50
- Will need to perform drop test to ensure no leaks. .20.

Labor

Job #	Description	Total
1	BLACK TANK FLUSH	190.00

Customer #: 59966
 HUMPHREYS,
 CHRISTOPHER SEAN





Parts				
Part #	Description	Qty	Price	Total
F100075932	SHOWER, PAN W/ RH DRAIN 24" X 32" - WHITE	1.00	68.52	68.52
16131	HXTAPEFOAM DS TAPE 1/8 THICK	30.00	0.35	10.50

Other Services				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	60.87	60.87

Subtotal for Job #1: 329.89

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES WHEN USING BLACK WATER FLUSH WATER ALSO COMES OUT FROM ONE OF THE WALLS INSIDE UNIT **KIND OF WHERE THE WALL BEGINS TO GO ROUND - MAY BE COMING OUT AT THE TOILET AREA**

CAUSE: 1004 ISSUE CAUSED BY the Back flow preventer check valve for the Black tank flush is leaking profusely

CORRECTION: The check valve needs to be replaced. Model 571 125 psi half inch. We will need 30 minutes to replace it

4-14-26 Removed old backflow preventer for installed new one hung it so that its facing the correct direction with a bracket underneath the sink hooked up a hose to check for leaks turned on full pressure flushing black tank no leaks

Labor			Total
Job #	Description		
2	BLACK TANK FLUSH		66.50

Parts				
Part #	Description	Qty	Price	Total
31023	SHOWER DRAIN STRAINER - 2" DRAIN OPENING	1.00	16.68	16.68
55-5289	FRESH WATER VACUUM BREAKER	1.00	10.93	10.93

Subtotal for Job #2: 94.11

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES CABINET DOOR ABOVE KITCHEN SINK IS BROKE **HINGE BROKE OFF DOOR**

CAUSE: 1004 ISSUE CAUSED BY The bouncing of the trailer has caused the screw holes to strip it has been tried to hook in the same place multiple times

CORRECTION: I would recommend moving the piston to the other side of the door using proper screws to secure

4-14-26 I moved the piston to the other side and readjusted the hinges so that the door was straight checked function moving up and down correctly filled holes from previous orientation

Labor			Total
Job #	Description		
3	CABINET DOOR		28.50

Subtotal for Job #3: 28.50

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES REFRIGERATOR IS NOT STAYING COLD ON LP - WORKS WHEN ON SHORE POWER

CAUSE: 1004 ISSUE CAUSED BY Propane regulator





CORRECTION: I was able to get the fridge to ignite and start cooling from a different job line I determined that the regulator needs to be replaced should be the cause of the issue in LP mode need 30 minutes to verify that its working after regulator is replaced. When I was first trying to start it up in propane mode there was a red light indicating that propane mode was not working but then it started after I attempted to relight pilot second time. Continuing fridge diagnostic upon the replacement of the propane regulator

5/29/26

After replacing the propane regulator I put the refrigerator in propane mode it turned on and is cooling the fridge

Labor		
Job #	Description	Total
4	REFRIGERATOR DIAGNOSTIC TIME	95.00

Parts				
Part #	Description	Qty	Price	Total
06-0450	2-STAGE 90 DEG REGULATOR	1.00	53.07	53.07
Subtotal for Job #4:				148.07

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES STOVE STOP BURNERS NOT STAYING LIT

CAUSE: 1004 ISSUE CAUSED BY Regulator is running at 9 needs to be 11

CORRECTION: Regulator needs to be replaced on unit 30 minutes . Single stage, Tried to get a regulator from the store we need to order the part model number is in the pictures. Continuing further diagnostics win regulator is replaced.

5/29/26 after replacing the propane regulator the stove has a perfect contant running flame

Labor		
Job #	Description	Total
5	STOVE TOP DIAGNOSE	95.00
Subtotal for Job #5:		95.00

Job #NOTE - External

CUSTOMER STATES UNIT IS NOT WINTERIZED & WHEN HE PICKED UNIT UP HE NEVER RECEIVED HOSE FOR VACUUM

Subtotal for Job #NOTE: 0.00

Job #6 - Warranty

COMPLAINT: REMOVE & REPLACE SHOWER PAN

REFERS TO LINE #1

CAUSE: Shower pan has a piece missing from around the drian. Resulting in it needing to be replaced .

CORRECTION: Removed all parts around shower removed shower enclosure removed pan. installed new pan. And existing enclosure. Caulked it and waiting for silicone to dry to leak test the unit

Labor		
Job #	Description	Total
6	SHOWER STALL R&R	570.00

Parts				
Part #	Description	Qty	Price	Total
F100075932	SHOWER, PAN W/ RH DRAIN 24" X 32" - WHITE	1.00	68.52	68.52
8112	CHRISTMAS TREE CLIP	10.00	0.05	0.50



Subtotal for Job #6: 639.02

W/O: 73140
Promised Date: 26 MAY 26

Parts Total:	228.72
Labour Total:	1,045.00
Sublet Total:	0.00
Extras Total:	60.87
WORK ORDER TOTAL:	1,334.59

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 30 May 2026

Customer Signature : _____



Customer Work Order

Customer #: 59966
HUMPHREYS,
CHRISTOPHER SEAN

