



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73353
Promised Date:
13 MAY 26



WO #: 73353 (Appointment Date: 13 MAY 2026 - Time: 08:15am)
Customer Name: 60016 - HOCKETT,
DEWEY ALAN

Completed Date:
Invoice#:
Author: BRIAN
Stock Desc: 9484 2025 AVENGER 16BH
Serial#: 5ZT2AVECXSB939684
Chassis#: 5ZT2AVECXSB939684
Miles/Hrs:
Tag#: 7159
Purchased Date: 27 JUN 25
Warranty Date: 27 JUN 25

Date In: 13 MAY 26
Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES REFRIGERATOR WILL NOT GET BELOW 50 DEGREES WITH FOOD OR DRINKS INSIDE / it said 40 degrees but when you add groceries etc, then it would be 53, or 58 up to 63. ive lost alot of food, milk

CAUSE: DEFECTIVE REFER

CORRECTION: TESTED AS PER CHECK SHEET. THE REFER DOES NOT SEEM TO KEEP UP. THE REFER WILL NEED TO BE REPLACED.
2.00HRS

Labor

Job #	Description	Total
1	REFRIGERATOR DIAGNOSTIC TIME	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Internal

COMPLAINT: CUSTOMER STATES HOLDING TANKS ALWAYS SHOW 3/4 FULL

CAUSE: 1001 CUSTOMER REQUESTED we diagnose why the black tank always says 3/4 full

CORRECTION: I dumped both tanks and the black still said 3/4 full. I ran water for a couple minutes through the toilet.. then I got a spray attachment and hooked it to the hose and blasted all the walls inside the tank and cleaned up the material stuck all over the sensor.. then tank started to read correct ..then I filled the black tank all the way up and did a 1 big final flush . System working proeprly

Labor

Job #	Description	Total
2	MONITOR PANEL DIAGNOSE	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Customer #: 60016
HOCKETT, DEWEY ALAN



W/O: 73353
Promised Date: 15 MAY 26



Customer #: 60016
HOCKETT, DEWEY ALAN



Job #3 - External

COMPLAINT: CUSTOMER STATES EXTERIOR SHOWER DOOR BROKE

CAUSE: Customer requested we replace the exterior shower door

CORRECTION: Relayed to parts to order new door

Labor

Job #	Description	Total
3	EXTERIOR SHOWER	1.95

Subtotal for Job #3: 1.95

Parts Total: 0.00
Labour Total: 1.95
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.15
WORK ORDER TOTAL: 2.10

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 26 May 2026

Customer Signature : _____

