

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66476
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11087 - 2022 CATALINA 283RKSLE 5ZT2CATB5NX025377

VIN: 5ZT2CATB5NX025377 HIN:

SER#: 5ZT2CATB5NX025377

Mileage: 0

Work Order Comp: 12 MAR 22

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 09 FEB 22

Inv #: 373799

WO # Job # Description JOB INFORMATION

66476 2 THE FIREPLACE REMOTE CONTROL IS MISSING. THIS WAS NOTED ON
 DELIVERY
 NO LABOR
 PUT IN CAMPER

66476 3 THE BEDROOM DOOR HAS CHUNK OUT OF EDGE AND SCRATCHES BY THE KNOB
 THE BEDROOM DOOR HAS A CHUNK OUT OF EDGE AND SCRATCHES BY THE
 KNOB.
 Moved unit into shop from sales lot. Removed damaged bedroom
 door. Uncrated new door and checked for damage. None, door ok.
 Transferred door knob and hinges from old door to new door.
 Mounted new door to door frame. Checked for alignment to
 closure. OK.

66476 6 KITCHEN FAUCET IS LEAKING WHERE THE NECK MEETS THE BASE AND
 RUNNING DOWN THE FAUCET AND UNDER THE SINK.
 KITCHEN FAUCET IS LEAKING WHERE THE NECK MEETS THE BASE AND
 RUNNING DOWN THE FAUCET AND UNDER THE SINK.
 Disconnected water lines. Removed damaged kitchen faucet from
 sink. Mounted new kitchen faucet to sink. Water lines built in
 to faucet are too short to reach water line connections under
 sink. Made up two hoses to connect faucet lines to supply lines.
 Fittings on new faucet do not have enough threads to be able to
 tighten fittings to keep from leaking. Installed 12" flexible
 water lines that have shorter threads allowing fitting to be
 tightened securely. Leak test all fittings with system

Claim : 66476

 WO # Job # Description JOB INFORMATION

 antifreeze. No leaks at all fittings. Moved unit back to sales lot.

66476 1 TV WONT PICK UP ANY CHANNELS
 TV WILL NOT PICK-UP CHANNELS.
 Living room TV will not pick up any channels. Test TV connected in front bedroom picks up 12 channels. Test TV will not pick up channels at outside antenna port. Removed antenna booster from wall behind living room tv. Checked coax from booster to TV. Coax checked ok. Removed booster from wall. Found all coax connectors were loose. Removed outside Cable/Satelite from wall. Found bad coax connector. Cut off connector and installed a new connector. This coax goes to sat terminal on booster and is not for connecting a tv to it. Remounted outside connector and relabeled "Satellite" only. Added label to "Cable" connector on other side of unit. Trimmed booster mounting hole bigger to get all coax wires back in wall hole. Rechecked living room tv after booster was remounted in wall. TV ok.

66476 5 FURNACE WILL NOT RUN. NO FAN NO HEAT
 FURNACE WILL NOT RUN. NO FAN NO HEAT.
 Furnace does not come on and run when thermostat call for heat. Checked fuse in fuse panel. Fuse good. Removed thermostat from wall. Checked all connections. All good and correct. Removed louver panel and furnace cover. Checked switch next to control board. Switch in "ON" position. Furnace still does not run. Checked power wires to furnace. No power to furnace. Checked all wiring at furnace. Power wire for furnace are connected to thermostat wires. Cut wires and connected to correct hot and ground. Turned od thermostat. Furnace now comes "ON" and runs. Replaced cover and louver panel. Remounted thermostat on wall.

 Part No Job# Description PARTS Qty Price Total

 F100307355 2 FIRELACE REMOTE 1.00 18.50 18.50
 F100282648 3 DOOR, BATH 1-3/8X2 1.00 42.50 42.50
 F100200276 6 FAUCET, KITCHEN SS 1.00 53.13 53.13
 C01292790 6 1/2" BLUE PVC HIGH 2.00 0.33 0.66
 C01292791 6 1/2" PVC RED HOSE 2.00 0.33 0.66
 72-0818 6 1/2" MPT TO 1/2" P 2.00 2.40 4.80
 681487 6 1/2" BARB X 1/2 FP 2.00 2.70 5.40
 5778 6 SINK RISER LINE 2.00 8.14 16.28
 88-8708 6 ELL 1/2 X 1/2 2.00 1.73 3.46

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00

Claim : 66476

```

*****
Lab Code  Job#  Description      LABOUR
*****
Z990      3  MISC LABOUR CODE (EXTERNAL)      Hrs      Rate      Total
Z990      6  MISC LABOUR CODE (EXTERNAL)      0.50     150.00     75.00
Z990      6  MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      6  MISC LABOUR CODE (EXTERNAL)      0.50     150.00     75.00
Z990      6  MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      1  MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      5  MISC LABOUR CODE (EXTERNAL)      1.00     150.00    150.00
Z990      5  MISC LABOUR CODE (EXTERNAL)      1.00     150.00    150.00
*****

```

```

*****
Excode    Job#  Description      EXTRAS
*****
FRT       2  UPS-REMOTE      Qty      Price      Total
FRT       3  FREIGHT & CRATE - BEDROOM DOOR      1.00     15.70     15.70
FRT       6  UPS-FAUCET      1.00    130.89    130.89
FRT       6  UPS-FAUCET      1.00     15.68     15.68
*****

```

```

Parts Total:      145.39
Labour Total:     450.00
Sublet Total:      0.00
Extras Total:     162.27

```

>>>> Claim Total: 757.66

Customer Signature: _____

Date: _____