

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66476

Completed : 12 MAR 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 11087 Description : 2022 TT COACHMEN CATALINA 283RKSLE
Tag : Date In : 09 FEB 22 Mileage : 0
Author : BH Promised : 26 MAR 22
Location : 0307 CHECK STATUS WDate Sched :
Serial# : 5ZT2CATB5NX025377 Chassis# : 5ZT2CATB5NX025377
Warr. Date : Cust PO# :
Print Date : 12 MAR 22

Job # Description JOB INFORMATION Type Bill To

PDIN COMPLAINT: Transferred to BAS*66570 on 22 FEB 22 I PDI PRE-D
 Estimate amount was 0.00 PDI - NEW
 TRAVEL TRAILER
 CAUSE: PDINTT - PDI NEW TRAVEL TRAILER.
 CORRECTION: Cleaned snow & ice from top of slideout.
 Moved unit into shop from sales lot.
 Purged and filled LP tanks. Relocated
 Brake-away switch to clear future hitch
 brackets. Installed battery box.
 Checked all exterior lights and brakes.
 Checked lug nuts and set tire pressure
 at 65 psi. Operated all manual stab
 jacks. Checked entrance door and all
 compartment doors. Checked awning and
 roof. Checked power cord. Checked all
 interior lights. Checked converter
 output. Removed packing from all
 appliances. Checked all electrical
 outlets and GFCI outlets. Checked all
 USB outlets. Checked all cabinets and
 drawers. Checked all windows and
 blinds. Recorded all serial numbers and
 took pictures. Filled fresh water tank.
 Flushed all antifreeze from all water
 lines and faucets. Checked all water
 lines and faucets for leaks. Opened
 by-pass on water heater and filled.
 Purged all air from water lines. Filled
 all holding tanks and checked monitor
 panel. Performed LP drop test and set
 LP pressure at 11 in.wc. Replaced
 broken sewer cap. Applied all company
 decals. Retracted all stab jacks.
 Moved unit back to sales lot.

Continued on page 2

Work Order : 66476

```

*****
Job #  Description                               JOB INFORMATION                               Type Bill To
*****
1      COMPLAINT:  TV WONT PICK UP ANY CHANNELS                                     W      10024  FORES
      CAUSE:       TV WILL NOT PICK-UP CHANNELS.~
      CORRECTION:  Living room TV will not pick up any
                    channels.  Test TV connected in front
                    bedroom picks up 12 channels.  Test TV
                    will not pick up channels at outside
                    antenna port.  Removed antenna booster
                    from wall behind living room tv.
                    Checked coax from booster to TV.  Coax
                    checked ok.  Removed booster from wall.
                    Found all coax connectors were loose.
                    Removed outside Cable/Satelite from
                    wall.  Found bad coax connector.  Cut
                    off connector and installed a new
                    connector.  This coax goes to sat
                    terminal on booster and is not for
                    connecting a tv to it.  Remounted
                    outside connector and relabeled
                    "Satellite" only.  Added label to
                    "Cable" connector on other side of unit.
                    Trimmed booster mounting hole bigger to
                    get all coax wires back in wall hole.
                    Rechecked living room tv after booster
                    was remounted in wall.  TV ok.
2      COMPLAINT:  THE FIREPLACE REMOTE CONTROL IS MISSING. W      10024  FORES
      CAUSE:       THIS WAS NOTED ON DELIVERY
      CORRECTION:  NO LABOR
3      COMPLAINT:  PUT IN CAMPER
      COMPLAINT:  THE BEDROOM DOOR HAS CHUNK OUT OF EDGE W      10024  FORES
                    AND SCRATCHES BY THE KNOB
      CAUSE:       THE BEDROOM DOOR HAS A CHUNK OUT OF EDGE
                    AND SCRATCHES BY THE KNOB.
      CORRECTION:  Moved unit into shop from sales lot.
                    Removed damaged bedroom door.  Uncrated
                    new door and checked for damage.  None,
                    door ok.  Transferred door knob and
                    hinges from old door to new door.
                    Mounted new door to door frame.  Checked
                    for alignment to closure.  OK.
4      COMPLAINT:  NO PRESSURE AT HOT SIDE OF FAUCET EXCEPT I  SPN      SALES
                    KITCHEN FAUCET ABOVE WATER HEATER
      CAUSE:       NO PRESSURE AT HOT SIDE OF FAUCETS
                    EXCEPT KITCHEN FAUCET ABOVE WATER
                    HEATER.
      CORRECTION:  Checked all faucets, Kitchen, bathroom
                    sink and shower and outside shower.
                    Only faucet with pressure on hot side is
                    kitchen sink, which is above water
                    heater and a direct line to faucet.

```

Continued on page 3

Work Order : 66476

- 5 COMPLAINT: FURNACE WILL NOT RUN. NO FAN NO HEAT W 10024 FORES
 CAUSE: FURNACE WILL NOT RUN. NO FAN NO HEAT.
 CORRECTION: Furnace does not come on and run when thermostat call for heat. Checked fuse in fuse panel. Fuse good. Removed thermostat from wall. Checked all connections. All good and correct. Removed louver panel and furnace cover. Checked switch next to control board. Switch in "ON" position. Furnace still does not run. Checked power wires to furnace. No power to furnace. Checked all wiring at furnace. Power wire for furnace are connected to thermostat wires. Cut wires and connected to correct hot and ground. Turned od thermostat. Furnace now comes "ON" and runs. Replaced cover and louver panel. Remounted thermostat on wall.
- 6 COMPLAINT: KITCHEN FAUCET IS LEAKING WHERE THE W 10024 FORES
 NECK MEETS THE BASE AND RUNNING DOWN THE FAUCET AND UNDER THE SINK.
 CAUSE: KITCHEN FAUCET IS LEAKING WHERE THE NECK MEETS THE BASE AND RUNNING DOWN THE FAUCET AND UNDER THE SINK.
 CORRECTION: Disconnected water lines. Removed damaged kitchen faucet from sink. Mounted new kitchen faucet to sink. Water lines built in to faucet are too short to reach water line connections under sink. Made up two hoses to connect faucet lines to supply lines. Fittings on new faucet do not have enough threads to be able to tighten fittings to keep from leaking. Installed 12" flexible water lines that have shorter threads allowing fitting to be tightened securely. Leak test all fittings with system antifreeze. No leaks at all fittings. Moved unit back to sales lot.
- WINT Transferred to BAS*66570 on 22 FEB 22 Estimate I PDI PRE-D
 amount was 0.00 WINTERIZE UNIT AND DRAIN HOLDING
 TANKS. ***INCLUDES 2 GALLONS OF ANTI-FREEZE*** UNITS
 WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA
 DE-WINTERIZATION IS NOT INCLUDED

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
PDINT	13034	55362 STD BATTERY		I-PDI	0	10.95	0.00
PDINT	24181	-50 RV ANTI-FREEZE		I-PDI	0	4.99	0.00

Continued on page 4

Work Order : 66476

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
PDINT	39462	SEWER CAP W/ HOSE CONNECTI	I-PDI		0	4.99	0.00
2	F100307355	FIRELACE REMOTE	W-10024		1	18.50	18.50
3	F100282648	DOOR, BATH 1-3/8X2	W-10024		1	42.50	42.50
6	F100200276	FAUCET, KITCHEN SS	W-10024		1	53.13	53.13
6	C01292790	1/2" BLUE PVC HIGH	W-10024		2	0.33	0.66
6	C01292791	1/2" PVC RED HOSE	W-10024		2	0.33	0.66
6	72-0818	1/2" MPT TO 1/2" P	W-10024		2	2.40	4.80
6	681487	1/2" BARB X 1/2 FP	W-10024		2	2.70	5.40
6	5778	SINK RISER LINE	W-10024		2	8.14	16.28
6	88-8708	ELL 1/2 X 1/2	W-10024		2	1.73	3.46
WINT	24181	-50 RV ANTI-FREEZE GALLON	I-PDI		0	4.49	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
DINTT	Z991	MISC LABOUR CODE (INTE	DKM	I-PDI		0.00	150.00	0.00
1	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		1.00	150.00	150.00
2	Z990	MISC LABOUR CODE (EXTE		W-10024		0.00	150.00	0.00
3	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.50	150.00	75.00
4	Z990	MISC LABOUR CODE (EXTE		I-SPN		0.00	25.00	0.00
4	Z990	MISC LABOUR CODE (EXTE	DKM	I-SPN		0.22	25.00	5.50
5	Z990	MISC LABOUR CODE (EXTE	DKM	I-SPN		0.41	25.00	10.25
6	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		1.00	150.00	150.00
6	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.00	150.00	0.00
6	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.50	150.00	75.00
6	Z990	MISC LABOUR CODE (EXTE	DKM	W-10024		0.00	150.00	0.00
INTER	Z990	WINTERIZE UNIT	DKM	I-PDI		0.00	130.00	0.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
DINTT	SS	SHOP SUPPLIES		I-PDI	0.00	35.00	0.00
DINTT	LPGI	LP - UNIT SALES		I-PDI	0.00	3.99	0.00
2	FRT	UPS-REMOTE		W-10024	1.00	15.70	15.70
3	FRT	FREIGHT & CRATE - BEDROOM		W-10024	1.00	130.89	130.89
6	FRT	UPS-FAUCET		W-10024	1.00	15.68	15.68
INTER	SS	SHOP SUPPLIES		I-PDI	0.00	9.70	0.00

Continued on page 5

Work Order : 66476

CUSTOMER COMMENTS*****
BW TOOK PARTS FROM BACK ROOM TO DKM ON 03/01 @ 3:00PM. DOOR IS STILL IN
1AFIREPLACE REMOTE IS IN BACKROOM 2-28-22...CAM
BEDROOM DOOR IN SHOP 1A 2-25-22....CAM
FAUCET ARRIVED IN BACKROOM 2-16-22...CAM
ORDER PARTS PER BEN. 2-14-22
BH GAVE PARTS SHEET TO MATT
BH GOT APPROVAL
BH SENT IN PREAUTH*****
BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	SPN	0.00	15.75	0.00	0.00	0.00	15.75
W	10024	145.39	450.00	0.00	162.27	0.00	757.66
	Totals	145.39	465.75	0.00	162.27	0.00	773.41