



Pre-Authorization

Pre-Authorization number

88

(PA03987995)

PREAUTH965

Reference no.26977

Status

Approved

Servicing Dealer 8140

Name Tri-AM RV Center of East TN

Address 1202 Idell Rd
Bulls Gap, TN 37711

VIN 4YDTBLL22TD431682

Retail sold on

Root		Approved			Actual		Base	
Operation Description		Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
3103202B	Drawer - Replace	0	0.6	0.3		1	0.2	Complaint: The second drawer down from top to the left of entry is damaged and rough Cause: Noted on DAF, wood damaged when built Correction: Remove drawer and guides, replace with new drawer and reinstall guides then test drawer
3104106B	Overhead Cabinet - Stile	0	0.5	0.5		1	0.5	KRV-Approved to replace face only. Complaint: Cabinetry above second drawer in kitchen is damaged Cause: Wood is rough and looks damaged on cabinetry door, noted on DAF Correction: Remove the damaged cabinetry stile and replace with new
3100806A	Cabinet Door - Repair	0	0.4	0.3		1	0.2	Complaint: Top cabinet door 1st on left at entry door has a defective area Cause: Damaged at factory install, noted on DAF Correction: Smooth area on cabinet door, fill, color blend area
3100808B	Cabinet Door - Replace	0	0.5	0.3		1	0.2	Complaint: Second cabinet door at entry is cracked Cause: Noted on DAF Correction: Remove damaged cabinet door and the hardware, replace cabinet door with new one and reinstall hardware
3202008A	Panel - Interior Wall - Repair	0	0.4	0.3		1	0.1	Complaint: Left side of slide out fascia is scratched and paint faded in spots Cause: Noted on DAF Correction: Fill, color, and blend areas

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.

Root		Approved Actual				Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	
3200808A	Door - Interior Sliding - Repair	0	0.4	0.3		1	0.2	Complaint: Bathroom door from the living area has scratched paint in several areas Cause: Noted on DAF Correction: Fill, color, and blend areas
Pre-Authorization number: PREAUTH96588				2				