

6/8/20

Job #4 - WarrantyCOMPLAINT: CUSTOMER STATES LOVE SEAT IS MOVING
IT NEEDS TO BE SCREWED DOWN - P

CAUSE: VERIFIED LOVE SEAT IS MOVING

CORRECTION: NEED TO ADD LEG LOCK BOLTS
LABOR .40**Job #5 - External**

CUSTOMER REQUESTING TO HAVE A

Job #6 - WarrantyCOMPLAINT: CUSTOMER STATES HEARD NOISE
RIGHT INSIDE THE DOOR. STATES IT
PLEASE CHECK AND ADVISE

CORRECTION: TECH COULD NOT VERIFY

13.84 on Batt

Batt 1+2 = 13.84

Slide in 10.8

Slide out 12.8

Awning in 13.6

⑤
(Hrs 30 Amp
Breakers)
no Fuse② 24 Series
Batteries

Comments



Sort by ▾

feedback:

Feedback06/05/2026mpegan@forestriverinc.comHello, please provide photo of the unity board. Also, we will need the following diag questions answered, these are needed for the vendor's review. Thank you. Voltage Questions - Unity Board 1. What is the voltage at the Unity X270D for BATT 1 & BATT 2? (two readings at the Unity board) 2. What is the voltage at the RV battery (what type of battery)? 3. What is the voltage underload for RET at the 30amp REV PINs where the slide is wired to? 4. What is the voltage underload for EXT at the 30amp REV PINs where the slide is wired to? 5. Do the BATT 1 and BATT 2 wires each have a 30amp In-line fuse OR wired to a 30amp fuse at the breaker/short stop?

SD Reply



AO **Ashlee Olsen**
1:06 PM, Jun 5

Page 1 • submitted PA#2700388

SD Join the conversation

