

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66534
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11088 - 2022 CATALINA 343BH7SLE 5ZT2CAZB3NX025451
VIN: 5ZT2CAZB3NX025451 HIN:

SER#: 5ZT2CAZB3NX025451

Mileage: 0

Auth. No:

Warr. Date:

Work Order Comp: 10 MAR 22

Dealer #:

Work Order Date: 17 FEB 22

Inv #: 373724

WO # Job # Description JOB INFORMATION *****

66534 1 OUTSIDE KITCHEN SINK MISSING DRAIN PLUG
INSTALLED SINK BASKET

66534 2 BUNK SLIDE OUT HITTING SLIDING DOOR
BUNK SLIDE HITTING SLIDING DOOR.
When bunk slide comes in it is hitting sliding door. Roller
track is coming loose from ceiling. Added extra screws in
ceiling track to secure to ceiling. Door came loose from track
rollers. Reattached door to track rollers. Adjusted height of
door to align with opposite wall when closed. Top slide facia
hits door when closing slide out. Top facia board too long and
needs to be cut off. Cut off 1/2 inch of right end of eacia
board for clearance.

66534 3 TV WON'T PICK UP CHANNELS
TV WON'T PICK UP CHANNELS.
Searched for channels. Could not find any. Checked coax from
booster to TV. Found a Bad connection at TV end. Straightened
center coax. Reinstalled coax at TV. Now picks up channels.

66534 4 TV BOOSTER WIRES PULLED OUT OF BACK OF BOOSTER
TV BOOSTER WIRES PULLED OUT OF BACK OF BOOSTER.
TV Booster not working. Removed from wall. Found power wires
pulled out of terminal on back of booster. Remoived broken
terminal. Attached new terminal to two power wires. Reconnected
to back of TV booster. Remounted booster in wall. Relabeled

Claim : 66534

 WO # Job # Description JOB INFORMATION

outside coax connectors. Door side outlet is for "SATELLITE"
 only , not cable/satellite. Roadside coax connector was not
 labeled. Added "CABLE" label.

 Part No Job# Description PARTS Qty Price Total

 JRP95045 1 95045 WHITE THREAD 1.00 1.81 1.81

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.40 150.00 60.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00

Parts Total: 1.81
 Labour Total: 135.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 136.81

Customer Signature: _____

Date: _____