

Claim Response

Claim: C3016425

Non-Warranty Goodwill Adjustment

Last Modified bystutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3016425	66536	2/17/2022	2/21/2022	4YDT28B20K3249188		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	7/13/2019

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved
5121839											
Component Model: 6020		Component Serial Number: N 18 23									
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved

5122839

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: LP RECALL 21-414 Cause: FALLS UNDER RECALL Correction: remove recalled lp regulator installed new lp regulator and hoses (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet	71.41	Approved parts & subLet	71.41
Submitted labor & subLet	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	<u>146.41</u>	Total approved:	<u>146.41</u>