

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66536

Completed : 28 FEB 22 Customer : 1013 - KEYSTONE RV CO -
 Licence # : Invoice # :
 Stock No : Description : 2019 TT KEYSTONE HIDEOUT 28BHS
 Tag : Date In : 17 FEB 22 Mileage :
 Author : BJW Promised : 26 FEB 22
 Location : 0301 SEE IF W/O CAN Date Sched :
 Serial# : 4YDT28B20K3249188 Chassis# :
 Warr. Date : Cust PO# :
 Print Date : 28 FEB 22

```
*****
Job # Description JOB INFORMATION Type Bill To
*****
1 COMPLAINT: LP RECALL 21-414 W 1013 KEYST
  CAUSE: remove recalled lp regulator installed
        new lp regulator and hoses
*****
```

```
*****
Job # Part No Description PARTS Bill to Qty Price Total
*****
1 692585 REGULATOR - KIT - AUTO CHANGE W-1013 1 56.11 56.11
1 446897 12" LP HOSE PIGTAIL W-1013 2 7.65 15.30
*****
```

```
*****
Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total
*****
1 Z990 MISCELLANEOUS REPAIR SAR W-1013 0.50 150.00 75.00
*****
```

CUSTOMER COMMENTS

NOTE: BW CONTACTED KEYSTONE ON 02/28. KEYSTONE ADVISED THAT MANAGEMENT IS REVIEWING THE LP REGULATOR RECALL PARTS. KEYSTONE REP ADVISED BW THAT AS LONG AS WE HAVE THE OLD REGULATOR, WE CAN RELEASE THE RV AND THE CLAIM WILL PAY.

BH LEFT INFO FOR BW TO REACH OUT TO HIDEOUT AT KEYSTONE TO FIND OUT STATUS OF PRE AUTH AND WHY A DECISION IS TAKING SO LONG. BWW ATTEMPTED TO CALL ON SATURDAY FEB 26TH, BUT KEYSTONE WAS CLOSED.

BH SENT CLAIM

BILLINGS SUMMARY

```
*****
Type Bill Id Parts Labour Sublet Extras Tax Total
*****
W 1013 71.41 75.00 0.00 0.00 0.00 146.41
*****
```

Continued on page 2

Work Order : 66536

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	71.41	75.00	0.00	0.00	0.00	146.41
