

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66540

Completed : 28 FEB 22 Customer : 1013 - KEYSTONE RV CO -
Licence # : Invoice # :
Stock No : 10732 Description : 2022 TT KEYSTONE SPRINGDALE 295BH
Tag : Date In : 18 FEB 22 Mileage : 0
Author : BH Promised :
Location : 0301 NEED TO CLSOE Date Sched :
Serial# : 4YDTSGN28N3106774 Chassis# : 4YDTSGN28N3106774
Warr. Date : Cust PO# :
Print Date : 01 MAR 22

Job # Description JOB INFORMATION Type Bill To

PDIN PDI - NEW TRAVEL TRAILER I PDI PRE-D
1 COMPLAINT: THE SWITCH FOT THE REAR JACK WAS SMOKING W 1013 KEYST
WHEN USING IT
CAUSE: SCREW HOLDING SWITCH WAS TOUCHING THE
CIRCUT BREAKER
CORRECTION: PUT A SHORTER SCREW IN PLACE
2 COMPLAINT: THE FRONT STABILIZER JACKS ARE NOT W 1013 KEYST
WORKING AT ALL
CAUSE: JACK NOT WORKING
CORRECTION: CHECKED WIRES, SWITCH AND MOTOR THE
SWITCH WAS BAD ONLY WORKED ON THE
RETRACT BUT NOT EXTEND PUT IN PO FOR NEW
SWITCH
3 COMPLAINT: THE OUTDOOR GRILL IS MOUNTED FROM THE W 1013 KEYST
FACTORY IN A POSITION THAT WILL NOT
ALLOW THE LP HOSE TO REACH THE PORT.
CAUSE: GRILL HOSE WOULD NOT REACH PORT
CORRECTION: LINE HAD 2 HOSE SUPPORTS REMOVED THE ONE
THAT KEPT THE HOSE FROM REACHING THE
PORT TESTED THE CONNECTION TO MAKE SURE
IT WOULD REACH THE PORT
WINT WINTERIZE UNIT AND DRAIN HOLDING TANKS. ***INCLUDES I PDI PRE-D
2 GALLONS OF ANTI-FREEZE*** UNITS WITH WASHING
MACHINE OR ICEMAKER WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED

Job # Part No Description PARTS Bill to Qty Price Total

PDINT 13034 55362 STD BATTERY BOX I-PDI 1 10.95 10.95
WINT 24181 -50 RV ANTI-FREEZE GALLON I-PDI 0 4.49 0.00
2 387874 LIPPERT STAB JACK W-1013 1 30.98 30.98

Continued on page 2

Work Order : 66540

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to      Hrs      Rate      Total
*****
DINTT Z991      MISC LABOUR CODE (INTE SAR I-PDI      1.19     150.00     178.50
DINTT Z991      MISC LABOUR CODE (INTE SAR I-PDI      0.92     150.00     138.00
DINTT Z991      MISC LABOUR CODE (INTE SAR I-PDI      2.83     150.00     424.50
DINTT Z991      MISC LABOUR CODE (INTE SAR I-PDI      0.03     150.00       4.50
      1 Z990      MISCELLANEOUS REPAIR    SAR W-1013    1.03     150.00     154.50
      1 Z990      MISCELLANEOUS REPAIR    SAR W-1013    0.12     150.00      18.00
      2 Z990      MISCELLANEOUS REPAIR    SAR W-1013    0.38     150.00      57.00
      3 Z990      MISCELLANEOUS REPAIR    SAR W-1013    0.50     150.00      75.00
INTER Z990      WINTERIZE UNIT          SAR I-PDI      0.10     150.00      15.00
INTER Z990      WINTERIZE UNIT          SAR I-PDI      0.61     130.00      79.30
                        SAR I-PDI      0.39     130.00      50.70
*****

```

```

*****
Job #   Excode   Description      EXTRAS      bill to      Qty      Price      Total
*****
DINTT   SS       SHOP SUPPLIES          I-PDI      0.00      35.00       0.00
DINTT   LPGI      LP - UNIT SALES        I-PDI      8.00       3.99      31.92
INTER   SS       SHOP SUPPLIES          I-PDI      0.00       9.70       0.00
      2   FRT      UPS-JACK SWITCH        W-1013     1.00      11.76      11.76
*****

```

CUSTOMER COMMENTS

```

*****
JACK SWITCH IN BACKROOM 2-24-22...CAM
BH SENT IN PREAUTH
*****

```

BILLINGS SUMMARY

```

*****
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
I   PDI           10.95     1030.00      0.00      31.92      0.00     1,072.87
W   1013          30.98     165.00      0.00      11.76      0.00      207.74
      Totals      41.93     1195.00      0.00      43.68      0.00     1,280.61
*****

```