



Warranty Authorization Form

Date: 6/8/2026

Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

Ph. 715-325-5170
mail@greenwayrv.com

General Information

Pre-Auth #: 951892 Unit: 573FM4436M1117889
Series: Momentum Model: MT395MS-R-2021
Notes: JH 6/5 After Management Review: Approved. GD Case 1037742.
Status: Approved

Dealer Information

1127 Greenway RV Sales & Service
715-325-5170
mail@greenwayrv.com

Greenway RV Sales & Service
8220 State Hwy 13 South
Wisconsin Rapids, WI 54494

Requestor: iclaim services
Return Fax #: (715) 325-5577
Email: greenway@dealer-advisors.com

Operation Line 1

Flat Rate Code: 920017 VISUAL INSPECTION Wall Securement Campaign *Fault Code:* TSB
for 18k and up Momentum and Solitude Fifth Wheels

Serial #: *Model #:* *Notes:*

Problem: CS Campaign for wall securement. *Time Requested:* .1
Cause: Check front bedroom for movement on side walls. *Time Allowed:* .1
Remedy: Does show movement - visual inspection complete. *Sublet Repairs:* 0.00
Status: Approved

Operation Line 2

Flat Rate Code: 920018 - LAG BOLTS INSTALL - Wall Securement Campaign *Fault Code:* TSB
for 18k and up Momentum and Solitude Fifth Wheels

Serial #: *Model #:* *Notes:*

Problem: CS campaign for wall securement and door inspections. *Time Requested:* 5.9
Cause: Movement detected. *Time Allowed:* 5.9
Remedy: Consult GD for further instruction on how to proceed. Took pics of before lifting the front and after. Removed front fylon to check for cracks but found none. Had to remove front cap as well - will add a separate line item for this. 5.9 hours for lag bolts *Sublet Repairs:* 0.00
Status: Approved

Operation Line 3

Flat Rate Code: 530029 Fiberglass - Front Cap Repair

Fault Code: Damaged/Maintenance

Serial #:

Model #:

Notes:

Problem: CS campaign for wall securement and door inspections.

Time Requested: 2

Cause: Had to remove the front cap to check for any other repairs for this campaign.

Time Allowed: 2

Remedy: R&I front cap.

Sublet Repairs: 0.00

Status: Approved

Operation Line 4

Flat Rate Code: 920019 DOOR INSPECTION - Wall Securement Campaign *Fault Code:* TSB
for 18k and up Momentum and Solitude Fifth Wheels

Serial #:

Model #:

Notes:

Problem: CS campaign for wall securement and door inspection.

Time Requested: .1

Cause: Door inspection after lag bolt installation

Time Allowed: .1

Remedy: Inspect doors.

Sublet Repairs: 0.00

Status: Approved