

Claim Response

Claim: C3016713

Last Modified by ambri

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3016713	66544	2/19/2022	2/21/2022	4YDT29027MT432311		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	2/27/2021

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved
5121839											
Component Model: 6020 Component Serial Number: N 19 44											
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved

5121839

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory	21-414 Winn-Tec Complaint: LP REGULATOR SERVICE CAMPAIGN		0.50	0.50	75.00	0.00	1	0.50	Approved
Cause: UNIT NEEDS RECALL Correction: DID LP REGULATOR RECALL AND THEN CHECKED FOR LEAKS. DID LP DROP TEST AND SET THE REGULATOR TO THE RIGHT PRESSURE. (AP KBS)										

Submitted parts & subLet 71.41
Submitted labor & subLet 75.00
Submitted freight: 0.00
Tax: 0.00
Total Submitted: 146.41

Approved parts & subLet 71.41
Approved labor & subLet 75.00
Approved freight: 0.00
Tax: 0.00
Total approved: 146.41