

Claim Response

Claim: C3021034

Last Modified bystutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3021034	66551	2/21/2022	2/24/2022	4YDT28021M3109463		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	4/30/2021

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	446897	Hose - LP - 12" Pigtail	2.00	0.00	6.65	15.00	15.30	0.00	0.00	0.00	Approved
5121839											
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved

5121839
Component Model: 6020 **Component Serial Number:** N 20 32

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
7141442B	Safety Advisory	21-414 Winn-Tec Complaint: RECALL ON LP REGULATOR Cause: UNIT NEEDED TO THE RECALL Correction: REPLACED LP REGULATOR AND DID LP DROP TEST. HAD TO ADJUST THE REGULATOR. (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

Submitted parts & subLet	71.41	Approved parts & subLet	71.41
Submitted labor & subLet	75.00	Approved labor & subLet	75.00
Submitted freight:	0.00	Approved freight:	0.00
Tax:	0.00	Tax:	0.00
Total Submitted:	<u>146.41</u>	Total approved:	<u>146.41</u>