



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27176



WO #: 27176 (Appointment Date: 18 MAY 2026 - Time: 09:00am)

Customer: 91946 - WORKMAN, JACOB
Address: 288 EAGLE DR
MOORESBURG, TN
37811

Home Phone: (423) 259-0573

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 11045

Stock Desc: (11045) 2025 FOREST RIVER

ROCKWOOD ULTRA 2908RL

Model: 2908RL

Serial #: 4X4TRLL20SZ195673

Chassis #:

Mileage:

Key #: 6275

Req'n #:

License #:

Trim:

Purchase Date: 17 SEP 25

Date In: 18 MAY 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 17 SEP 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES AWNING WILL NOT RETRACT BY ITSELF

CAUSE: CONFIRMED POWER IS COMING IN BUT NO POWER COMES OUT
UNITY BOARD IS BAD

TECH HAS ATTACHED A PHOTO OF THE TAG ON THE AWNING ARM. TECH STATED UNTIL THE
BOARD IS REPLACED TO GET THE TAG ON THE FABRIC IT COULD CAUSE MORE DAMAGE TO THE
AWNING BY MANUALLY RETRACTING
A PHOTO CAN BE ATTACHED AFTER REPAIRS

CORRECTION: REPLACE THE UNITY BOARD AND RETEST
LABOR WITH DIAG 1.0

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - External

COMPLAINT: CUSTOMER STATES BATTERIES NOT STAYING CHARGED, CAN USE IT TO GET
SLIDEOUT OUT, BUT ONLY CLICKS WHEN TRYING TO RETRACT THEM

CORRECTION: TESTED AND NO ISSUES FOUND
BATTERY 1 READING 13.05
BATTERY 2 READING 13.07

Subtotal for Job #2: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Customer #: 91946
WORKMAN, JACOB



Subtotal for Job #ROOFINS: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES LOVE SEAT MOVES ALOT WHEN TRAVELING, HE WONDERS IF IT NEEDS TO BE SCREWED DOWN - PLEASE CHECK AND ADVISE

CAUSE: VERIFIED LOVE SEAT IS MOVING FREELY IN THE MIDDLE OF UNIT

CORRECTION: NEED TO ADD LEG LOCKERS TO HELP THE LOVE SEAT FROM SLIDING IN TRAVEL LABOR .40

Subtotal for Job #4: 0.00

Job #5 - External

CUSTOMER REQUESTING TO HAVE AUTO LEVELERS ADJUSTED

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES HE HAS NOTICED A FEW DROPS OF WATER ON THE CABINET RIGHT INSIDE THE DOOR. STATES IT DOSNT LOOK LIKE ITS COMING FROM THE CEILING. PLEASE CHECK AND ADVISE

CORRECTION: TECH COULD NOT VERIFY NO ISSUE AT THIS TIME

Subtotal for Job #6: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 05 Jun 2026

W/O: 27176



Customer #: 91946
WORKMAN, JACOB

