



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM

Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM

Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer KRISTIN DECAMP 1246850 +1 - (763) 923 - 4320 NOEMAIL@GMAIL.COM 33945 BLUEBERRY RD BAYFIELD, WI 54814	Pickup-Customer Same as Customer	Vehicle 2025 FOREST RIVER NIGHTFALL 4X4TNFA24SF002541 2 Mi In	Service Advisor KEVIN GOODIEL goodielk
	Billing-Customer Same as Customer		

A. MISCELLANEOUS	CUSTOMER STATES THE FRESH WATER TANK IS BULGING WHEN ADDING WATER AND CAUSED THE STRAPS TO FLEX TO THE AXLE. THE FLOOR BULGED UP AND TRIM AND STAPLES CAME OUT ABOVE TANKS NEXT TO FRIDGE, AND ALSO CAUSED THE SCREW TO COME OUT OF ONE OF THE FRIDGE SUPPORTS ON BOTTOM LEFT SCREW TO HOLD THE FRIDGE IN. I ALSO NOTICED IT LOOKS LIKE THERES NO OVER FLOW HOSE FOR THE 2 FRESH TANKS.. TOOK PICS	Warranty Pay	\$438.36
------------------	--	--------------	----------

Job added by KEVIN GOODIEL on Tue Jun 16, 2026 | 9:45 AM

1. No overflow drain

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$429.00

Labor Cost: \$62.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	2.6	0	2.6	\$0.00	\$62.40

1. lifted unit, removed gas lines, LED light, 3 metal braces, cut around waste pipes, removed portion of under belly, examined tanks. An inlet connection to a water hose was used as an overflow outlet. The valve inside was closing, giving pressure no place to go. Unscrewed connection after the tank started swelling. You could hear the air pressure escaping upon opening a crack in the line (video in ro) . Removed spring and valve from outlet, screwed overflow hose back in, further filled tanks, overflow hoses work now as they should. Squeegeed the floor after draining for safe work area. Tanks no longer overflow. Reattached underbelly, 3 metal brackets reinstalled, 2 in which had to be reset (before and after photos in ro) , gas lines, LED light, attached underbelly, sealed compromised rodent entry areas of underbelly, lowered unit, closed and cleaned up unit, put away lift, wrote report. Request 8.0 hours

Parts

Parts Total Sale Amount \$9.36

Parts Total Cost Amount \$7.20





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM

Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM

Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer
KRISTIN DECAMP
1246850
+1 - (763) 923 - 4320

Billing-Customer
Same as Customer

Vehicle
2025 FOREST RIVER
NIGHTFALL
4X4TNFA24SF002541

Service Advisor
KEVIN GOODIEL
goodielk

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$429.00

Labor Cost: \$62.40

Name	Quantity	Unit Price	Sale Price	Cost Price
08011439 - SEAL,BLACK PER FT	6	\$1.56	\$9.36	\$7.20

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$429.00	\$62.40	\$9.36	\$7.20

B. MISCELLANEOUS	CUSTOMER STATES THE FLOOR IS COMPROMISED DUE TO THE FRESH WATER TANK BULGING. JUST CHECK OVER FLOOR AND CABINETS.	Warranty Pay	\$165.00
-------------------------	--	---------------------	-----------------

Job added by KEVIN GOODIEL on Tue Jun 16, 2026 | 9:45 AM

1. Concern\shallow staples

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$165.00

Labor Cost: \$24.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.9	1	1	\$165.00	\$24.00

1. Moved carpet, rugs and furniture to examine floor. Thoroughly examined floor, saw no damage. Cabinet by fridge had loose panel. Staples were in too deep, not grabbing enough panel material. Removed old staples, pounded in panel with rubber mallet, removed more staples, Refastened panel, covered nail holes with wood putty. Request 1.5 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$165.00	\$24.00	\$0.00	\$0.00

C. MISCELLANEOUS	CUSTOMER STATES THE REAR DOOR SIDE WINDOW DOES NOT CLOSE ALL THE WAY UNLESS YA PUSH IT IN FROM THE OUT SIDE	Warranty Pay	\$0.00
-------------------------	--	---------------------	---------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM
Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM
Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer KRISTIN DECAMP 1246850 +1 - (763) 923 - 4320	Billing-Customer Same as Customer	Vehicle 2025 FOREST RIVER NIGHTFALL 4X4TNFA24SF002541	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Job added by KEVIN GOODIEL on Tue Jun 16, 2026 | 9:45 AM

1. ???

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.11	0	0	\$0.00	\$0.00

1. could not duplicate concern. Took 2 videos of windows opening smoothly without assistance.

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

D. MISCELLANEOUS	CUSTOMER STATES DOOR SIDE FENDER IS CRACKED	Warranty Pay	\$0.00
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Tue Jun 16, 2026 | 9:45 AM

1. Plastic crack

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.08	0	0	\$0.00	\$0.00

1. confirmed fender skirt is cracked. Recommend new fender. Request 1 hour.

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

E. MISCELLANEOUS	CUSTOMER STATES INSTALL NEW LIC PLATE ITS ON THE FLOOR IN THE DOOR	Customer Pay	\$0.00
-------------------------	---	---------------------	---------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM
Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM
Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer KRISTIN DECAMP 1246850 +1 - (763) 923 - 4320	Billing-Customer Same as Customer	Vehicle 2025 FOREST RIVER NIGHTFALL 4X4TNFA24SF002541	Service Advisor KEVIN GOODIEL goodielk
---	---	---	---

Job added by KEVIN GOODIEL on Tue Jun 16, 2026 | 9:45 AM

1. Request

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.21	0	0	\$0.00	\$0.00

1. installed new plate.

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

F. MISCELLANEOUS	CUSTOMER STATES THE ANTENNA IS BROKE ON THE ROOF	Warranty Pay	\$0.00
-------------------------	---	---------------------	---------------

Tags: Add-on

Job added by KEVIN GOODIEL on Tue Jun 16, 2026 | 9:50 AM

1. antenna is broken

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
matthewl	-	0.11	0	0	\$0.00	\$0.00

1. Confirmed antenna is broken. Recommend new antenna. Request 2 hours

Total Labor Sale \$0.00	Total Labor Cost \$0.00	Total Parts Sale \$0.00	Total Parts Cost \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM

Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM

Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer
KRISTIN DECAMP
1246850
+1 - (763) 923 - 4320

Billing-Customer
Same as Customer

Vehicle
2025 FOREST RIVER
NIGHTFALL
4X4TNFA24SF002541

Service Advisor
KEVIN GOODIEL
goodielk

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$0.00	\$0.00

Category	Sale	Cost
Labor	\$594.00	\$86.40
Parts	\$9.36	\$7.20
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
Invoice Total	\$603.36	\$93.60

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
D	MISC	Wed Jun 17, 2026	8:17 AM	8:22 AM	0.08 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
E	MISC	Wed Jun 17, 2026	8:22 AM	8:35 AM	0.21 hrs	CP	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
F	MISC	Wed Jun 17, 2026	8:35 AM	8:41 AM	0.11 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM
Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM
Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer
KRISTIN DECAMP
1246850
+1 - (763) 923 - 4320

Billing-Customer
Same as Customer

Vehicle
2025 FOREST RIVER
NIGHTFALL
4X4TNFA24SF002541

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
B	MISC	Wed Jun 17, 2026	8:41 AM	8:49 AM	0.13 hrs	W	matthewl	1 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Wed Jun 17, 2026	8:50 AM	8:56 AM	0.11 hrs	W	matthewl	0 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Wed Jun 17, 2026	8:57 AM	9:42 AM	0.75 hrs	W	matthewl	2.6 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 17, 2026	9:42 AM	9:59 AM	0.29 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
A	MISC	Wed Jun 17, 2026	9:59 AM	10:13 AM	0.23 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 17, 2026	10:13 AM	10:34 AM	0.34 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
A	MISC	Wed Jun 17, 2026	10:34 AM	10:39 AM	0.08 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 17, 2026	10:39 AM	10:43 AM	0.06 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
B	MISC	Wed Jun 17, 2026	10:45 AM	10:50 AM	0.08 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
\$603.36

RO# : 40975 Tag# : SF002541

Check-in: Tue Jun 16, 2026 | 9:45 AM
Ready for Pickup: Mon Jun 22, 2026 | 10:09 AM
Promise Time: Sun Jun 21, 2026 | 6:00 PM

Customer
KRISTIN DECAMP
1246850
+1 - (763) 923 - 4320

Billing-Customer
Same as Customer

Vehicle
2025 FOREST RIVER
NIGHTFALL
4X4TNFA24SF002541

Service Advisor
KEVIN GOODIEL
goodielk

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Wed Jun 17, 2026	11:17 AM	12:17 PM	0.99 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
A	MISC	Wed Jun 17, 2026	12:51 PM	1:09 PM	0.31 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					
A	MISC	Wed Jun 17, 2026	1:09 PM	1:24 PM	0.24 hrs	W	matthewl	-
Tag: Regular Hour			Reason: -					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40975	LINK RV	\$603.36
57200	40975	LINK RV	-\$594.00
67200	40975	LINK RV	\$86.40
14400	matthewl	LINK RV	-\$86.40
54200	40975	LINK RV	-\$9.36
64000	40975	LINK RV	\$7.20
14000	40975	LINK RV	-\$7.20

