

**Claim Response**

**Claim: C3028170**

**Non-Warranty Goodwill Adjustment**

Last Modified bystutk

Claim	Reference no.	Repair start date	Repair date	VIN	Pre-auth	Dealer	Repairing dealer name	Labor rate	Changed warranty rate	Type	Date Of Purchase
C3028170	66573	2/22/2022	3/7/2022	4YDT29824L3101589		1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	150.00	0.00	SA21-414	6/20/2020

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	692585	Regulator - Kit - Auto Change	1.00	0.00	48.79	15.00	56.11	0.00	0.00	0.00	Approved

**Component Model: 6020**

**Component Serial Number: N 18 23**

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	7141442B	Safety Advisory 21-414 Winn-Tec Complaint: REGULATOR RECALL Cause: FOUND REGULATOR NEEDS TO BE CHANGED Correction: CHANGED LP REGULATOR AND DID LP DROP TEST. (AP KBS)		0.50	0.50	75.00	0.00	1	0.50	Approved

<b>Submitted parts &amp; subLet</b>	<b>56.11</b>	<b>Approved parts &amp; subLet</b>	<b>56.11</b>
<b>Submitted labor &amp; subLet</b>	<b>75.00</b>	<b>Approved labor &amp; subLet</b>	<b>75.00</b>
<b>Submitted freight:</b>	<b>0.00</b>	<b>Approved freight:</b>	<b>0.00</b>
<b>Tax:</b>	<b>0.00</b>	<b>Tax:</b>	<b>0.00</b>
<b>Total Submitted:</b>	<b><u>131.11</u></b>	<b>Total approved:</b>	<b><u>131.11</u></b>