



Pre-Authorization

Pre-Authorization number	PREAUTH108741(PA03999753)	Reference no.79890	Status	Approved
--------------------------	---------------------------	--------------------	--------	----------

Servicing Dealer 1194 Name Basden's American RV Address 600 E Baseline Rd VIN 4YDFCGN22T2506164 Retail sold on 3/31/2026
Evansville, IN 47725

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



Root		Approved Actual				Base		Complaint/Cause/Correction
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	
1204016B	Slide Out Cross Shaft	0	0.2	0.2		1	1	Complaint: OFF DOOR SIDE REAR SLIDE HAS A RUBBING GRINDING NOISE EVERYONCE IN A WHILE See been on noise coming from off door side tire area from the outside Cause: Lubrication Correction: Had BEN run the slideroom out and in 2 times and only once heard the squeak. With the slideroom out sprayed slide lubricant all over the mechanism.
4157106A	A/C - Furrion - Repair	0	1.2	0.5		1	0.5	Complaint: CHECK THE REMOTE WITH THE A/C NOT CHANGING THE TEMP Cause: Plugged in the shore power then got the ac remote to power on the ac but the remote didn't respond to the ac. Manually pushed the power button on the ac to power on. Set the temp on the remote but the ac didn't respond. Set the temp manually then tried ag Correction: CASE 6772498 PART NUMBER 2024049534 REPLACE THE REMOTE KRV-VCB
2302202F	Compartment Door	0	0.3	0.3		1	0.2	Complaint: STORAGE DOOR ON THE DS FRONT IS CROOKEdneeds adjust Cause: Compartment door crooked Correction: Took pictures of the crooked door the cut the silicone and unscrewed the door from the body. Pushed the door towards the back then put the screws back in. Trimmed with silicone. Took pictures of the process.
Pre-Authorization number: PREAUTH108741				1				

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.