

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66659

Completed : 19 MAR 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
Licence # : Invoice # :
Stock No : 10741 Description : 2022 TT COACHMEN FREEDOM EXPRESS 32
Tag : Date In : 03 MAR 22 Mileage : 0
Author : DH Promised : 31 MAR 22
Location : 0321 CHECK STATUS WDate Sched :
Serial# : 5ZT2FEXB8NW021807 Chassis# : 5ZT2FEXB8NW021807
Warr. Date : 07 MAR 22 Cust PO# :
Print Date : 19 MAR 22

Job # Description JOB INFORMATION Type Bill To

FPDI COMPLAINT: Transferred to BAS*66752 on 14 MAR 22 I PDI PRE-D
Estimate amount was 0.00 FINAL PDI ON
NEW TRAVEL TRAILERS
CORRECTION: check tires lights brakes, breakaway,
lug nuts roof, LP system, LP drop test,
install battery, found shade in side
broken, found trim pulled loose, check
furnace water heater, range, refer,
showers, toilet,
SWAP COMPLAINT: Transferred to BAS*66752 on 14 MAR 22 I DO DEALE
Estimate amount was 0.00 SWAP CUSTOMER'S
HITCHWORK
CORRECTION: swap customer hitch works aand adjust
WALK COMPLAINT: Transferred to BAS*66752 on 14 MAR 22 I PDI PRE-D
Estimate amount was 180.00 WALK THRU
CORRECTION: set up camper and clean up water on
floor from rain.DID WALK THRU.CHANGED LP
TANKS AND COVER AND ROD FROM OLD TO NEW.
1 COMPLAINT: Transferred to BAS*66752 on 14 MAR 22 I DO DEALE
Estimate amount was 0.00 INSTALL SHOCKS
ON BED PER GM.
CORRECTION: had to add wood too bed to get top to
stay down install shocks to bed
2 COMPLAINT: WINDOW SHADE IN LIVING ROOM APART W 10024 FORES
CORRECTION: remove valance, remove roller tube
assembly, fill out PO and turn in broken
shade and PO to parts, put valance back
up so do not get lost or damaged
3 COMPLAINT: CORNER MOLDING IN BEDROOM NOT ATTACHED I SPN SALES
CAUSE: bedroom door guid was atatched to corner
trim with short screws that did not go
into wall stud and pulled trim off
CORRECTION: bedroom door guid was atatched to corner
trim with short screws that did not go

Continued on page 2

Work Order : 66659

 Job # Description JOB INFORMATION Type Bill To

into wall stud and pulled trim off,
 remove nails and staples from trim and
 remount corner trim, fill screw holes,
 cut a shim to go behind guide too keep
 door from rubbing trim, and mount guide
 to wall beside trim

10 Transferred to BAS*66752 on 14 MAR 22 Estimate I DO DEALE
 amount was 0.00 EXTENDED DROP BAR FOR CUSTOMER 52286
 THAT WAS PRE BILLED . PER DREW

4 COMPLAINT: Transferred to BAS*66752 on 14 MAR 22 I DO DEALE
 Estimate amount was 0.00 SWAPING OLD LP
 TANKS FROM TRADE

CORRECTION: DID THIS ON WALK THRU TICKET.

 Job # Part No Description PARTS Bill to Qty Price Total

FPDIN	DC-24	ADVANCE GROUP 24 D	I-PDI	0	131.99	0.00
FPDIN	5516	A10-3050FHVP 30M-5	I-PDI	0	23.99	0.00
1	20-1069	BR-1060 2-PK GAS S	I-DO	0	5.99	0.00
1	20-1067	BED STRUT MOUNT	I-DO	0	7.00	0.00
1	560766	G26 GAS SPRING PRO	I-DO	0	17.99	0.00
2	F100117692	SHADE, ROLLER NIGH	W-10024	1	36.66	36.66
10	14-2931	90-02-4300 EQUALIZER ADJ H	I-DO	0	152.99	0.00

 Job# Lab Code Description LABOUR Mech Bill to Hrs Rate Total

DINTT	PDINTT	PDI - NEW TRAVEL TRAIL JP	I-PDI	0.00	150.00	0.00
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL JP	I-PDI	0.00	150.00	0.00
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL JP	I-PDI	0.00	150.00	0.00
SWAP	Z990	MISC LABOUR CODE (EXTE JP	I-DO	0.00	105.00	0.00
WALK	Z990	MISC LABOUR CODE (EXTE DGH	I-PDI	0.00	150.00	0.00
WALK	Z990	MISC LABOUR CODE (EXTE DGH	I-PDI	0.00	150.00	0.00
WALK	Z990	MISC LABOUR CODE (EXTE DGH	I-PDI	0.00	150.00	0.00
1	Z990	MISC LABOUR CODE (EXTE JP	I-DO	0.00	150.00	0.00
2	Z990	MISC LABOUR CODE (EXTE	W-10024	0.00	150.00	0.00
2	Z990	MISC LABOUR CODE (EXTE JP	W-10024	0.20	150.00	30.00
2	Z990	MISC LABOUR CODE (EXTE	W-10024	0.00	150.00	0.00
2	Z990	MISC LABOUR CODE (EXTE RAB	W-10024	0.00	150.00	0.00
3	Z990	MISC LABOUR CODE (EXTE JP	I-SPN	0.20	25.00	5.00
4	Z990	MISC LABOUR CODE (EXTE DGH	I-DO	0.00	150.00	0.00

 Job # Excode Description EXTRAS bill to Qty Price Total

2	FRT	UPS-SHADE	W-10024	1.00	30.40	30.40
---	-----	-----------	---------	------	-------	-------

Continued on page 3

Work Order : 66659

CUSTOMER COMMENTS

CUSTOMER CAME BY AND GOT BLIND
*****BW ATTEMPTED TO CONTACT CUSTOMER BY PHONE ON 03/18. JUST RANG AND NEVER
WENT TO VOICEMAIL. BW EMAILED CUSTOMER TO ADVISE THAT ROLLER SHADE IS
HERE NOW.BH TRIED TO CALL CUSTOMER AND THE PHONE JUST RANG AND RANG 3-14
SHADE IN BACKROOM 3-10-22...CAMCREATED PRE-AUTH (#951737) FOR SHADE, WATING ON APPROVAL. 3-4-22.
MABDEFECTIVE SHADE ON WARRANTY SHELF 3-4-22 AND NEW ONE
ORDERED...CAM*****
BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	SPN	0.00	5.00	0.00	0.00	0.00	5.00
W	10024	36.66	30.00	0.00	30.40	0.00	97.06
	Totals	36.66	35.00	0.00	30.40	0.00	102.06